

Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

Client: David Hare Home: (609) 412-8600

Property: 715 Peach St

Avenel, NJ 07001

Operator: TRISTATE

Estimator: Jason Kluska Business: (215) 850-3372

Company: **Guardian Restoration Business:** 13440 James Street

Philadelphia, PA 19136

Type of Estimate:

Date Entered: 10/7/2021 Date Assigned:

Price List: NJNE8X\_OCT21

Labor Efficiency: Restoration/Service/Remodel

> Estimate: HARE-FIRE




Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

# HARE-FIRE Main Level

#### **Main Level**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1. R&R Ductwork - flexible - insulated - 12" round	LF		1.05	14.80	0.00	0.00	0.00
A supplement will be submitted if the associ	iation does not	replace the in:	sulated ductwo	rk.			
2. Seal floor or ceiling joist system	SF		0.00	1.22	0.00	0.00	0.00
Ceiling framing along with open wall studs	need to be seal	led, if the asso	ciation does no	ot do this a supplen	ient will be sub	mitted.	
Total: Main Level					0.00	0.00	0.00



Bedroom Height: 8'

493.33 SF Walls738.13 SF Walls & Ceiling27.20 SY Flooring64.17 LF Ceil. Perimeter

244.79 SF Ceiling244.79 SF Floor64.17 LF Floor Perimeter

Door 3' X 6' 8"

Door 2' 1" X 6' 8"

Door 2' 6" X 6' 8"

Window 5' X 4'

Opens into HALLWAY
Opens into MASTER\_BATH
Opens into WALKIN\_CLOS
Opens into Exterior

TT III GOTT	• 1	• •		opens me	Enterior		
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3. Contents - move out then reset	1.00 EA		0.00	72.25	5.75	14.46	92.46
4. Detach & Reset Interior door - Colonist - slab only	1.00 EA	24.05	0.00	0.00	1.91	4.82	30.78
5. Remove Carpet - metal transition strip	2.50 LF		1.05	0.00	0.17	0.00	2.80
6. Carpet - metal transition strip	2.50 LF		0.00	3.09	0.61	1.54	9.88
7. Remove Carpet - High grade	244.79 SF		0.38	0.00	6.16	0.00	99.18
8. Remove Carpet pad	244.79 SF		0.16	0.00	2.60	0.00	41.77
9. Carpet - High grade	281.51 SF		0.00	5.14	115.03	289.40	1,851.39
15 % waste added for Carpet - High grade	·.						
10. Carpet pad	244.79 SF		0.00	0.60	11.68	29.38	187.93
11. Remove Window blind - PVC - 1" - 7.1 to 14 SF	2.00 EA		14.04	0.00	1.86	0.00	29.94
12. Window blind - PVC - 1" - 7.1 to 14 SF	2.00 EA		0.00	74.74	11.88	29.90	191.26
ARE-FIRE					10/8	3/2021	Page: 2



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500 Fax: 215-821-2315

## **CONTINUED - Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
13. Recessed light fixture - Detach & reset trim only	4.00 EA		0.00	3.80	1.21	3.04	19.45
14. Detach & Reset Light fixture	1.00 EA	61.00	0.00	0.00	4.85	12.20	78.05
15. Remove 1/2" drywall - hung, taped, floated, ready for paint	244.79 SF		0.58	0.00	9.41	0.00	151.39
16. Remove Batt insulation - 6" - R21 - paper / foil faced	244.79 SF		0.40	0.00	6.49	0.00	104.41
17. Batt insulation - 6" - R21 - paper / foil faced	244.79 SF		0.00	1.63	31.72	79.80	510.53
18. Metal studding - Track - 2 1/2" wide - 25 ga mat. only	244.79 LF		0.00	0.38	7.39	18.60	119.01
19. 1/2" drywall - hung, taped, floated, ready for paint	244.79 SF		0.00	2.53	49.24	123.86	792.42
20. Additional cost for gluing drywall	244.79 SF		0.00	0.30	5.84	14.68	93.96
21. Clean floor or roof joist system	244.79 SF		0.00	1.01	16.38	0.00	263.62
22. Clean light fixture	1.00 EA		0.00	11.16	0.74	0.00	11.90
23. Clean recessed light fixture	4.00 EA		0.00	11.17	2.96	0.00	47.64
24. Clean the walls	493.33 SF		0.00	0.38	12.42	0.00	199.89
25. Clean baseboard	64.17 LF		0.00	0.38	1.62	0.00	26.00
26. Clean door / window opening (per side)	5.00 EA		0.00	13.71	4.54	0.00	73.09
27. Clean window unit (per side) 10 - 20 SF	2.00 EA		0.00	15.88	2.10	0.00	33.86
28. Clean sill - wood	6.00 LF		0.00	0.77	0.31	0.00	4.93
29. Clean door (per side)	3.00 EA		0.00	7.58	1.51	0.00	24.25
30. Clean door hardware	3.00 EA		0.00	7.01	1.39	0.00	22.42
31. Clean floor	244.79 SF		0.00	0.44	7.14	0.00	114.85
32. Seal underlayment for odor control	244.79 SF		0.00	0.58	9.41	0.00	151.39
33. Deodorize building - Hot thermal fog	1,958.33 CF		0.00	0.07	9.08	0.00	146.16
34. Mask the floor per square foot - plastic and tape - 4 mil	244.79 SF		0.00	0.24	4.67	11.76	75.18
35. Seal/prime then paint the walls and ceiling twice (3 coats)	738.13 SF		0.00	1.32	77.46	194.86	1,246.65
36. Seal & paint door or window opening (per side)	5.00 EA		0.00	31.65	12.58	31.66	202.49
37. Seal & paint window sill	6.00 LF		0.00	2.57	1.22	3.08	19.72
38. Seal & paint door slab only (per side)	3.00 EA		0.00	38.41	9.16	23.04	147.43
39. Seal & paint baseboard - two coats	64.17 LF		0.00	1.50	7.66	19.26	123.18
IARE-FIRE					10/8	3/2021	Page: 3




Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

#### **CONTINUED - Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
40. Final cleaning - construction - Residential	244.79 SF		0.00	0.27	5.26	13.22	84.57
Totals: Bedroom					461.41	918.56	7,425.83



Door

Walk-in Closet Height: 8'

160.00 SF Walls185.00 SF Walls & Ceiling2.78 SY Flooring20.00 LF Ceil. Perimeter

2' 6" X 6' 8"

25.00 SF Ceiling25.00 SF Floor20.00 LF Floor Perimeter

**Opens into BEDROOM** 

DESCRIPTION REMOVE REPLACE O&P **TOTAL** QTY RESET TAX 1.00 EA 54.24 41. Contents - move out then reset -0.00 4.31 10.84 69.39 Small room 42. Detach & Reset Interior door -1.00 EA 24.05 0.00 0.00 1.91 4.82 30.78 Colonist - slab only 43. Closet shelf and rod package -10.00 LF 0.00 11.73 9.32 23.46 150.08 Detach & reset 44. Clean closet shelf and rod per 10.00 LF 0.00 1.13 0.75 0.00 12.05 lineal foot 45. Remove Carpet - High grade 25.00 SF 0.38 0.00 0.63 0.00 10.13 46. Remove Carpet pad 25.00 SF 0.16 0.00 0.27 0.00 4.27 47. Carpet - High grade 28.75 SF 0.00 5.14 11.75 29.56 189.09 15 % waste added for Carpet - High grade. 48. Carpet pad 25.00 SF 0.00 0.60 1.19 3.00 19.19 49. Detach & Reset Light fixture 1.00 EA 61.00 0.00 0.00 4.85 12.20 78.05 50. Remove Baseboard - 3 1/4" 20.00 LF 0.63 0.00 0.83 0.00 13.43 51. Baseboard - 3 1/4" 20.00 LF 0.00 3.72 5.92 14.88 95.20 52. Remove 1/2" drywall - hung, 185.00 SF 0.58 0.00 7.11 0.00 114.41 taped, floated, ready for paint 53. Remove Batt insulation - 6" - R21 -0.00 0.00 25.00 SF 0.40 0.66 10.66 paper / foil faced 54. Batt insulation - 6" - R21 - paper / 25.00 SF 0.00 1.63 3.24 8.16 52.15 foil faced 55. Remove Batt insulation - 4" - R15 -80.00 SF 0.34 0.00 1.80 0.00 29.00 paper / foil faced



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500 Fax: 215-821-2315


#### **CONTINUED - Walk-in Closet**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
56. Batt insulation - 4" - R15 - paper / foil faced	80.00 SF		0.00	1.40	8.90	22.40	143.30
57. Metal studding - Track - 2 1/2" wide - 25 ga mat. only	25.00 LF		0.00	0.38	0.76	1.90	12.16
58. 1/2" drywall - hung, taped, floated, ready for paint	185.00 SF		0.00	2.53	37.21	93.62	598.88
59. Additional cost for gluing drywall	185.00 SF		0.00	0.30	4.42	11.10	71.02
60. Clean floor or roof joist system	25.00 SF		0.00	1.01	1.67	0.00	26.92
61. Clean light fixture	1.00 EA		0.00	11.16	0.74	0.00	11.90
62. Clean stud wall	160.00 SF		0.00	0.81	8.59	0.00	138.19
63. Clean door / window opening (per side)	5.00 EA		0.00	13.71	4.54	0.00	73.09
64. Clean door (per side)	3.00 EA		0.00	7.58	1.51	0.00	24.25
65. Clean door hardware	3.00 EA		0.00	7.01	1.39	0.00	22.42
66. Clean floor	25.00 SF		0.00	0.44	0.73	0.00	11.73
67. Seal underlayment for odor control	25.00 SF		0.00	0.58	0.96	0.00	15.46
68. Deodorize building - Hot thermal fog	200.00 CF		0.00	0.07	0.93	0.00	14.93
69. Mask the floor per square foot - plastic and tape - 4 mil	25.00 SF		0.00	0.24	0.48	1.20	7.68
70. Seal/prime then paint the walls and ceiling twice (3 coats)	185.00 SF		0.00	1.32	19.42	48.84	312.46
71. Seal & paint door or window opening (per side)	5.00 EA		0.00	31.65	12.58	31.66	202.49
72. Seal & paint door slab only (per side)	3.00 EA		0.00	38.41	9.16	23.04	147.43
73. Seal & paint baseboard - two coats	20.00 LF		0.00	1.50	2.39	6.00	38.39
74. Seal & paint closet shelving	10.00 LF		0.00	9.06	7.20	18.12	115.92
75. Final cleaning - construction - Residential	25.00 SF		0.00	0.27	0.54	1.36	8.65
Totals: Walk-in Closet					178.66	366.16	2,875.15



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315



Master Bath Height: 8'

194.67 SF Walls230.50 SF Walls & Ceiling3.98 SY Flooring24.33 LF Ceil. Perimeter

35.83 SF Ceiling 35.83 SF Floor

24.33 LF Floor Perimeter

Door 2' 1" X 6' 8" Opens into BEDROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
76. Detach & Reset Interior door - Colonist - slab only	1.00 EA	24.05	0.00	0.00	1.91	4.82	30.78
77. Remove Toilet	1.00 EA		34.87	0.00	2.31	0.00	37.18
78. Clean toilet	1.00 EA		0.00	23.00	1.52	0.00	24.52
79. Install Toilet	1.00 EA		0.00	278.37	18.44	0.00	296.81
80. Remove Vanity with granite or marble top	2.00 LF		13.07	0.00	1.73	0.00	27.87
81. Vanity with granite or marble top	2.00 LF		0.00	445.33	70.81	178.14	1,139.61
82. R&R P-trap assembly - ABS (plastic)	1.00 EA		10.46	79.64	7.17	18.02	115.29
83. Remove Sink faucet - Bathroom	1.00 EA		26.15	0.00	1.73	0.00	27.88
84. Clean sink faucet	1.00 EA		0.00	10.18	0.67	0.00	10.85
85. Install Sink faucet - Bathroom	1.00 EA		0.00	104.40	8.30	20.88	133.58
86. Remove Medicine cabinet	1.00 EA		25.12	0.00	1.66	0.00	26.78
87. Medicine cabinet	1.00 EA		0.00	194.89	15.49	38.98	249.36
88. Remove Light bar - 3 lights	1.00 EA		27.89	0.00	1.85	0.00	29.74
89. Light bar - 3 lights	1.00 EA		0.00	85.82	6.83	17.16	109.81
90. Remove Shower door	1.00 EA		25.58	0.00	1.69	0.00	27.27
91. Clean shower door	1.00 EA		0.00	18.76	1.49	3.76	24.01
92. Install Shower door	1.00 EA		0.00	115.07	9.14	23.02	147.23
93. Tub/shower faucet - Detach & reset	1.00 EA		0.00	278.37	22.13	55.68	356.18
94. R&R Shower head only	1.00 EA		10.46	68.47	6.28	15.80	101.01
95. Remove Ceramic/porcelain tile - High grade	85.33 SF		2.51	0.00	14.19	0.00	228.37
96. Ceramic/porcelain tile - High grade	85.33 SF		0.00	15.03	101.96	256.50	1,640.97
97. Shower pan - Large	1.00 EA		0.00	272.01	21.62	54.40	348.03
98. Tile - metal trim - aluminum - up to 9/16	4.00 LF		0.00	4.14	1.32	3.32	21.20



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500 Fax: 215-821-2315

## **CONTINUED - Master Bath**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
99. R&R Bathroom ventilation fan	1.00 EA		24.57	116.34	11.21	28.18	180.30
100. Remove Bath accessory	3.00 EA		6.98	0.00	1.39	0.00	22.33
101. Bath accessory	3.00 EA		0.00	30.96	7.38	18.58	118.84
102. Remove Baseboard - 5 1/4"	16.00 LF		0.71	0.00	0.75	0.00	12.11
103. Baseboard - 5 1/4"	16.00 LF		0.00	4.65	5.92	14.88	95.20
104. Remove Casing - 3 1/4"	16.00 LF		0.71	0.00	0.75	0.00	12.11
105. Casing - 3 1/4"	16.00 LF		0.00	3.32	4.22	10.62	67.96
106. Remove 1/2" drywall - hung, taped, floated, ready for paint	230.50 SF		0.58	0.00	8.86	0.00	142.55
107. Remove Batt insulation - 6" - R21 - paper / foil faced	35.83 SF		0.40	0.00	0.95	0.00	15.28
108. Batt insulation - 6" - R21 - paper / foil faced	35.83 SF		0.00	1.63	4.64	11.68	74.72
109. Remove Batt insulation - 4" - R15 - paper / foil faced	97.33 SF		0.34	0.00	2.19	0.00	35.28
110. Batt insulation - 4" - R15 - paper / foil faced	97.33 SF		0.00	1.40	10.84	27.26	174.36
111. Metal studding - Track - 2 1/2" wide - 25 ga mat. only	35.83 LF		0.00	0.38	1.08	2.72	17.42
112. 1/2" drywall - hung, taped, floated, ready for paint	230.50 SF		0.00	2.53	46.37	116.64	746.18
113. Additional cost for gluing drywall	230.50 SF		0.00	0.30	5.50	13.84	88.49
114. Clean floor or roof joist system	35.83 SF		0.00	1.01	2.40	0.00	38.59
115. Clean stud wall	194.67 SF		0.00	0.81	10.45	0.00	168.13
116. Clean door / window opening (per side)	1.00 EA		0.00	13.71	0.91	0.00	14.62
117. Clean door (per side)	1.00 EA		0.00	7.58	0.50	0.00	8.08
118. Clean door hardware	1.00 EA		0.00	7.01	0.46	0.00	7.47
119. Clean floor	35.83 SF		0.00	0.44	1.04	0.00	16.81
120. Seal underlayment for odor control	35.83 SF		0.00	0.58	1.38	0.00	22.16
121. Deodorize building - Hot thermal fog	286.67 CF		0.00	0.07	1.33	0.00	21.40
122. Remove Ceramic/porcelain tile	35.83 SF		2.51	0.00	5.96	0.00	95.89
123. Ceramic/porcelain tile	35.83 SF		0.00	13.54	38.57	97.02	620.73
124. Remove Threshold - cultured marble	2.50 LF		4.55	0.00	0.75	0.00	12.13
125. Threshold - cultured marble	2.50 LF		0.00	38.92	7.74	19.46	124.50
126. Seal grout on tile wall	85.33 SF		0.00	1.61	10.92	27.48	175.78
ARE-FIRE					10/8	3/2021	Page:




Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

#### **CONTINUED - Master Bath**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
127. Tile/stone sealer	35.83 SF		0.00	1.02	2.90	7.32	46.77
128. Mask the floor per square foot - plastic and tape - 4 mil	35.83 SF		0.00	0.24	0.68	1.72	11.00
129. Seal/prime then paint the walls and ceiling twice (3 coats)	230.50 SF		0.00	1.32	24.19	60.86	389.31
130. Seal & paint door or window opening (per side)	1.00 EA		0.00	31.65	2.52	6.34	40.51
131. Seal & paint door slab only (per side)	1.00 EA		0.00	38.41	3.05	7.68	49.14
132. Seal & paint baseboard - two coats	24.33 LF		0.00	1.50	2.90	7.30	46.70
133. Final cleaning - construction - Residential	35.83 SF		0.00	0.27	0.77	1.94	12.38
Totals: Master Bath					551.71	1,172.00	8,879.56



Hallway Height: 8'

229.33 SF Walls278.00 SF Walls & Ceiling5.41 SY Flooring28.67 LF Ceil. Perimeter

48.67 SF Ceiling 48.67 SF Floor

28.67 LF Floor Perimeter

Missing Wall

Door

1' 8" X 6' 8"

Door

2' 6" X 6' 8"

Door

3' X 6' 8"

Door

2' 6" X 6' 8"

Opens into LIVING\_ROOM
Opens into LINEN\_CLOSET
Opens into HALL\_BATHROO
Opens into BEDROOM
Opens into OFFICE

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
134. Remove Baseboard - 3 1/4"	28.67 LF		0.63	0.00	1.20	0.00	19.26
135. Baseboard - 3 1/4"	28.67 LF		0.00	3.72	8.48	21.34	136.47
136. Remove Casing - 3 1/4"	64.00 LF		0.71	0.00	3.01	0.00	48.45
137. Casing - 3 1/4"	64.00 LF		0.00	3.32	16.90	42.50	271.88
138. Detach & Reset Light fixture	1.00 EA	61.00	0.00	0.00	4.85	12.20	78.05
139. Clean light fixture	1.00 EA		0.00	11.16	0.74	0.00	11.90
140. Remove 1/2" drywall - hung,	163.33 SF		0.58	0.00	6.28	0.00	101.01



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500 Fax: 215-821-2315

# **CONTINUED - Hallway**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
141. Remove Batt insulation - 6" - R21 - paper / foil faced	48.67 SF		0.40	0.00	1.29	0.00	20.76
142. Batt insulation - 6" - R21 - paper / foil faced	48.67 SF		0.00	1.63	6.31	15.86	101.50
143. Metal studding - Track - 2 1/2" wide - 25 ga mat. only	48.67 LF		0.00	0.38	1.46	3.70	23.65
144. 1/2" drywall - hung, taped, floated, ready for paint	163.33 SF		0.00	2.53	32.86	82.64	528.72
145. Additional cost for gluing drywall	163.33 SF		0.00	0.30	3.90	9.80	62.70
146. Remove Vinyl plank flooring - High grade	48.67 SF		1.64	0.00	5.29	0.00	85.11
147. Remove Vapor barrier - visqueen - 6mil	48.67 SF		0.11	0.00	0.35	0.00	5.70
148. Vinyl plank flooring - High grade	48.67 SF		0.00	6.71	25.97	65.32	417.87
149. Vapor barrier - visqueen - 6mil	48.67 SF		0.00	0.32	1.24	3.12	19.93
150. Clean floor or roof joist system	48.67 SF		0.00	1.01	3.26	0.00	52.42
151. Clean stud wall	114.67 SF		0.00	0.81	6.15	0.00	99.03
152. Clean door / window opening (per side)	4.00 EA		0.00	13.71	3.63	0.00	58.47
153. Clean door (per side)	4.00 EA		0.00	7.58	2.01	0.00	32.33
154. Clean door hardware	4.00 EA		0.00	7.01	1.86	0.00	29.90
155. Clean floor	48.67 SF		0.00	0.44	1.42	0.00	22.83
156. Seal underlayment for odor control	48.67 SF		0.00	0.58	1.87	0.00	30.10
157. Deodorize building - Hot thermal fog	389.33 CF		0.00	0.07	1.81	0.00	29.06
158. Mask the floor per square foot - plastic and tape - 4 mil	48.67 SF		0.00	0.24	0.92	2.34	14.94
159. Seal/prime then paint the walls and ceiling twice (3 coats)	278.00 SF		0.00	1.32	29.17	73.40	469.53
160. Seal & paint door or window opening (per side)	4.00 EA		0.00	31.65	10.07	25.32	161.99
161. Seal & paint door slab only (per side)	4.00 EA		0.00	38.41	12.22	30.72	196.58
162. Seal & paint baseboard - two coats	28.67 LF		0.00	1.50	3.42	8.60	55.03
163. Final cleaning - construction - Residential	48.67 SF		0.00	0.27	1.04	2.62	16.80
Totals: Hallway					198.98	399.48	3,201.97



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

Hall Bathroom Height: 8'



226.67 SF Walls272.50 SF Walls & Ceiling5.09 SY Flooring28.33 LF Ceil. Perimeter

45.83 SF Ceiling 45.83 SF Floor

28.33 LF Floor Perimeter

Door 2' 6" X 6' 8" Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
164. Detach & Reset Interior door - Colonist - slab only	1.00 EA	24.05	0.00	0.00	1.91	4.82	30.78
165. Remove Toilet	1.00 EA		34.87	0.00	2.31	0.00	37.18
166. Clean toilet	1.00 EA		0.00	23.00	1.82	4.60	29.42
167. Install Toilet	1.00 EA		0.00	278.37	18.44	0.00	296.81
168. Remove Vanity with granite or marble top	2.50 LF		13.07	0.00	2.17	0.00	34.85
169. Vanity with granite or marble top	2.50 LF		0.00	445.33	88.51	222.66	1,424.50
170. R&R P-trap assembly - ABS (plastic)	1.00 EA		10.46	79.64	7.17	18.02	115.29
171. Remove Sink faucet - Bathroom	1.00 EA		26.15	0.00	1.73	0.00	27.88
172. Clean sink faucet	1.00 EA		0.00	10.18	0.80	2.04	13.02
173. Install Sink faucet - Bathroom	1.00 EA		0.00	104.40	8.30	20.88	133.58
174. Remove Medicine cabinet	1.00 EA		25.12	0.00	1.66	0.00	26.78
175. Medicine cabinet	1.00 EA		0.00	194.89	15.49	38.98	249.36
176. Remove Light bar - 3 lights	1.00 EA		27.89	0.00	1.85	0.00	29.74
177. Light bar - 3 lights	1.00 EA		0.00	85.82	6.83	17.16	109.81
178. Remove Shower door	1.00 EA		25.58	0.00	1.69	0.00	27.27
179. Clean shower door	1.00 EA		0.00	18.76	1.24	0.00	20.00
180. Install Shower door	1.00 EA		0.00	115.07	9.14	23.02	147.23
181. Tub/shower faucet - Detach & reset	1.00 EA		0.00	278.37	22.13	55.68	356.18
182. R&R Shower head only	1.00 EA		10.46	68.47	6.28	15.80	101.01
183. Remove Ceramic/porcelain tile - High grade	64.00 SF		2.51	0.00	10.64	0.00	171.28
184. Ceramic/porcelain tile - High grade	64.00 SF		0.00	15.03	76.48	192.38	1,230.78
185. Remove Bathtub	1.00 EA		104.60	0.00	6.93	0.00	111.53
186. Clean tub	1.00 EA		0.00	22.25	1.76	4.46	28.47



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

#### **CONTINUED - Hall Bathroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
187. Install Bathtub	1.00 EA		0.00	599.65	47.68	119.94	767.27
188. Tile - metal trim - aluminum - up to 9/16	16.00 LF		0.00	4.14	5.27	13.24	84.75
189. R&R Bathroom ventilation fan	1.00 EA		24.57	116.34	11.21	28.18	180.30
190. Remove Bath accessory	3.00 EA		6.98	0.00	1.39	0.00	22.33
191. Bath accessory	3.00 EA		0.00	30.96	7.38	18.58	118.84
192. Remove Baseboard - 5 1/4"	16.00 LF		0.71	0.00	0.75	0.00	12.11
193. Baseboard - 5 1/4"	16.00 LF		0.00	4.65	5.92	14.88	95.20
194. Remove Casing - 3 1/4"	16.00 LF		0.71	0.00	0.75	0.00	12.11
195. Casing - 3 1/4"	16.00 LF		0.00	3.32	4.22	10.62	67.96
196. Remove 1/2" drywall - hung, taped, floated, ready for paint	272.50 SF		0.58	0.00	10.47	0.00	168.52
197. Remove Batt insulation - 6" - R21 - paper / foil faced	45.83 SF		0.40	0.00	1.21	0.00	19.54
198. Batt insulation - 6" - R21 - paper / foil faced	45.83 SF		0.00	1.63	5.94	14.94	95.58
199. Remove Batt insulation - 4" - R15 - paper / foil faced	113.33 SF		0.34	0.00	2.55	0.00	41.08
200. Batt insulation - 4" - R15 - paper / foil faced	113.33 SF		0.00	1.40	12.61	31.74	203.01
201. Metal studding - Track - 2 1/2" wide - 25 ga mat. only	45.83 LF		0.00	0.38	1.38	3.48	22.28
202. 1/2" drywall - hung, taped, floated, ready for paint	272.50 SF		0.00	2.53	54.80	137.88	882.11
203. Additional cost for gluing drywall	272.50 SF		0.00	0.30	6.50	16.36	104.61
204. Clean floor or roof joist system	45.83 SF		0.00	1.01	3.07	0.00	49.36
205. Clean stud wall	226.67 SF		0.00	0.81	12.16	0.00	195.76
206. Clean door / window opening (per side)	1.00 EA		0.00	13.71	0.91	0.00	14.62
207. Clean door (per side)	1.00 EA		0.00	7.58	0.50	0.00	8.08
208. Clean door hardware	1.00 EA		0.00	7.01	0.46	0.00	7.47
209. Clean floor	45.83 SF		0.00	0.44	1.34	0.00	21.51
210. Seal underlayment for odor control	45.83 SF		0.00	0.58	1.76	0.00	28.34
211. Deodorize building - Hot thermal fog	366.67 CF		0.00	0.07	1.70	0.00	27.37
212. Remove Ceramic/porcelain tile	45.83 SF		2.51	0.00	7.62	0.00	122.65
213. Ceramic/porcelain tile	45.83 SF		0.00	13.54	49.33	124.10	793.97




Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

#### **CONTINUED - Hall Bathroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
214. Remove Threshold - cultured marble	2.50 LF		4.55	0.00	0.75	0.00	12.13
215. Threshold - cultured marble	2.50 LF		0.00	38.92	7.74	19.46	124.50
216. Seal grout on tile wall	64.00 SF		0.00	1.61	8.20	20.60	131.84
217. Tile/stone sealer	45.83 SF		0.00	1.02	3.72	9.36	59.83
218. Mask the floor per square foot - plastic and tape - 4 mil	45.83 SF		0.00	0.24	0.88	2.20	14.08
219. Seal/prime then paint the walls and ceiling twice (3 coats)	272.50 SF		0.00	1.32	28.60	71.94	460.24
220. Seal & paint door or window opening (per side)	1.00 EA		0.00	31.65	2.52	6.34	40.51
221. Seal & paint door slab only (per side)	1.00 EA		0.00	38.41	3.05	7.68	49.14
222. Seal & paint baseboard - two coats	28.33 LF		0.00	1.50	3.38	8.50	54.38
223. Final cleaning - construction - Residential	45.83 SF		0.00	0.27	0.98	2.48	15.83
Totals: Hall Bathroom					613.98	1,303.00	9,881.96



Linen Closet

70.67 SF Walls75.46 SF Walls & Ceiling

0.53 SY Flooring

8.83 LF Ceil. Perimeter

Height: 8'

4.79 SF Ceiling4.79 SF Floor

8.83 LF Floor Perimeter

Door 1' 8" X 6' 8" Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
224. Detach & Reset Interior door - Colonist - slab only	1.00 EA	24.05	0.00	0.00	1.91	4.82	30.78
225. Remove Shelving - 12" - in place	10.00 LF		0.53	0.00	0.35	0.00	5.65
226. Clean shelving - wood	10.00 LF		0.00	0.96	0.77	1.92	12.29
227. Install Shelving - 12" - in place	10.00 LF		0.00	6.75	5.36	13.50	86.36
228. Remove Baseboard - 3 1/4"	8.83 LF		0.63	0.00	0.37	0.00	5.93
229. Baseboard - 3 1/4"	8.83 LF		0.00	3.72	2.62	6.58	42.05
230. Remove 1/2" drywall - hung, taped, floated, ready for paint	75.46 SF		0.58	0.00	2.90	0.00	46.67



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

#### **CONTINUED - Linen Closet**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
231. Remove Batt insulation - 6" - R21 - paper / foil faced	4.79 SF		0.40	0.00	0.13	0.00	2.05
232. Batt insulation - 6" - R21 - paper / foil faced	4.79 SF		0.00	1.63	0.62	1.56	9.99
233. Metal studding - Track - 2 1/2" wide - 25 ga mat. only	4.79 LF		0.00	0.38	0.14	0.36	2.32
234. 1/2" drywall - hung, taped, floated, ready for paint	75.46 SF		0.00	2.53	15.18	38.18	244.27
235. Additional cost for gluing drywall	75.46 SF		0.00	0.30	1.80	4.52	28.96
236. Remove Vinyl plank flooring - High grade	4.79 SF		1.64	0.00	0.52	0.00	8.38
237. Remove Vapor barrier - visqueen - 6mil	4.79 SF		0.11	0.00	0.04	0.00	0.57
238. Vinyl plank flooring - High grade	4.79 SF		0.00	6.71	2.56	6.42	41.12
239. Vapor barrier - visqueen - 6mil	4.79 SF		0.00	0.32	0.12	0.30	1.95
240. Clean floor or roof joist system	4.79 SF		0.00	1.01	0.32	0.00	5.16
241. Clean stud wall	70.67 SF		0.00	0.81	3.79	0.00	61.03
242. Clean door / window opening (per side)	1.00 EA		0.00	13.71	0.91	0.00	14.62
243. Clean door (per side)	1.00 EA		0.00	7.58	0.50	0.00	8.08
244. Clean door hardware	1.00 EA		0.00	7.01	0.46	0.00	7.47
245. Clean floor	4.79 SF		0.00	0.44	0.14	0.00	2.25
246. Seal underlayment for odor control	4.79 SF		0.00	0.58	0.18	0.00	2.96
247. Deodorize building - Hot thermal fog	38.33 CF		0.00	0.07	0.18	0.00	2.86
248. Mask the floor per square foot - plastic and tape - 4 mil	4.79 SF		0.00	0.24	0.10	0.24	1.49
249. Seal/prime then paint the walls and ceiling twice (3 coats)	75.46 SF		0.00	1.32	7.92	19.92	127.45
250. Seal & paint door or window opening (per side)	1.00 EA		0.00	31.65	2.52	6.34	40.51
251. Seal & paint door slab only (per side)	1.00 EA		0.00	38.41	3.05	7.68	49.14
252. Seal & paint baseboard - two coats	8.83 LF		0.00	1.50	1.06	2.66	16.97
253. Seal & paint closet shelving	10.00 LF		0.00	9.06	7.20	18.12	115.92
254. Final cleaning - construction - Residential	4.79 SF		0.00	0.27	0.11	0.26	1.66
Totals: Linen Closet					63.83	133.38	1,026.91



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

Coat Closet Height: 8'



84.00 SF Walls 90.88 SF Walls & Ceiling 0.76 SY Flooring 10.50 LF Ceil. Perimeter 6.88 SF Ceiling6.88 SF Floor10.50 LF Floor Perimeter

Door 1' 9" X 6' 8" Opens into LIVING\_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
255. Detach & Reset Interior door - Colonist - slab only	1.00 EA	24.05	0.00	0.00	1.91	4.82	30.78
256. Remove Closet shelf and rod package	2.75 LF		5.24	0.00	0.95	0.00	15.36
257. Clean closet shelf and rod per lineal foot	2.75 LF		0.00	1.13	0.21	0.00	3.32
258. Install Closet shelf and rod package	2.75 LF		0.00	18.03	3.94	9.92	63.44
259. Remove Baseboard - 3 1/4"	10.50 LF		0.63	0.00	0.44	0.00	7.06
260. Baseboard - 3 1/4"	10.50 LF		0.00	3.72	3.11	7.82	49.99
261. Remove 1/2" drywall - hung, taped, floated, ready for paint	90.88 SF		0.58	0.00	3.49	0.00	56.20
262. Remove Batt insulation - 6" - R21 - paper / foil faced	6.88 SF		0.40	0.00	0.18	0.00	2.93
263. Batt insulation - 6" - R21 - paper / foil faced	6.88 SF		0.00	1.63	0.89	2.24	14.34
264. Metal studding - Track - 2 1/2" wide - 25 ga mat. only	6.88 LF		0.00	0.38	0.20	0.52	3.33
265. 1/2" drywall - hung, taped, floated, ready for paint	90.88 SF		0.00	2.53	18.28	45.98	294.19
266. Additional cost for gluing drywall	90.88 SF		0.00	0.30	2.17	5.46	34.89
267. Remove Vinyl plank flooring - High grade	6.88 SF		1.64	0.00	0.75	0.00	12.03
268. Remove Vapor barrier - visqueen - 6mil	6.88 SF		0.11	0.00	0.05	0.00	0.81
269. Vinyl plank flooring - High grade	6.88 SF		0.00	6.71	3.67	9.24	59.07
270. Vapor barrier - visqueen - 6mil	6.88 SF		0.00	0.32	0.18	0.44	2.82
271. Clean floor or roof joist system	6.88 SF		0.00	1.01	0.46	0.00	7.41
272. Clean stud wall	84.00 SF		0.00	0.81	4.51	0.00	72.55
273. Clean door / window opening (per side)	1.00 EA		0.00	13.71	0.91	0.00	14.62
274. Clean door (per side)	1.00 EA		0.00	7.58	0.50	0.00	8.08
275. Clean door hardware	1.00 EA		0.00	7.01	0.46	0.00	7.47
ARE-FIRE					10/8	/2021	Page: 14




Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

#### **CONTINUED - Coat Closet**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
276. Clean floor	6.88 SF		0.00	0.44	0.20	0.00	3.23
277. Seal underlayment for odor control	6.88 SF		0.00	0.58	0.26	0.00	4.25
278. Deodorize building - Hot thermal fog	55.00 CF		0.00	0.07	0.26	0.00	4.11
279. Mask the floor per square foot - plastic and tape - 4 mil	6.88 SF		0.00	0.24	0.13	0.34	2.12
280. Seal/prime then paint the walls and ceiling twice (3 coats)	90.88 SF		0.00	1.32	9.54	24.00	153.50
281. Seal & paint door or window opening (per side)	1.00 EA		0.00	31.65	2.52	6.34	40.51
282. Seal & paint door slab only (per side)	1.00 EA		0.00	38.41	3.05	7.68	49.14
283. Seal & paint baseboard - two coats	10.50 LF		0.00	1.50	1.25	3.16	20.16
284. Seal & paint closet shelving	2.75 LF		0.00	9.06	1.98	4.98	31.88
285. Final cleaning - construction - Residential	6.88 SF		0.00	0.27	0.14	0.38	2.38
Totals: Coat Closet					66.59	133.32	1,071.97



Office Height: 8'

382.67 SF Walls 541.11 SF Walls & Ceiling 17.60 SY Flooring 54.50 LF Ceil. Perimeter 158.44 SF Ceiling158.44 SF Floor49.50 LF Floor Perimeter

Door5' X 6' 8"Opens into OFFICE\_CLOSEWindow5' X 4'Opens into ExteriorDoor2' 6" X 6' 8"Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
286. Contents - move out then reset	1.00 EA		0.00	72.25	5.75	14.46	92.46
287. Detach & Reset Interior door - Colonist - slab only	1.00 EA	24.05	0.00	0.00	1.91	4.82	30.78
288. Remove Carpet - metal transition strip	2.50 LF		1.05	0.00	0.17	0.00	2.80
289. Carpet - metal transition strip	2.50 LF		0.00	3.09	0.61	1.54	9.88
290. Remove Carpet - High grade	158.44 SF		0.38	0.00	3.99	0.00	64.20



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

## **CONTINUED - Office**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
291. Remove Carpet pad	158.44 SF		0.16	0.00	1.68	0.00	27.03
292. Carpet - High grade	182.21 SF		0.00	5.14	74.46	187.32	1,198.34
15 % waste added for Carpet - High grad	le.						
293. Carpet pad	158.44 SF		0.00	0.60	7.56	19.02	121.64
294. Remove Window blind - PVC - 1" - 7.1 to 14 SF	2.00 EA		14.04	0.00	1.86	0.00	29.94
295. Window blind - PVC - 1" - 7.1 to 14 SF	2.00 EA		0.00	74.74	11.88	29.90	191.26
296. Recessed light fixture - Detach & reset trim only	4.00 EA		0.00	3.80	1.21	3.04	19.45
297. Remove 1/2" drywall - hung, taped, floated, ready for paint	158.44 SF		0.58	0.00	6.09	0.00	97.99
298. Remove Batt insulation - $6^{\prime\prime}$ - $R21$ - paper / foil faced	158.44 SF		0.40	0.00	4.20	0.00	67.58
299. Batt insulation - 6" - R21 - paper / foil faced $$	158.44 SF		0.00	1.63	20.53	51.66	330.45
300. Metal studding - Track - 2 1/2" wide - 25 ga mat. only	158.44 LF		0.00	0.38	4.79	12.04	77.04
301. 1/2" drywall - hung, taped, floated, ready for paint	158.44 SF		0.00	2.53	31.87	80.18	512.90
$302. \ \ Additional\ cost\ for\ gluing\ drywall$	158.44 SF		0.00	0.30	3.78	9.50	60.81
303. Clean floor or roof joist system	158.44 SF		0.00	1.01	10.60	0.00	170.62
304. Clean recessed light fixture	4.00 EA		0.00	11.17	2.96	0.00	47.64
305. Clean the walls	382.67 SF		0.00	0.38	9.63	0.00	155.04
306. Clean baseboard	49.50 LF		0.00	0.38	1.25	0.00	20.06
307. Clean door / window opening (per side)	4.00 EA		0.00	13.71	3.63	0.00	58.47
308. Clean window unit (per side) 10 - 20 SF	2.00 EA		0.00	15.88	2.10	0.00	33.86
309. Clean sill - wood	6.00 LF		0.00	0.77	0.31	0.00	4.93
310. Clean door (per side)	3.00 EA		0.00	7.58	1.51	0.00	24.25
311. Clean door hardware	3.00 EA		0.00	7.01	1.39	0.00	22.42
312. Clean floor	158.44 SF		0.00	0.44	4.62	0.00	74.33
313. Seal underlayment for odor control	158.44 SF		0.00	0.58	6.09	0.00	97.99
314. Deodorize building - Hot thermal fog	1,267.52 CF		0.00	0.07	5.88	0.00	94.61
315. Mask the floor per square foot - plastic and tape - 4 mil	158.44 SF		0.00	0.24	3.02	7.60	48.65




Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

#### **CONTINUED - Office**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
316. Seal/prime then paint the walls and ceiling twice (3 coats)	541.11 SF		0.00	1.32	56.78	142.86	913.91
317. Seal & paint door or window opening (per side)	4.00 EA		0.00	31.65	10.07	25.32	161.99
318. Seal & paint window sill	6.00 LF		0.00	2.57	1.22	3.08	19.72
319. Seal & paint door slab only (per side)	3.00 EA		0.00	38.41	9.16	23.04	147.43
320. Seal & paint baseboard - two coats	49.50 LF		0.00	1.50	5.90	14.86	95.01
321. Final cleaning - construction - Residential	158.44 SF		0.00	0.27	3.40	8.56	54.74
Totals: Office					321.86	638.80	5,180.22



140.03 SF Walls

160.86 SF Walls & Ceiling

2.32 SY Flooring21.67 LF Ceil. Perimeter

Height: 8'
20.84 SF Ceiling

20.84 SF Floor

16.67 LF Floor Perimeter

Door	5' X 6' 8"	Opens into OFFICE

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
322. Bypass (sliding) door set - slabs only - Detach & reset	1.00 EA		0.00	33.94	2.70	6.78	43.42
323. Closet shelf and rod package - Detach & reset	8.33 LF		0.00	11.73	7.76	19.54	125.01
324. Clean closet shelf and rod per lineal foot	8.33 LF		0.00	1.13	0.62	0.00	10.03
325. Remove Carpet - High grade	20.84 SF		0.38	0.00	0.52	0.00	8.44
326. Remove Carpet pad	20.84 SF		0.16	0.00	0.22	0.00	3.55
327. Carpet - High grade	23.96 SF		0.00	5.14	9.79	24.64	157.58
15 % waste added for Carpet - High grade.							
328. Carpet pad	20.84 SF		0.00	0.60	1.00	2.50	16.00
329. Remove 1/2" drywall - hung, taped, floated, ready for paint	20.84 SF		0.58	0.00	0.80	0.00	12.89
330. Remove Batt insulation - 6" - R21 - paper / foil faced	20.84 SF		0.40	0.00	0.55	0.00	8.89



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500 Fax: 215-821-2315

## **CONTINUED - Office Closet**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
331. Batt insulation - 6" - R21 - paper / foil faced	20.84 SF		0.00	1.63	2.70	6.80	43.47
332. Metal studding - Track - 2 1/2" wide - 25 ga mat. only	20.84 LF		0.00	0.38	0.62	1.58	10.12
333. 1/2" drywall - hung, taped, floated, ready for paint	20.84 SF		0.00	2.53	4.19	10.54	67.46
334. Additional cost for gluing drywall	20.84 SF		0.00	0.30	0.49	1.26	8.00
335. Clean floor or roof joist system	20.84 SF		0.00	1.01	1.39	0.00	22.44
336. Clean door / window opening (per side)	1.00 EA		0.00	13.71	0.91	0.00	14.62
337. Clean door - bypass set (per side)	1.00 EA		0.00	15.26	1.01	0.00	16.27
338. Clean door hardware	1.00 EA		0.00	7.01	0.46	0.00	7.47
339. Clean floor	20.84 SF		0.00	0.44	0.61	0.00	9.78
340. Seal underlayment for odor control	20.84 SF		0.00	0.58	0.80	0.00	12.89
341. Deodorize building - Hot thermal fog	166.70 CF		0.00	0.07	0.77	0.00	12.44
342. Mask the floor per square foot - plastic and tape - 4 mil	20.84 SF		0.00	0.24	0.40	1.00	6.40
343. Seal/prime then paint the walls and ceiling twice (3 coats)	160.86 SF		0.00	1.32	16.88	42.46	271.68
344. Seal & paint door or window opening (per side)	5.00 EA		0.00	31.65	12.58	31.66	202.49
345. Seal/Paint bypass door set - slab only- 2 coats (per side)	1.00 EA		0.00	45.85	3.65	9.18	58.68
346. Seal & paint baseboard - two coats	16.67 LF		0.00	1.50	1.99	5.00	32.00
347. Seal & paint closet shelving	8.33 LF		0.00	9.06	6.00	15.10	96.57
348. Final cleaning - construction - Residential	20.84 SF		0.00	0.27	0.44	1.12	7.19
Totals: Office Closet					79.85	179.16	1,285.78



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

<b>─</b> 12' 10" <b>─</b>
Entry 12' 8" Cor 80 8
Line 196
111 4 H
inch inch inch inch inch inch inch inch
nets (B1) Siving Room
7.7.7
7 2 12 17 17 17 17 17 17 17 17 17 17 17 17 17
© <b>⊢</b> 5' <b>-3</b> 111
3' 1"

**Living Room** 

Height: 8'

471.33 SF Walls785.08 SF Walls & Ceiling34.86 SY Flooring61.42 LF Ceil. Perimeter

313.75 SF Floor 61.42 LF Floor Perimeter

313.75 SF Ceiling

 Missing Wall
 3' X 8'

 Missing Wall
 6' 9" X 8'

 Window
 5' X 4'

 Missing Wall
 4' X 8'

 Door
 1' 9" X 6' 8"

Opens into FOYER\_ENTRY
Opens into DINING\_ROOM
Opens into Exterior
Opens into HALLWAY
Opens into COAT\_CLOSET

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
349. Contents - move out then reset	1.00 EA		0.00	72.25	5.75	14.46	92.46
350. Remove Baseboard - 3 1/4"	61.42 LF		0.63	0.00	2.56	0.00	41.25
351. Baseboard - 3 1/4"	61.42 LF		0.00	3.72	18.17	45.70	292.35
352. Remove Vinyl plank flooring - High grade	313.75 SF		1.64	0.00	34.09	0.00	548.64
353. Remove Vapor barrier - visqueen - 6mil	313.75 SF		0.11	0.00	2.29	0.00	36.80
354. Vinyl plank flooring - High grade	313.75 SF		0.00	6.71	167.36	421.06	2,693.68
355. Vapor barrier - visqueen - 6mil	313.75 SF		0.00	0.32	7.98	20.08	128.46
356. Clean the walls and ceiling	785.08 SF		0.00	0.38	19.76	0.00	318.09
357. Clean roof window or skylight	2.00 EA		0.00	35.58	4.71	0.00	75.87
358. Clean recessed light fixture	4.00 EA		0.00	11.17	2.96	0.00	47.64
359. Clean door / window opening (per side)	3.00 EA		0.00	13.71	2.72	0.00	43.85
360. Clean door (per side)	3.00 EA		0.00	7.58	1.51	0.00	24.25
361. Clean door hardware	3.00 EA		0.00	7.01	1.39	0.00	22.42
362. Clean floor	313.75 SF		0.00	0.44	9.15	0.00	147.20
363. Seal underlayment for odor control	313.75 SF		0.00	0.58	12.06	0.00	194.04
364. Deodorize building - Hot thermal fog	2,510.00 CF		0.00	0.07	11.64	0.00	187.34
365. Mask the floor per square foot - plastic and tape - 4 mil	313.75 SF		0.00	0.24	5.99	15.06	96.35
366. Recessed light fixture - Detach & reset trim only	4.00 EA		0.00	3.80	1.21	3.04	19.45
367. Seal/prime then paint the walls and ceiling twice (3 coats)	785.08 SF		0.00	1.32	82.39	207.26	1,325.96
HARE-FIRE					10	0/8/2021	Dogo: 1




Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

#### **CONTINUED - Living Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
368. Seal & paint door or window opening (per side)	5.00 EA		0.00	31.65	12.58	31.66	202.49
369. Seal & paint door slab only (per side)	3.00 EA		0.00	38.41	9.16	23.04	147.43
370. Seal & paint baseboard - two coats	61.42 LF		0.00	1.50	7.32	18.42	117.87
371. Final cleaning - construction - Residential	313.75 SF		0.00	0.27	6.73	16.94	108.38
Totals: Living Room					429.48	816.72	6,912.27



Dining Room Height: 8'

101.33 SF Walls158.15 SF Walls & Ceiling

6.31 SY Flooring15.17 LF Ceil. Perimeter

56.81 SF Ceiling 56.81 SF Floor

15.17 LF Floor Perimeter

Window 5' X 4'
Missing Wall 6' 9" X 8'
Missing Wall 8' 3" X 8'

Opens into Exterior
Opens into LIVING\_ROOM
Opens into KITCHEN

_				-			
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
372. Contents - move out then reset - Small room	1.00 EA		0.00	54.24	4.31	10.84	69.39
373. Remove Baseboard - 3 1/4"	15.17 LF		0.63	0.00	0.63	0.00	10.19
374. Baseboard - 3 1/4"	15.17 LF		0.00	3.72	4.49	11.28	72.20
375. Remove Vinyl plank flooring - High grade	56.81 SF		1.64	0.00	6.17	0.00	99.34
376. Remove Vapor barrier - visqueen - 6mil	56.81 SF		0.11	0.00	0.41	0.00	6.66
377. Vinyl plank flooring - High grade	56.81 SF		0.00	6.71	30.30	76.24	487.74
378. Vapor barrier - visqueen - 6mil	56.81 SF		0.00	0.32	1.44	3.64	23.26
379. Clean the walls and ceiling	158.15 SF		0.00	0.38	3.98	0.00	64.08
380. Clean chandelier	1.00 EA		0.00	45.63	3.02	0.00	48.65
381. Clean door / window opening (per side)	2.00 EA		0.00	13.71	1.82	0.00	29.24
382. Clean window unit (per side) 10 - 20 SF	2.00 EA		0.00	15.88	2.10	0.00	33.86




Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

#### **CONTINUED - Dining Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
383. Clean floor	56.81 SF		0.00	0.44	1.66	0.00	26.66
384. Seal underlayment for odor control	56.81 SF		0.00	0.58	2.18	0.00	35.13
385. Deodorize building - Hot thermal fog	454.50 CF		0.00	0.07	2.11	0.00	33.93
386. Mask the floor per square foot - plastic and tape - 4 mil	56.81 SF		0.00	0.24	1.08	2.72	17.43
387. Seal/prime then paint the walls and ceiling twice (3 coats)	158.15 SF		0.00	1.32	16.60	41.76	267.12
388. Seal & paint door or window opening (per side)	2.00 EA		0.00	31.65	5.03	12.66	80.99
389. Seal & paint window sill	6.00 LF		0.00	2.57	1.22	3.08	19.72
390. Seal & paint baseboard - two coats	15.17 LF		0.00	1.50	1.81	4.56	29.13
391. Final cleaning - construction - Residential	56.81 SF		0.00	0.27	1.22	3.06	19.62
Totals: Dining Room					91.58	169.84	1,474.34



Kitchen Height: 8'

303.33 SF Walls 415.28 SF Walls & Ceiling

12.44 SY Flooring

37.92 LF Ceil. Perimeter

111.94 SF Ceiling

111.94 SF Floor

37.92 LF Floor Perimeter

Missing Wall - Goes to Floor Door 8' 3" X 8' 2' 10" X 6' 8" 2' 6" X 6' 8" Opens into DINING\_ROOM
Opens into FOYER\_ENTRY
Opens into UTILITY\_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
392. Contents - move out then reset - Large room	1.00 EA		0.00	108.38	8.62	21.68	138.68
393. Refrigerator - Remove & reset	1.00 EA		0.00	52.81	4.20	10.56	67.57
394. Dishwasher - Detach & reset	1.00 EA		0.00	313.01	24.89	62.60	400.50
395. Detach & Reset Range - freestanding - gas	1.00 EA	214.58	0.00	0.00	17.06	42.92	274.56
396. R&R Ceramic/porcelain tile - High grade	71.29 SF		2.51	15.03	99.41	250.08	1,599.92

Backspalsh will be affected by detaching counter tops (flooring under lower cabinets)



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

## **CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
397. Add-on for tile backsplash installation	71.29 SF		0.00	16.53	93.68	235.68	1,507.78
398. Tile - metal trim - aluminum - up to 9/16	16.00 LF		0.00	4.14	5.27	13.24	84.75
399. Remove Sink faucet - Kitchen	1.00 EA		26.15	0.00	1.73	0.00	27.88
400. Clean sink faucet	1.00 EA		0.00	10.18	0.67	0.00	10.85
401. Install Sink faucet - Kitchen	1.00 EA		0.00	104.40	8.30	20.88	133.58
402. P-trap assembly - Detach & reset	1.00 EA		0.00	80.04	6.36	16.00	102.40
403. Remove Countertop - Granite or Marble	26.00 SF		7.52	0.00	12.95	0.00	208.47
404. Clean countertop	26.00 SF		0.00	0.79	1.36	0.00	21.90
405. Install Countertop - Granite or Marble	26.00 SF		0.00	38.94	80.48	202.48	1,295.40
406. Remove Cabinetry - lower (base) units	6.42 LF		10.47	0.00	4.45	0.00	71.67
407. Clean cabinetry - lower - inside and out	6.42 LF		0.00	15.53	7.93	19.94	127.57
408. Install Cabinetry - lower (base) units	6.23 LF		0.00	43.28	21.43	53.92	344.98
409. Clean cabinetry - upper - inside and out	12.58 LF		0.00	15.53	12.94	0.00	208.31
410. Clean range - exterior	1.00 EA		0.00	33.29	2.21	0.00	35.50
411. Clean microwave - over range - exterior	1.00 EA		0.00	13.64	0.90	0.00	14.54
412. Clean sink	1.00 EA		0.00	13.71	0.91	0.00	14.62
413. Clean refrigerator - exterior	1.00 EA		0.00	20.40	1.35	0.00	21.75
414. Washer/Washing machine - Remove & reset	1.00 EA		0.00	51.39	4.08	10.28	65.75
415. Clean washer - exterior	1.00 EA		0.00	10.42	0.69	0.00	11.11
416. Dryer - Remove & reset	1.00 EA		0.00	39.62	3.14	7.92	50.68
417. Clean dryer - exterior	1.00 EA		0.00	10.66	0.71	0.00	11.37
418. Remove Baseboard - 3 1/4"	37.92 LF		0.63	0.00	1.58	0.00	25.47
419. Baseboard - 3 1/4"	37.92 LF		0.00	3.72	11.22	28.22	180.50
420. Remove Vinyl plank flooring - High grade	111.94 SF		1.64	0.00	12.16	0.00	195.74
421. Remove Vapor barrier - visqueen - 6mil	111.94 SF		0.11	0.00	0.82	0.00	13.13
422. Vinyl plank flooring - High grade	111.94 SF		0.00	6.71	59.71	150.22	961.05
423. Vapor barrier - visqueen - 6mil	111.94 SF		0.00	0.32	2.84	7.16	45.82



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

#### **CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
424. Clean the walls and ceiling	415.28 SF		0.00	0.38	10.45	0.00	168.26
425. Clean recessed light fixture	3.00 EA		0.00	11.17	2.22	0.00	35.73
426. Clean door / window opening (per side)	3.00 EA		0.00	13.71	2.72	0.00	43.85
427. Clean door (per side)	2.00 EA		0.00	7.58	1.00	0.00	16.16
428. Clean door hardware	2.00 EA		0.00	7.01	0.93	0.00	14.95
429. Clean floor	111.94 SF		0.00	0.44	3.26	0.00	52.51
430. Seal underlayment for odor control	111.94 SF		0.00	0.58	4.30	0.00	69.23
431. Deodorize building - Hot thermal fog	895.54 CF		0.00	0.07	4.15	0.00	66.84
432. Mask the floor per square foot - plastic and tape - 4 mil	111.94 SF		0.00	0.24	2.14	5.38	34.39
433. Recessed light fixture - Detach & reset trim only	3.00 EA		0.00	3.80	0.91	2.28	14.59
434. Seal/prime then paint the walls and ceiling twice (3 coats)	415.28 SF		0.00	1.32	43.58	109.64	701.39
435. Seal & paint door or window opening (per side)	3.00 EA		0.00	31.65	7.55	19.00	121.50
436. Seal & paint door slab only (per side)	2.00 EA		0.00	38.41	6.11	15.36	98.29
437. Seal & paint baseboard - two coats	37.92 LF		0.00	1.50	4.52	11.38	72.78
438. Final cleaning - construction - Residential	111.94 SF		0.00	0.27	2.40	6.04	38.66
Totals: Kitchen					610.29	1,322.86	9,822.93



#### **Utility Room**

101.95 SF Walls

110.15 SF Walls & Ceiling

0.91 SY Flooring

12.74 LF Ceil. Perimeter

Height: 8'

8.20 SF Ceiling 8.20 SF Floor

12.74 LF Floor Perimeter

Door 2' 6" X 6' 8" Opens into KITCHEN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
439. Detach & Reset Interior door - Colonist - slab only	1.00 EA	24.05	0.00	0.00	1.91	4.82	30.78




Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

## **CONTINUED - Utility Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
440. Clean water heater	1.00 EA		0.00	24.85	1.65	0.00	26.50
441. Clean furnace - forced air	1.00 EA		0.00	55.71	3.69	0.00	59.40
442. Clean the walls and ceiling	110.15 SF		0.00	0.38	2.77	0.00	44.63
443. Clean door / window opening (per side)	1.00 EA		0.00	13.71	0.91	0.00	14.62
444. Clean door (per side)	1.00 EA		0.00	7.58	0.50	0.00	8.08
445. Clean door hardware	1.00 EA		0.00	7.01	0.46	0.00	7.47
446. Clean floor	8.20 SF		0.00	0.44	0.24	0.00	3.85
447. Deodorize building - Hot thermal fog	65.58 CF		0.00	0.07	0.30	0.00	4.89
448. Mask the floor per square foot - plastic and tape - 4 mil	8.20 SF		0.00	0.24	0.16	0.40	2.53
449. Seal & paint door or window opening (per side)	1.00 EA		0.00	31.65	2.52	6.34	40.51
450. Seal & paint door slab only (per side)	1.00 EA		0.00	38.41	3.05	7.68	49.14
451. Final cleaning - construction - Residential	8.20 SF		0.00	0.27	0.18	0.44	2.83
Totals: Utility Room					18.34	19.68	295.23

Height: 8' Foyer/Entry 25.25 SF Ceiling



160.00 SF Walls 185.25 SF Walls & Ceiling 2.81 SY Flooring 20.00 LF Ceil. Perimeter

**Opens into Exterior** 

25.25 SF Floor

20.00 LF Floor Perimeter

**TOTAL** 

Door	2' X	6' 8"		Opens into Exterior					
Missing Wall - Goes to Floor	2' 10	0'' X 6' 8''		Opens into KITCHEN					
Missing Wall	3' X	8'		Opens into LIVING_ROOM					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P			
450 D D 1 1 0 1/4"	20.00 I.E		0.62	0.00	0.02	0.00			

452. Remove Baseboard - 3 1/4"	20.00 LF	0.63	0.00	0.83	0.00	13.43
453. Baseboard - 3 1/4"	20.00 LF	0.00	3.72	5.92	14.88	95.20
454. Remove Vinyl plank flooring - High grade	25.25 SF	1.64	0.00	2.74	0.00	44.15
455. Remove Vapor barrier - visqueen - 6mil	25.25 SF	0.11	0.00	0.18	0.00	2.96



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

# **CONTINUED - Foyer/Entry**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
456. Vinyl plank flooring - High grade	25.25 SF		0.00	6.71	13.46	33.88	216.77
457. Vapor barrier - visqueen - 6mil	25.25 SF		0.00	0.32	0.65	1.62	10.35
458. Clean the walls and ceiling	185.25 SF		0.00	0.38	4.66	0.00	75.06
459. Clean recessed light fixture	1.00 EA		0.00	11.17	0.74	0.00	11.91
460. Clean door / window opening (per side)	2.00 EA		0.00	13.71	1.82	0.00	29.24
461. Clean door (per side)	1.00 EA		0.00	7.58	0.50	0.00	8.08
462. Clean door hardware	1.00 EA		0.00	7.01	0.46	0.00	7.47
463. Clean floor	25.25 SF		0.00	0.44	0.74	0.00	11.85
464. Seal underlayment for odor control	25.25 SF		0.00	0.58	0.97	0.00	15.62
465. Deodorize building - Hot thermal fog	202.00 CF		0.00	0.07	0.94	0.00	15.08
466. Mask the floor per square foot - plastic and tape - 4 mil	25.25 SF		0.00	0.24	0.48	1.22	7.76
467. Recessed light fixture - Detach & reset trim only	1.00 EA		0.00	3.80	0.30	0.76	4.86
468. Seal/prime then paint the walls and ceiling twice (3 coats)	185.25 SF		0.00	1.32	19.44	48.90	312.87
469. Seal & paint door or window opening (per side)	2.00 EA		0.00	31.65	5.03	12.66	80.99
470. Seal & paint door slab only (per side)	1.00 EA		0.00	38.41	3.05	7.68	49.14
471. Seal & paint baseboard - two coats	20.00 LF		0.00	1.50	2.39	6.00	38.39
472. Final cleaning - construction - Residential	25.25 SF		0.00	0.27	0.54	1.36	8.72
Totals: Foyer/Entry					65.84	128.96	1,059.90
Total: Main Level					3,752.40	7,701.92	60,394.02

## Hvac/Duct

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
473. Clean furnace - forced air - Large	1.00 EA		0.00	89.59	5.94	0.00	95.53
474. Heat/AC register - Mechanically attached - Detach & reset	16.00 EA		0.00	8.28	8.78	0.00	141.26
475. Clean register - heat / AC	16.00 EA		0.00	5.95	6.31	0.00	101.51



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500

Fax: 215-821-2315

#### **CONTINUED - Hvac/Duct**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
476. Clean ductwork - Interior (PER REGISTER)	16.00 EA		0.00	35.09	37.20	0.00	598.64
Totals: Hvac/Duct					58.23	0.00	936.94

#### General

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
477. Dumpster load - Approx. 12 yards, 1-3 tons of debris	1.00 EA		525.54	0.00	41.78	105.10	672.42
478. Taxes, insurance, permits & fees (Bid Item)	1.00 EA		0.00	0.00	0.00	0.00	0.00
If permits are needed will bill as incurred	•						
479. Lead Paint Safety (Bid Item)	1.00 EA		0.00	0.00	0.00	0.00	0.00
Totals: General					41.78	105.10	672.42

#### **Labor Minimums Applied**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
480. Heat, vent, & air cond. labor minimum	1.00 EA		0.00	378.68	30.11	75.74	484.53
481. Finish hardware labor minimum	1.00 EA		0.00	41.23	3.28	8.24	52.75
Totals: Labor Minimums Applied					33.39	83.98	537.28
Line Item Totals: HARE-FIRE					3,885.80	7,891.00	62,540.66

## **Grand Total Areas:**

3,119.31	SF Walls	1,107.02	SF Ceiling	4,226.33	SF Walls and Ceiling
1,107.02	SF Floor	123.00	SY Flooring	398.25	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	408.25	LF Ceil. Perimeter
1,107.02	Floor Area	1,200.28	Total Area	3,119.31	Interior Wall Area
1,225.00	Exterior Wall Area	145.00	Exterior Perimeter of Walls		
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500 Fax: 215-821-2315

# **Summary**

Line Item Total Overhead		50,763.86 3,945.50
Profit		3,945.50
Total Tax(Rep-Maint)		3,885.80
Replacement Cost Value		\$62,540.66
Net Claim		\$62,540.66
	Jason Kluska	



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500 Fax: 215-821-2315

# Recap of Taxes, Overhead and Profit

	Overhead (10%)	Profit (10%) To	otal Tax(Rep-Maint) (6.625%)	Mat Tax (Cap Impr) (6.625%)	Clothing Acc Tax (6.625%)	Storage Rental Tax (6.625%)
Line It	tems					
	3,945.50	3,945.50	3,885.80	0.00	0.00	0.00
Total						
	3,945.50	3,945.50	3,885.80	0.00	0.00	0.00



Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500 Fax: 215-821-2315

# **Recap by Room**

**Estimate: HARE-FIRE** 

General Labor Minimums Applied	525.54 419.91	1.04% 0.83%
Area Subtotal: Main Level Hvac/Duct	48,939.70 878.71	96.41% 1.73%
Foyer/Entry	865.10	1.70%
Utility Room	257.21	0.51%
Dining Room Kitchen	7,889.78	2.39% 15.54%
Living Room	5,666.07 1,212.92	11.16% 2.39%
Office Closet	1,026.77	2.02%
Office	4,219.56	8.31%
Coat Closet	872.06	1.72%
Linen Closet	829.70	1.63%
Hall Bathroom	7,964.98	15.69%
Hallway	2,603.51	5.13%
Master Bath	7,155.85	14.10%
Walk-in Closet	2,330.33	4.59%
Bedroom	6,045.86	11.91%



HARE-FIRE

# **Guardian Restoration Co.**


Guardian Restoration Co. 7315 James Street Philadelphia PA 19136 215-288-7500 Fax: 215-821-2315

# **Recap by Category**

O&P Items	Total	%
APPLIANCES	671.41	1.07%
CABINETRY	3,675.84	5.88%
CLEANING	482.37	0.77%
CONTENT MANIPULATION	433.61	0.69%
GENERAL DEMOLITION	795.46	1.27%
DOORS	226.34	0.36%
DRYWALL	4,304.74	6.88%
ELECTRICAL	232.68	0.37%
FLOOR COVERING - CARPET	2,939.34	4.70%
FLOOR COVERING - VINYL	3,811.89	6.10%
FLOOR COVERING - WOOD	181.78	0.29%
FINISH CARPENTRY / TRIMWORK	1,552.94	2.48%
FINISH HARDWARE	226.99	0.36%
HEAT, VENT & AIR CONDITIONING	378.68	0.61%
INSULATION	1,370.36	2.19%
LIGHT FIXTURES	415.44	0.66%
MARBLE - CULTURED OR NATURAL	194.60	0.31%
MIRRORS & SHOWER DOORS	230.14	0.37%
PLUMBING	2,117.86	3.39%
PAINTING	8,838.93	14.13%
TILE	6,072.78	9.71%
WINDOW TREATMENT	298.96	0.48%
O&P Items Subtotal	39,453.14	63.08%
Non-O&P Items	Total	%
CONT: CLEAN APPLIANCES	21.08	0.03%
CLEANING	6,011.88	9.61%
GENERAL DEMOLITION	4,083.68	6.53%
PLUMBING	556.74	0.89%
PAINTING	637.34	1.02%
Non-O&P Items Subtotal	11,310.72	18.09%
O&P Items Subtotal	39,453.14	63.08%
Overhead	3,945.50	6.31%
Profit Total Tay(Pan Maint)	3,945.50	6.31%
Total Tax(Rep-Maint)	3,885.80	6.21%
Total	62,540.66	100.00%

10/8/2021

Page: 30



# Main Level