

Rod End Bearing Division

Project Initiation Document (PID)

PID Number:	PID-000002	Date Initiated:	06/22/2026	
Customer:	AS-STD	Target Date:	07/02/2026	
Prepare by:	Nanthiwa K.	Check by:	Thapanon P.	
Customer P/N:	M81935/1-XX(L)	NHBB P/N:	TANM(L)x	

Project Category Selection (Check one box to determine required phases):

- ☐ 1. Full APQP (With Product Design) : Execute Phases 1, 2, 3, 4, 5
- ☐ 2. Full APQP (Build-to-print) : Execute Phases 1, 3, 4, 5 (Skip Ph 2)
- ☐ 3. New Model (Standard Case) : Execute Phases 3, 4, 5 (Skip Ph 1, 2)
- ☒ 4. New Model (Missing Doc) : Execute Phases 3, 5 (Skip Ph 1, 2, 4)
- ☐ 5. New Variant (Similarity) : Execute Phase 5 Only

PHASE EXECUTION CHECKLIST

(Instructions: Check the box "N/A" if the phase is skipped. Otherwise, mark "Done" and attach the document behind this PID when completed).

PHASE 1: Planning

(Ref: PD-DV-EN-111001)

- ☐ Feasibility and Specification Review Record
- ☐ Preliminary Project Plan / Timeline
- ☐ Preliminary BOM

PHASE 2: Product Design

(Ref: PD-DV-EN-12001)

- ☐ Internal Engineering Drawing
- ☐ DFMEA (Only if Customer requires)

PHASE 3: Process Design

(Ref: PD-DV-EN-111002, 111003, 111004, 111005)

- ☐ Process Flow Diagram (PFD)
- ☐ Process FMEA (PFMEA)
- ☐ Pre-Launch Control Plan
- ☐ Tooling / Jig Design Drawing

PHASE 4: Validation

(Ref: PD-DV-EN-111006, 111007)

- ☐ First Article Inspection Report (FAIR)
- ☐ MSA (GR&R) and Capability Study (Cpk/Ppk) Report
- ☐ Packaging Standard Document
- ☐ Production Readiness Review (PRR) Checklist
- ☐ PPAP Approval Form (Signed by Customer)

PHASE 5: Mass Production

- ☐ Mass Production Control Plan
- ☐ Work Instructions / Standard Operating Procedures (SOP)
- ☐ Lessons Learned Record (Update to PFMEA if any issues)

FINAL APPROVAL

By signing below, the cross-functional team and management confirm that all required deliverables checked above have been verified, attached, and the project is formally closed and handed over to mass production.

Prepare

Check

Approve

