

Diagnostics Report

2025-09-24 15:09:09

Customer Details

Huggins

Repair Details

Work Order

Address

Customer:

Repair Order

B19BUB

29684

Registration Vehicle 2019/Mitsubishi/L200 (KK#,KL#)/

MMCJYKL10KH016167

VIN Odometer

73607miles

Telephone

Insurance

Report Type: post-scan

Scan Overview

0 0 0 Fault Cleared Fault Found Affected Modules

Module Checklist

System	Status	DTC
MPI/GDI/Diesel	②	0
AT/CVT/A-MT/TC-SST	②	0
ABS/ASC/ASTC/WSS	②	0
SRS-Air Bag	②	0
Meter	②	0
Air Conditioner	②	0
Lane Keep ADAS	②	0
ETACS	②	0
KOS/OSS/IMMO/Keyless - without KOS	②	0
AUDIO	②	0
Customer name:	②	0

DTCs