

Diagnostics Report

2025-09-23 13:51:32

<u>Customer Details</u> <u>Repair Details</u>

Customer: AS Work Order 29504

Address -- Registration KV19BUC

Vehicle --/Benz/S (222)/ VIN WDD2221202A480670

Telephone Odometer 74971.54miles

Insurance

Repair Order

Report Type: pre-scan

Scan Overview

13 8 0

Fault Found Affected Modules Fault Cleared

Module Checklist

System	Status	DTC
ECM(Engine Control Unit)	⊘	0
TCM(Transmission Control Unit)	②	0
ESP(Electronically controlled vehicle stability braking system control unit)	⊗	1
SRS(Supplemental Restraint System Control Unit)	②	0
KI(Instrument Cluster)	②	0
TPM(Tire Pressure Monitor Control Unit)	②	0
PTS(Parking System) ADAS	②	0
SAMF(Front SAM signal acquisition control unit)	⊗	2
LIN:ABF(Instrument Panel Switch)	②	0
LIN:AU(Analog Clock)	②	0
LIN:BSN(Battery Sensor)	②	0
LIN:FSW(Wiper Motor)	②	0
LIN:VCS(Rain/sunlight sensor)	②	0
SAMR(Rear SAM signal acquisition control unit)	⊗	1
LIN:SHM(Seat Heating/Ventilation)	②	0
EZS(Electronic Ignition Lock Control Unit)	②	0
ES(Electric Power Steering)	②	0
KLA(Air Conditioner Control Unit)	⊗	1
ADS(Suspension)	⊘	0
SCR(AdBlue control unit)	⊘	0
PTCU(Drivetrain Control Unit)	⊘	0
HU(Head Unit Control Unit)	⊗	3
KG(Keyless Go Control Unit)	⊘	0
LIN:HSM(Rear Switching Control Unit)	⊘	0
SW-SW-R(Right Headlamp Control Unit)	②	0
SW-SW-L(Left Headlamp Control Unit)	②	0
SG-L-VR(Right front LED matrix light group control unit)	⊘	0
SG-L-VL(Left front LED matrix light group control unit)	⊘	0
LRE(Steering Wheel Electronics)	②	0
ABA(Collision Prevention Assist)	⊘	0
DMFL(Left Front Door Control Unit)	⊗	1
DMFR(Right Front Door Control Unit)	②	0
DMRR(Right Rear Door Control Unit)	②	0
DMRL(Left Rear Door Control Unit)	⊗	3

Status

codes)

Stored(Event



ZBE(Head Unit Display)	⊗	1
TPAD(TPAD)	⊘	0
ZAN(Center Display Control Unit)	②	0
SMFK(Multifunctional stereo camera)	⊘	0
RBTMFR(Right Front Seat Belt Tensioner Control Unit)	⊘	0
RBTMFL(Left Front Seat Belt Tensioner Control Unit)	⊘	0
PSD(Sunroof Control Unit)	⊘	0
MTAS(Mobile Phone Cradle Control Unit)	⊘	0
MRM(Steering Column Control Unit)	⊘	0
HKS(Trunk Lid Control Unit)	⊘	0
FSCU(Fuel Pump Control Unit)	⊘	0
ESET-RR(Right Rear Seat Control Unit)	⊘	0
ESET-RL(Left Rear Seat Control Unit)	⊘	0
ESEP(Passenger Side Electric Seat Adjustment Control Unit)	⊘	0
LIN:LSE-BFS(Front Passenger Seat Lumbar Support Control Unit)	⊘	0
ESED(Driver Side Electric Seat Adjustment Control Unit)	⊘	0
LIN:LSE-FS(Driver Seat Lumbar Support Control Unit)	⊘	0
DTA(Telematics Service Control Unit)	⊘	0
DBE(Sunroof Control Unit)	⊘	0
LIN:AISP_2(Interior mirror)	⊘	0
LIN:AS_2(Alarm Siren)	⊘	0
AML(Ambient Lighting Lamp)	⊘	0

DTCs

DTC

B15A100

HU(Head Unit Control Unit) (3 DTCs)

DTC Description

Login to the server has failed.

ESP(Electronically controlled vehicle stability braking system control unit) (1 DTC)

DTC	DTC Description	Status
B11C1FA	The additional battery has a malfunction.	Stored
DTC	DTC Description	Status
B11C11B	The additional battery has a malfunction. The limit value for resistance has been exceeded.	Stored
B1F4500	The starter battery has excessive resistance.	Stored
B211C15	The output of relay 3 for the socket has a malfunction. There is a short circuit to positive or an open circuit.	Active and stored
B1A9015	Right front side air vent' potentiometer fault - open circuit or short circuit to positive	Stored

Stored



B15562A

Stored(Event B21A100 An internal control unit reset was performed. codes) DTC **DTC** Description Status Stored B1DFB13 The output for mirror housing adjustment has a malfunction. There is an open circuit. **DMRL(Left Rear Door Control Unit) (3 DTCs)** DTC **DTC** Description Status Active and B18B72A Left rear power window' switch fault - no signal change stored Switch 'Roller sun blind for roof' has a malfunction. There is no signal change. Active and B22FE2A stored B22FF2A Switch 'Roller sun blind for rear window' has a malfunction. There is no signal Active and change. stored DTC **DTC** Description Status

The controller sticks in the depressed position. There is no signal change.