

2025-09-24 10:05:29

Diagnostics Report

Customer Details Repair Details

Customer: Cary Work Order 29566 Repair Order

Address -- Registration FJ24XWP

Vehicle 2024 (R)/Volkswagen/EB - ID.Buzz 2023 >/all engine codes

VIN WV1ZZZEB8RH019895

Telephone Odometer 7270miles

Insurance

Report Type: pre-scan

Scan Overview

52 12 0
Fault Found Affected Modules Fault Cleared

Module Checklist

System	Status	DTC
01 - Engine Control Module 1	⊗	4
03 - Brakes 1	⊗	2
08 - Air Conditioning	⊗	4
09 - Electronic central electric	⊗	6
13 - Adaptive Cruise Control	⊗	2
15 - Airbag	⊗	1
16 - Steering column electronics	⊗	1
19 - Gateway	⊗	26
23 - Brake booster	②	0
2B - Steering Column Locking	②	0
3C - Lane change assistance	②	0
42 - Driver's door electronics	②	0
44 - Power Steering	⊗	2
51 - Electric drive	②	0
52 - Passenger's door electronics	②	0
5F - Information electronics 1	⊗	1
6C - Camera System Rear View	⊘	0
75 - Telematics Communication Unit	⊗	1
76 - Parking assistance	⊗	2
7E - Display unit Driver display	⊘	0
8C - Battery Energy Control Module	②	0
A5 - Front sensor for drivers assistant systems ADAS	②	0
B7 - Interface for access/start system	②	0
CO - Actuator for exterior noise	②	0
C6 - High-voltage battery charger	②	0
D6 - Light Control Left 2	②	0
D7 - Light Control Right 2	②	0

DTCs

U041300	Control unit 2 for battery energy management implausible signal	Passive/Sporadic
U105400	Information electronics 1 control unit No communication	Passive/Sporadic
U041500	Invalid data received from ABS control unit	Passive/Sporadic



U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic			
03 - Brakes 1 (2 DTCs)					
DTC	DTC Description	Status			
C123E00	Hydraulic brake booster	Passive/Sporadic			
C102D00	Tire pressure warning	Passive/Sporadic			
08 - Air Co	nditioning (4 DTCs)				
DTC	DTC Description	Status			
P0D6D00	A/C Compressor Motor Voltage Low	Passive/Sporadic			
P0EA900	A/C compressor motor voltage sensor B circuit performance	Passive/Sporadic			
B1453F0	A/C compressor High voltage power supply - error	Passive/Sporadic			
U014600	Lost communication with serial data gateway module A	Passive/Sporadic			
16 Steering	g column electronics (1 DTC)				
DTC	DTC Description	Status			
U112300	Databus error value received	Passive/Sporadic			
U14FE00	Secure Onboard Communication Signature inspection failed	Passive/Sporadic			
U14FF00	Secure Onboard Communication Signature creation failed	Passive/Sporadic			
U110B00	Light switch No communication	Passive/Sporadic			
B181504	Left rear reading lamp Faulty	Active/static			
B181604	Right rear reading lamp Faulty	Active/static			
U112300	Databus error value received	Passive/Sporadic			
U112100	Data bus message missing	Passive/Sporadic			
15 Airbag (1 DTC)					
DTC	DTC Description	Status			
U112100	Data bus message missing	Passive/Sporadic			
16 Steering column electronics (1 DTC)					
DTC	DTC Description	Status			
U112300	Databus error value received	Passive/Sporadic			
U14A800	Ethernet databus branch 11 no communication	Passive/Sporadic			



U140600	Static current too high	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic
U15FA00	EgoMaster Input data error	Passive/Sporadic
B126A29	Lamp switch Range/performance	Passive/Sporadic
U14FE00	Secure Onboard Communication Signature inspection failed	Passive/Sporadic
B163002	predictive route data Signal error	Passive/Sporadic
C113E00	Software error detected	Passive/Sporadic
U140A00	Terminal 30 Open circuit	Passive/Sporadic
U10DC00	Local data bus 4 Electrical error	Passive/Sporadic
P0E5F00	Battery charger coupler temperature A too high	Passive/Sporadic
U15AD00	Quick battery charging (DC) Charging station incompatible	Passive/Sporadic
U163300	Power line communication Connection fault	Passive/Sporadic
B1A7BF0	High voltage insulation measurement Faulty	Passive/Sporadic
U10E000	Front sensor for driver assist system No communication	Passive/Sporadic
U112100	Data bus message missing	Active/static
C11A098	Control module Temperature too high	Active/static
P1DD500	Charge socket A Connector locking mechanism activation error	Passive/Sporadic
B1CA2F0	Charging socket flap A Unlocking activation error	Passive/Sporadic
B1CA2F1	Charging socket flap A Locking activation error	Passive/Sporadic
P1DDC00	Charge socket A Connector locking mechanism not locked	Passive/Sporadic
P1DCB00	External charging infrastructure No charge readiness for charging socket A	Passive/Sporadic
P1DCA00	Battery charger DC charging socket Temperature too high	Passive/Sporadic
U012200	Lost communication with vehicle dynamics control module	Passive/Sporadic
U015100	Lost Communication With Restraints Control Module	Passive/Sporadic
U029200	Lost communication with drive motor control unit B	Active/static
DTC	DTC Description	Status
U140A00	Terminal 30 Open circuit	Passive/Sporadic



B1168F2	Steering angle sensor no initialization	Passive/Sporadic	
U111000	Function restriction caused by communication interruption	Passive/Sporadic	
U14FE00	Secure Onboard Communication Signature inspection failed	Passive/Sporadic	
15 Airbag (1 DTC)			
DTC	DTC Description	Status	
B1AE2F0	Driver assistance systems audio output Infotainment system, implausible signal	Passive/Sporadic	
U112100	Data bus message missing	Passive/Sporadic	
DTC	DTC Description	Status	
U163F00	Hybrid/high voltage battery system No communication with application server	Passive/Sporadic	
P1CF600	Charge socket A Connector unlock prohibited	Passive/Sporadic	