

2025-09-23 12:47:59

Diagnostics Report Cu

Customer Details Repair Details

Customer: Cary UK Work Order 29497 Repair Order

Address -- Registration EN72DZS

Vehicle 2023/Kia(Europe)/SPORTAGE HEV(NQ5E HEV)/G 1.6 T-GDI

VIN U5YPX81GMPL064912

Telephone Odometer 27767miles

Insurance

Report Type: post-scan

Scan Overview

U	U	U
Fault Found	Affected Modules	Fault Cleared

Module Checklist		
System	Status	DTC
ENG (Engine)	⊘	0
MCU (Motor Control System)	⊘	0
A/T (Transaxle)	⊘	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	⊘	0
AB (Airbag)	⊘	0
CLU (Cluster Module)	❷	0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	⊘	0
A/C (Air Conditioner)	❷	0
CODE (Transmitter Code Saving)	⊘	0
EPS (Motor Driven Power Steering)	❷	0
PTG (Power Tail Gate)	⊘	0
BMS (Battery Management System)	②	0
PSM (Power Seat Module)	②	0
MFSW (Multi Function Switch)	②	0
AVN (Audio Video Navigation) ADAS	⊘	0
AMP (Amplifier)	②	0
ECALL (eCall)	⊘	0
WPC (Wireless Power Charger)	⊘	0
HCU/LDC (Hybrid Control/Low DC-DC Converter)	⊘	0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	⊘	0
VESS (Virtual Engine Sound System)	⊘	0
ICU (Integrated Central Control Unit)	⊘	0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	⊘	0
E-ST (E-Shifter)	⊘	0
MLM (Mood Lamp Module)	⊘	0
F-CMR (Front View Camera)	⊘	0
SHVU-F (Seat heater Ventilation control Unit-Front)	⊘	0
FR (Front Radar)	⊘	0
ADAS_P (Advanced Driver Assistance Systems_Parking)	⊘	0
SHVU-R (Seat heater Ventilation control Unit-Rear)	❷	0
SCU (SBW Control Unit)	❷	0
RCR (Rear Corner Radar)	⊘	0
ILCU-RH (Integrated Led headlamp Control Unit_RH)	⊘	0
ILCU-LH (Integrated Led headlamp Control Unit_LH)	②	0



Customer name:

②

0

DTCs