

Diagnostics Report

2025-09-23 11:49:04

Customer Details

Repair Details

Work Order 29479

Customer: Address

Telephone

Repair Order

Cary UK

Registration

GC21LKG

28481 miles

Vehicle VIN

2021/FIAT/CE-500 BEV/ ZFAEFAC43MX032552

Odometer

Insurance

Report Type: pre-scan

Scan Overview

2 2 0 Fault Found Affected Modules Fault Cleared

Module Checklist

System	Status	DTC
EVCU (Electronic Vehicle Control Unit)	②	0
ABS (Anti-lock Brake System)	×	1
ORC (Airbag/Occupant Restraint)	②	0
IPC (Instrument Panel Cluster)	×	1
BCM (Body Controller)	②	0
BPCM (Battery Pack Control Module)	②	0
DDLM (Driver Door Latch Module)	②	0
DSM (Display Screen Module)	②	0
EMCM (Entertainment Multimedia Control Module)	②	0
EPS (Electric Power Steering)	②	0
ESM (Electronic Shifter)	②	0
ETM (Entertainment Telematic Module)	②	0
HALF (Haptical Lane Feedback) ADAS	②	0
HVAC (Heat, Ventilation and A/C)	②	0
ICS (Integrated Center Stack)	②	0
IDCM (Integrated Dual Charge Module)	②	0
PAM (Park Assist Module) ADAS	②	0
PDLM (Passenger Door Latch Module)	❷	0
TBM2 (Telematic Box Module 2)	⊘	0

DTCs

ABS (Anti-lock Brake System) (1 DTC)

DTC	DTC Description	Status

Haptic Lane Feedback (HALF) - signal invalid Stored

IPC (Instrument Panel Cluster) (1 DTC)

DTC **DTC** Description Status

U176487 Please refer to the service manual Stored