Real Button Press automatic automatic TRANSMIT (sense finger (data is Send data leave sensor) sent) over BLE * LED Purple * INITIALIZATION HRBO Get baseline muscle data - Read heart rate and for seconds blood oxygen level *LED Yellow* + LED Green T *RED Red* Yellow Button READING automatic Press Yellow Button (after 3 seconds) Reading muscle sensor data Press *LED Blue *