

## **Optical measurement**

### **SYLVAC-SCAN**

DESCRIPTION 52 REFLEX-CLICK

- Horizontal SCAN machine allowing to measure in the same position as the parts have been produced
- Robust construction with granite table for use in workshop or control laboratory
- Concept Reflex SCAN patented for measuring cylindrical workpieces without preprogramming
- Measurements performed in seconds by a single click
- Load the part, click the button and you get all the main values directly!
- Automatic recognition of recorded parts already measured
- Easy daily calibration thanks to the integrated master
- Quick return of investment









## **Optical measurement**

### **SYLVAC-SCAN**

### **DIMENSIONAL DRAWINGS**

52 REFLEX-CLICK





#### **TECHNICAL SPECIFICATIONS**

		902.5520		902.5521	
		Diameter	Length	Diameter	Length
Measuring range	mm	0.5 ÷ 52	300	0.5 ÷ 52	300
Resolution up to	mm	0.0001	0.0005	0.0001	0.0005
Max. error	μm	1.5 + D/100	4 + L/100	1.5 + D/100	4 + L/100
Repeatability	μm	0.6	2.5	0.6	2.5
Headstock		Non-Rotating headstock	for static measurements	Rotary headstock for static	and dynamic measurements
Max. weigth of part	kg		•	4	
Machine's weight	kg	103			

#### **BASIC INSTRUMENT**

- Instrument according to technical specifications
- 2 male centers
- Computer with screen, keyboard and mouse
- Windows 7 multilingual operating system
- Sylvac Reflex SCAN Software
- Manual



# **Optical measurement**

### **SYLVAC-SCAN**

**TECHNICAL SPECIFICATIONS** 

**SOFTWARES** 



THE PARTY NAMED IN COLUMN 1	FUNCTIONS			
	SYLVAC REFLEX SCAN 52	SYLVAC SCAN 25/50/50CE+/50+		
Automatic measurement of the main features (diameters, lenghts, angles, radius)	•			
Automatic parts / program recognition	•			
Off-line programming		•		
CAD import for programmation		•		
Reports editor	•	•		
Data export	•	•		
SPC basic calculations	•	•		
SPC software	On request	On request		
Access management - security lever	1	4		



#### **GEOMETRICAL TOLERANCING - FEATURES SUMMARY**

	SYLVAC REFLEX SCAN 52	SYLVAC SCAN 25/50/50CE+/50+
Diameters	•	•
Lenghts, heights, distances	•	•
Angles, chamfers	•	•
Radii	•	•
Threads (parallel)	•	•
Threads (root detail, taper, multi-starts, ball screws,		
worm screws, special threads)		•
Perpendicularity		•
Form deviation		•
2 and 3D alignment of the parts (axis correction)	•	•
Rotational diameters	Advanced	•
Run out	•	•
Concentricity	•	•
Roundness	•	•
Cylindricity	•	•
Across flats	•	•
Straightness	Advanced	•
Interrupted parts (splines, turbines)		•