

GOBI M350 Fieldbook — Equipment Checklist

APPN Aerial SOP — Locked revision 1.0

Equipment Checklist

Note

Ensure batteries for all equipment are fully charged before heading to the field. Ensure charging cables are available for necessary equipment.

- ☐ **Aircraft**
 - ☐ DJI M350
 - ☐ Aircraft batteries and spares
 - ☐ Landing gear
 - ☐ Landing pad
 - ☐ Spare parts
 - ☐ Tools
 - ☐ Logbook
 - ☐ **Radio Control Transmitter / Ground Control Station**
 - ☐ **GRYFN Gobi**
 - ☐ Gobi system (power once each month to charge the RGB camera internal battery)
 - ☐ Power cables, chargers
 - ☐ Ethernet cable (and dongle if needed)
 - ☐ SD card
 - ☐ *Capture* and *survey* polygon files
 - ☐ **Ground reference kit**
 - ☐ Reflectance calibration panels (11%, 30%, 56%, 82%)
 - ☐ Calibration validation panels (20%, 45%)
 - ☐ Ground control points and RTK GNSS system
 - ☐ 2 × folding tables to elevate panels
 - ☐ *If over 50 km from CORS base station*, a portable RTK base station ([link to GRYFN gitbook](#))
 - ☐ **Accessories**
 - ☐ Safety gear (signage and high-vis vests)
 - ☐ Aeronautical radio
 - ☐ Field laptop and spare batteries
 - ☐ External storage media
 - ☐ Water, food, esky, sunscreen, bug spray, first aid kit, etc.
 - ☐ Spirit bubble, spirit level (or angle measurement) and measuring tape
 - ☐ Portable fan (for cooling GOBI during data offload)
 - ☐ External power brick (for charging UAV RC)
-