Combination3.vi

File Edit Operate Tools Window Help

Controls | Help | Debug | NewPort Setup

Speed XY

4 ———————————————— 4000   `4000`

Speed Z

0.001 ———————————————— 1   `1`

Z

`7.02001`

Y

`8428`

X

`-356`

Move Mode
☑ Continuous

WASD->>XYStageControl
E/R->>Increase Z
Q/F->>Decrease Z

XY Movement
☐ Mirror for Microscope

ENTER YOUR NOTES HERE...

Position Display

Num	X	Y	Z
1	-356	4814	0.002381
2	-356	8428	7.020009

AssignedNUM
`2`

Select Position
`1`

Delete Position
`1`

Save/Update

Move to Saved Position

Delete

Count of Saved Positions
`2`

☐ AUTO

If Z>50, "Move" function will only make XY move!

Fresnel Rhomb Control

CONNECTED!

-    Move Relatively   +
     `45`

-    Move Relatively   +
     `20`

Deg. of Polarizer

-    Move Relatively   +
     `10`

Stop Rotation

Polarizer Clock

`0`

SetZero

EN   4:18 PM 8/8/2012