Aeris V9 ICU Ventilator - Quick Reference Guide

Alarm A-17 Low FiO2: delivered oxygen concentration is more than 5 percent below the set value for 30 seconds. Check the oxygen supply hose and wall pressure (must be 280 to 600 kPa). If the alarm persists, ventilate the patient with a manual resuscitator and replace the oxygen sensor.

Alarm A-22 High Airway Pressure: peak pressure exceeded the set limit (default 40 cmH2O). Check for kinked tubing, secretions or patient coughing.

Oxygen sensor calibration must be performed every 24 hours and after replacing the sensor. The internal battery provides 90 minutes of operation.