ECO#	DESCRIPTION	ORIGINATOR	WRITTEN		DISTRIB.	DATA ENTRY	INCORP
	NOISE VCC COUPLES RF MODULATOR DISTORTION OF VIDEO	J. SMITH	12/4/92	12/11/92	1/29/93	1/20/93	1/20/93
	ADD NEW TABULATED VALUE TO P/N: C070535-XXX	J. SMITH	12/18/92	1/8/93	1/29/93	1/21/93	1/21/93
	FCC REQUIRES TV TRANSFER SWITCH TO SHIPPED/SYSTEM	J. SMITH	1/27/93	1/28/93	1/29/93	1/29/93	1/29/93
	REVISED PACKOUT LANG DISK, INSTALL DISK & LABELS	J. SMITH	1/8/93	1/12/93	1/29/93	1/21/93	3/5/93
	PCB AND FCC EMISSION	J. SMITH	1/18/93	1/21/93	1/29/93	1/27/93	3/16/93
	ADD APPROVED VENDOR TO P/N: C303028-001	SONLY MU	1/15/93	1/15/93	1/29/93	1/21/93	1/29/93
	FRANCE WANTS TO START RECEIVING PAL B MACHINES	J. SMITH	1/25/93	1/28/93	1/28/93	1/29/93	2/10/93
	ACCESSORY PACK, READ ME CHANGE TO INTERNATIONAL	J. SMITH	1/27/93	1/29/93	1/29/93	2/1/93	2/12/93
	APPROVAL OF ALTERNATE COMP. SOURCE	J. SMITH	2/3/93	2/3/93	2/6/93	2/10/93	2/22/93
	FRANCE REQUESTED WORD REMOVED/LANDMINE PROG.	J. SMITH	2/3/93	2/3/93	2/6/93	2/10/93	3/5/93
	CHANGE TO THE DSP LOOPBACK CONNECTOR	J. SMITH	2/3/93	2/5/93	2/5/93	2/10/93	2/22/93
	BUG FIX / TOS 4.02 RELEASE	J. SMITH	2/3/93	2/3/93	2/5/93	2/10/93	3/8/93
	TO ADD CABLE PERITAL TO THE ASSY ACC PACK	J. SMITH	2/3/93	2/4/93	2/5/93	2/10/93	2/11/93
	TO REMOVE CONN SKT 44P PLCC SMT P/N C302967	SONGLY MU	2/11/93	2/23/93	2/24/93	2/24/93	3/16/93
	ASSY KEYBOARD FALCON030	J. SMITH	2/8/93	3/1/93	3/1/93	3/1/93	3/11/93
	6 LANG READ ME FIRST CARD TO INTERNATIONAL	J. SMITH	2/9/93	2/17/93	2/17/93	2/22/93	3/17/93
	6 LANG CALAPPT MAN. FILM/POLYBAG NOT LARGE ENOUGH	J. SMITH	2/9/93	2/17/93	2/17/93	2/23/93	3/17/93
	ADD DASH # C101901-010	SONGLY MU	2/11/93	2/17/93	2/17/93	2/23/93	3/26/93
	TO ADD APPROVAL OF 2ND VENDOR	SONGLY MU	2/11/93	2/17/93	2/17/93	2/23/93	3/22/93
	RELEASE OF MULTITOS 1.0	J.SMITH	2/18/93	2/19/93	2/19/93	2/23/93	3/22/93
	RELEASE OF SPEEDOGDOS	MELANIE U	3/23/93	3/30/93	3/30/93	4/1/93	4/20/93
	COST REDUCTION. CURRENT LENGTH EXCESSIVE	J. SMITH	2/24/93	3/1/93	3/1/93	3/2/93	3/22/93
	NEW PRODUCT COLOR REQUIRED BY MARKETING	J.SMITH	2/24/93	3/1/93	3/1/93	3/2/93	3/22/93
	BUG FIX. TOS 4.03 RELEASE	J.SMITH	3/1/93	3/1/93	3/1/93	3/2/93	3/15/93
	ADD ALTERNATE SOURCE /C302900-001	J. SMITH	3/5/93	3/12/93	3/12/93	3/15/93	3/26/93
	CORRECT ERROR MADE ON 1604/FERRITE BEAD	J. SMITH	3/8/93	3/9/93	3/9/93	3/11/93	3/29/93
	RELEASE OF GAL16V8 AND GAL20V8 CHIP	MELANIE U.	3/8/93	3/12/93	3/12/93	3/15/93	3/26/93
	ADD ALT. SOURCE/ C303004-001,C302942-001,C398112-030	MELANIE U.	3/9/93	3/12/93	3/12/93	3/15/93	3/26/93
	HDD INSULATOR/SPACER	J. SMITH	3/10/93	3/11/93	3/12/93	3/15/93	5/3/93
	TEST PROCEDURE /HDD FORMAT/HDD INSTALL	J. SMITH	3/11/93	3/12/93	3/12/93	3/16/93	3/15/93
	BUG FIX TOS 4.03 RELEASE TOS 4.04	MELANIE U.	3/11/93	3/12/93	3/12/93	3/15/93	3/15/93
	TRANSLATION CHG/CA401282-005 LANG DSK GER	MELANIE U	3/16/93	3/17/93	3/17/93	3/19/93	3/26/93
	FCC COMPLIANCE ON FAL030 MACHINES/SC1224 MONITORS	MELANIE U	3/17/93	3/19/93	3/19/93	4/1/93	5/3/93
	REVISE MULTITOS HDD/RELEASE MULTITOS FDD	MELANIE U.	3/18/93	3/18/93	3/18/93	4/1/93	WAITING FOR
	RELEASE OF FALCON030 4MB W/O HDD	MELANIE U.	3/22/93	3/30/93	3/30/93	4/1/93	5/3/93
	4MB RAM PCB FALCON030	J. SMITH	3/23/93	3/30/93	3/30/93	4/2/93	8/9/93
	APPROVED VENDORS VARIOUS IC CHIPS	MELANIE U.	3/23/93	3/30/93	3/30/93	4/2/93	5/17/93
	WRONG ACC PACK FOR ASSY SHPG/NETH-UK,NETH-FRA,SWF	MELANIE U.	3/23/93	3/30/93	3/30/93	4/6/93	5/18/93
	UPDATE IMPROPERLY ASSIGNED ATARI PART NUMBERS	MELANIE U.	3/31/93	4/1/93	4/1/93	4/1/93	6/25/93
	RELEASE MANUAL FOR SPEEDOGDSO MULTILINGUAL	MELANIE U.	3/31/93	4/6/93	4/6/93	4/6/93	5/27/93
	RELEASE 4MB WITH 80MB HDD FALCON030	MELANIE U.	3/31/93	3/31/93	3/31/93	4/6/93	6/29/93
	ITT CODEC	J SMITH	5/12/93	6/3/93	6/3/93	8/2/93	8/2/93

IMPROVE VIDEO QUALITY FOR NTSC MACHINES	MELANIE U.	4/13/93	4/14/93	4/15/93	4/18/93	7/29/93
SOUND CRACKLE DURING DMA PLAYBACK	J SMITH	4/16/93	4/20/93	4/20/93	4/21/93	7/29/93
RELEASE 4-LAYER F030 PCB	J SMITH	5/12/93	6/3/93	6/3/93	6/3/93	6/29/93
CONNER CP 2088/FAILURES	J SMITH	4/20/93	4/23/93	4/29/93	8/2/93	8/2/93
SPEEDOGDOS CHANGES/ REVISED DISKS	J SMITH	4/21/93	4/23/93	4/29/93	7/8/93	7/8/93
OLD INSULATOR DIFFICULT TO INSTALL/SAFETY COVERAGE	MELANIE U.	4/22/93	4/23/93	4/23/93	6/21/93	6/29/30
RELEASE DRAM TEST PROCEDURE	MELANIE U.	4/19/93	4/20/93	4/20/93	4/21/93	7/30/93
FALCON030 CALLS OUT WRONG FRENCH WARRANTY CARD	J. SMITH	5/14/93	6/2/93	6/2/93	7/7/93	7/7/93
RELEASE ATARIWORKS FOR PACKOUT IN USA VERSION FAL030	J. SMITH	5/18/93	6/2/93	6/2/93	8/2/93	8/3/93
RELEASE MULTILINGUAL MULTITOS MANUAL	J. SMITH	5/14/93	Jun-93	6/3/93	6/7/93	8/3/93
ADD PATENT LABEL	J. SMITH	5/20/93	6/2/93	6/2/93	6/21/93	6/29/93
302624-004 (74HC04)	J. SMITH	6/1/93				
C303237 FACTORY UTILITIES DISK	J.SMITH	6/29/93	7/8/93			
MULTITOS SW	G.LEBREC	7/7/93				
SPEEDDOS	G.LEBREC	7/7/93				
LANGUAGE S/W	G.LEBREC	7/7/93				
500129-001 FACTORY/ATARI WKSINSTALL INS	J.SMITH	7/8/93				
FALCON PCBA,CA401332/700015,FO30	J.SMITH	7/8/93				
REL EXTRA PROGRAMS F030 FDD,700039/HDD,700040	G.LEBREC/JS	7/22/93				
SHIELD CONTACT HDD FAL030	J.SMITH	7/27/93				

DOCUMENTS, FILM DISKETTE'S, ROM'S	STARTING	IMPLMT	STARTING	IMPLMT	STARTING	IMPLMT
DISTRIBUTED	SERIAL#	STATUS	SERIAL #	STATUS	SERIAL #	STATUS
1/29/93	UK B32C0220000080	12/10/92	GER B331023000311	1/1/93	USA B332021000051	2/4/93
1/29/93						
1/29/93						
DSK 1/29 DOC 3/15/93	UK B332022000206	2/4/93	GER B33203000462	2/4/93	USA B33202100051	2/4/93
3/18/93						
1/29/93						
2/24/93	FRA Y432024001001	2/27/93				
2/24/93						
2/24/93						
DSK 2/5 DOC 3/15/93	FRA Y432024001001	2/27/93				
DSK 2/5 DOC 2/24/93	UK Y432022001135	2/25/93	GER Y432023001774	2/24/93	FRA Y432024001001	2/27/93
DSK 2/5 DOC 3/15/93	UK Y432022001135	2/25/93	GER Y432023001774	2/24/93	FRA Y432024001001	2/27/93
2/24/93	FRA Y432024001001	2/27/93				
3/18/93						
3/15/93						
3/18/93	UK Y432022001015	2/23/93	GER Y432023001700	2/23/93	AUS Y432022001001	2/23/93
3/18/93	UK Y432022001015	2/23/93	FRA Y432024001001	2/23/93		
3/29/93						
3/29/93						
DSK 2/9 DOC 3/29/93	REPLACED BY ECO 1633					
DSK ONLY 2/9/93	UK: Y434022001959	4/9/93	GER: Y434023002101	4/9/93	USA: Y434021000001	4/9/93
3/29/93	0.00.0000000000000000000000000000000000	., .,				
3/29/93	REPLACED BY ECO 1630					
3/18/93						
3/29/93						
5/7/93	USA: Y434021000001	4/9/93				
3/29/93	33, 11 10 102 1000001	1,0,00				
3/29/93						
5/7/93	FRA: Y432024001105	3/1/93	GER: Y432023001820	3/1/93	USA: Y434021000001	3/1/93
3/17/93	FRA: Y434024001951-1990	4/9/93	GER: Y434023002101	4/9/93	USA: Y434021000001	4/9/93
3/18/93	FRA: Y434024002608	4/17/93	USA: Y43402100151	4/17/93	UK: YY434022002168	4/17/93
DSK 3/18 DOC 3/29/93	1101.1101021002000	1717700	00/1. 1 10 102 100 101	1717700	O10. 11 10 1022002 100	1717700
5/14/93						
R REPLY FROM HL LEE	UK Y434022001959	4/9/93	GER Y434023002101	4/9/93	RA Y434024001951-199	4/9/93
5/14/93	01(1101022001000	1,0,00	<u> </u>	1, 0, 00	1411101021001001100	1,0,00
5, 7, 17, 00						
8/3/93						
7/7/93						
7/2/93						
7/7/93	USA Y434021000151	4/21/93				
7/2/93	UK Y434022002127	4/9/93	FRA Y434024002566	4/9/93	GER Y434023002221	4/9/93
8/6/93	011110102121	., 5, 55		., 3, 30	22.1.1.0.020002221	., 5, 50
8/6/93					l	

7/29/93	USA Y434021000001			
7/2/93				
8/6/93				
7/7/93				
7/12/93				
8/6/93				
8/6/93				
7/2/93				

STARTING SERIAL #	IMPLMT STATUS	STARTING SERIAL #	IMPLMT STATUS	STARTING SERIAL#	IMPLMT STATUS	STARTING SERIAL#	IMPLMT STATUS
FRA B332014000100	2/4/93						
FRA Y432024001001	2/23/93						
FRA: Y434024001951-1990	4/9/93	FRA: Y434024002496	4/9/93	ITA Y434023000001	4/9/93	BEN: Y434022002191	4/9/93
UK: Y432022001215 UK: Y434022001959 ITA: YY434023000001	3/1/93 4/9/93 4/17/93	BEN: Y432022001215 BEN: Y434022002191	3/1/93 4/9/93	ITA: Y434023000001 ITA: Y434023000001	3/1/93 4/9/93	FRA: Y434024002496	4/9/93
USA Y434021000001	4/9/93	BEN Y434022002191	4/9/93	ITA Y434023000001	4/9/93	FRA Y434024002496	4/9/93
USA Y434021000151	4/9/93	ITA Y434023000001	4/9/93	BEN Y434022002191	4/9/93		