

Triage Examples

Four worked examples showing the expected classification format. These use equipment IDs not present in the 14-case dataset, so they demonstrate format and reasoning style without supplying answers to any evaluation case.

Example 1 — Straightforward, Critical

EQ-101 · Ventilator · ICU

Report

Reported problem: Ventilator stopped delivering ventilation during use and displayed a system alarm. Staff attempted the documented basic restart procedure, but the alarm returned. Clinical context: patient is fully ventilator-dependent and currently receiving mechanical ventilation. Equipment status: stopped, alarm active. Immediate action taken: restart attempted once. Patient impact observed: manual bagging initiated by nursing staff.

Expected classification

Equipment type	Ventilator
Issue type	Malfunction / alarm fault
Urgency	Critical
Assigned team	Biomedical Engineering
Confidence	High
Reason	Device stopped delivering ventilation to a fully dependent patient and a restart did not resolve the fault; manual bagging is already in progress, meeting the policy's Critical definition directly.

Example 2 — Straightforward, Medium

EQ-102 · Infusion Pump · Medical Ward

Report

Reported problem: Infusion pump display shows a low-battery warning intermittently while still connected to mains power. Clinical context: pump is running a scheduled non-urgent IV fluid infusion. Equipment status: in service, warning intermittent. Immediate action taken: mains connection checked and confirmed secure. Patient impact observed: none; infusion has not been interrupted.

Expected classification

Equipment type	Infusion Pump
Issue type	Power supply / battery fault
Urgency	Medium
Assigned team	Biomedical Engineering
Confidence	Medium-High
Reason	The infusion itself is unaffected and the patient is not in a time-critical situation, but an unresolved battery warning while on mains power is a reliability concern that should be checked within the working shift rather than left to routine scheduling.

Example 3 — Insufficient information (flagged, not guessed)

EQ-103 · Patient Monitor · Ward

Report

Reported problem: Monitor is not working properly. Clinical context: not provided. Equipment status: not specified. Immediate action taken: not specified. Patient impact observed: not specified.

Expected classification

Equipment type	Patient Monitor
Issue type	Unable to determine from information provided
Urgency	Provisionally High, pending confirmation
Assigned team	Biomedical Engineering (pending confirmation)
Confidence	Low
Reason	No clinical context, equipment status, or observed patient impact is provided. A patient monitor fault is provisionally treated as High pending more information, per policy Section 4, rather than assigning a specific issue type or a lower urgency that is not supported by evidence.
Missing information	Clinical context; current equipment status; whether a patient is currently connected to the monitor; any action already taken.

Example 4 — Vendor escalation routing

EQ-104 · Laboratory Analyzer · Laboratory

Report

Reported problem: Analyzer has failed its scheduled calibration verification twice in a row, with results outside the manufacturer's acceptable range. Clinical context: routine calibration check, no patient samples affected. Equipment status: taken out of service pending calibration. Immediate action taken: repeat calibration attempted once in-house with no change. Patient impact observed: none; backup analyzer in use.

Expected classification

Equipment type	Laboratory Analyzer
Issue type	Calibration failure
Urgency	Medium
Assigned team	Vendor Escalation
Confidence	High
Reason	Repeated calibration failure outside manufacturer tolerance is beyond in-house biomedical engineering scope per policy Section 3, and no patient impact makes this Medium rather than Critical or High; a backup analyzer is already covering the workload.