




#### $M \subset \bigcup$




USB









# CAN-2



### MCU connectors



### Gyro Sensor



## <u>UART selector</u>

MCU-BLE	USB-BLE
JP3 SolderJumper_2_Open	JP7 SolderJumper_2_Open
USART1_RTS BLE_UART_CTS	SERIAL_RTS BLE_UART_CTS
JP4 SolderJumper_2_Open	JP8 SolderJumper_2_Open
BLE_UART_RTS USART1_CTS	BLE_UART_RTS SERIAL_CTS
JP5 SolderJumper_2_Open	JP9 SolderJumper_2_Open
USART1_TX BLE_UART_RX	SERIAL_TX BLE_UART_RX
JP6 SolderJumper_2_Open	JP10 SolderJumper_2_Open
BLE_UART_TX USART1_RX	BLE_UART_TX SERIAL_RX

				F
Gento Aiba (GN:	10)			
Sheet: / File: GN10Mainboard.kicad_sch				
Title: GN10Mainboard				
Size: A2	Date:			Rev: v1.0
KiCad E.D.A. 8.0	.7			ld: 1/1