




$M \subset \bigcup$




USB







CAN-2



MCU connectors



Jyro Sensor



<u>UART selector</u>

MCU-BLE	USB-BLE	
JP3 SolderJumper_2_Open USART1_RTS BLE_UART_CTS	JP7 SolderJumper_2_Open SERIAL_RTS \ BLE_UART_CTS \	
JP4 SolderJumper_2_Open	JP8 SolderJumper_2_Open	
BLE_UART_RTS USART1_CTS JP5 SolderJumper_2_Open	BLE_UART_RTS SERIAL_CTS JP9 SolderJumper_2_Open	
USART1_TX DEBLE_UART_RX JP6	SERIAL_TX BLE_UART_RX JP10	
SolderJumper_2_Open BLE_UART_TX USART1_RX	SolderJumper_2_Open BLE_UART_TX SERIAL_RX	

Gento Aiba (GN1	0)		ı
Sheet: / File: GN10Mainboard.kicad_sch			
Title: GN10Mainboard			
Size: A2	Date:		Rev: v1.0
KiCad E.D.A. 8.0.7		ld: 1/1	