
## Oil systems



Loss rate ratio versus activity factor ratio for 3 oil system productivity tranches (Tranches are organized low to high, from left to right) Activity factor ratio of other equipment held constant at:

- $\Diamond$  AFR = 0.5
- AFR = 1
- AFR = 2