
## Gas systems



Loss rate ratio versus activity factor ratio for 3 gas system productivity tranches (productivity tranches are organized low to high, from left to right).

Activity factor ratio of other equipment held constant at:

- $\Diamond$  AFR = 0.5
- AFR = 1
- AFR = 2

Regression generated loss rate ratio