



Product catalogue

Custom Angle Heads

Reach a different face or angle of the part with an angle head configured around the application, the machine and the spindle taper.



In this catalogue

1. What an angle head does
2. The range
3. Ordering code and examples
4. Enquiry and contact

Products by

DIXI

What an angle head does

Machine where the spindle cannot reach

An angle head turns the drive from the machine spindle through an angle, so the tool can work on side faces, inside cavities and at compound angles without re-clamping the part or moving it to another machine.



Reach side faces

Drill, tap and mill faces at 90° to the spindle in the same setup.



Work at set angles

Heads built for a fixed angle such as 25° or 45°, to suit the feature.



Built to the job

Housing, gearing, mounting and coolant chosen for the application.

The range

Custom-built angle heads

Example	Description
BT50 slim angle head	Slim body for reaching into deep or narrow features
BT50 45-degree A-head	Output at 45° to the spindle axis
BT50-685 GPL anti-vibratory angle head	Anti-vibratory design
HSK100 25-degree A-head	HSK100 drive with output at 25°

Examples from the DIXI custom-built range. Each head is configured to the application.

Ordering code

How a custom head is specified

A custom-built angle head is defined by an ordering code of the form CBH X-XX-X-X-X-X-X. Each position records one decision about the head.

Position	Defines
X	Drive spindle taper (machine side)
XX	Output spindle taper (tool side)
X	Machine mounting
X	Material of construction (MOC) of the housing
X	Custom design description
X	Type of spiral bevel gear
X	Coolant type

Examples

Heads built for specific jobs



BT50 slim angle head



BT50 45-degree A-head



BT50-685 GPL anti-vibratory angle head



HSK100 25-degree A-head

What we need to configure your head. The machine and spindle taper, how the head will be mounted and located on the machine, the output angle and reach, the tool interface, the operation and its cutting loads, and how coolant should reach the tool. A drawing of the component with the feature marked is the fastest way to a correct proposal.

To quote quickly, send us

- ☐ Machine make, model and spindle taper
- ☐ Mounting and stop-block position on the machine
- ☐ Required output angle and reach
- ☐ Tool interface on the output side
- ☐ Operation, tool size and cutting data
- ☐ Coolant requirement
- ☐ Component drawing with the feature marked

Related SHK catalogues

Tool Holders & Pull Studs

BT, BBT and HSK holders; pull studs for all common standards

Rotary & Tilting Tables

Rotary tables, tilting tables and support tailstocks

CAM / Programming

SolidCAM for milling, turning and multi-axis work

How we work

From selection to support

01

Select

We review the part, the machine and the problem, and recommend the right product.

02

Supply

Equipment from established manufacturers, configured for your machine.

03

Install

Support with mounting, integration and first use on your shop floor.

04

Support

Service, spares and help when production needs change.

Start with the problem

Tell us what the machine or the part needs. We work back from the problem to the product, not the other way round.

One partner around the machine

Workholding, tooling, probing, chip and coolant handling, and machine services from one engineering team.

Established manufacturers

Products from specialist manufacturers, selected and supported locally from Bengaluru.

Talk to an engineer

Send a drawing, a photo of the machine or a short description of the problem. We will come back with the right solution.

Contact

Shrinivas M
Director, Business
Development
+91 86600 36390 (call /
WhatsApp)
shktechservices@gmail.com

Visit

SHK Tech Services
No. 46, 2nd Floor, 14th Cross Road,
2nd Stage Peenya,
Opp. CLAAS Agricultural
Machinery Pvt. Ltd., Bengaluru
560058
shktech.in