



Product catalogue

Measuring & Test Equipment

Granite plates, clamp force gauges, ATC alignment gauges and test arbors for checking and maintaining machine tools in the shop.




In this catalogue

1. Granite plates
2. Clamp force gauges
3. ATC alignment gauges
4. Test arbors
5. Enquiry and contact

Granite plates for testing

A stable reference surface

Granite is stable, does not rust and holds its flatness, which makes it the standard reference for inspection and machine checking.



Range

- Granite surface plates
- Surface plate stands
- Granite squares
- Granite parallels
- Plates with dial stand for comparative measurement

Clamp force gauges

Check the spindle drawbar

A worn drawbar or weak disc springs reduce the force holding the tool in the spindle, which affects finish, accuracy and safety. A clamp force gauge measures it directly in the spindle.



Use it to

- Check drawbar clamping force as part of preventive maintenance
- Confirm the result after spindle or drawbar service
- Investigate tool pull-out, chatter or poor finish

ATC alignment gauges

BT · BBT · HSK

Falcon ATC alignment gauges are used to align the automatic tool changer arm with the spindle, so tools are changed smoothly without damage to the tool holder or spindle.



ATC alignment tool parts: cat flange adapter, 40 taper, bushing and centre pin

Test arbors

Spindle and alignment checks



Test arbors are used with a dial indicator to check spindle runout and the alignment of the spindle to the machine axes.

See the SHK Machine Services catalogue for calibration and alignment services.

To quote quickly, send us

- ☐ Equipment required
- ☐ Spindle taper and size, for gauges and arbors
- ☐ Plate size and grade, for granite
- ☐ Machine make and model
- ☐ Quantity

Related SHK catalogues

Machine Services

Calibration, reconditioning and retrofit

Tool Holders & Pull Studs

BT, BBT and HSK holders; pull studs for all common standards

Probing & Tool Breakage

Touch probes, tool setting and breakage detection

How we work

From selection to support

01 Select We review the part, the machine and the problem, and recommend the right product.	02 Supply Equipment from established manufacturers, configured for your machine.	03 Install Support with mounting, integration and first use on your shop floor.	04 Support Service, spares and help when production needs change.
---	--	---	---

Start with the problem

Tell us what the machine or the part needs. We work back from the problem to the product, not the other way round.

One partner around the machine

Workholding, tooling, probing, chip and coolant handling, and machine services from one engineering team.

Established manufacturers

Products from specialist manufacturers, selected and supported locally from Bengaluru.

Talk to an engineer

Send a drawing, a photo of the machine or a short description of the problem. We will come back with the right solution.

Contact

Shrinivas M
Director, Business
Development
+91 86600 36390 (call /
WhatsApp)
shktechservices@gmail.com

Visit

SHK Tech Services
No. 46, 2nd Floor, 14th Cross Road,
2nd Stage Peenya,
Opp. CLAAS Agricultural
Machinery Pvt. Ltd., Bengaluru
560058
shktech.in