

FIRST NOTICE OF LOSS

FNOL Reference No.: CLM-2025-TN-00187 | Date of Filing: 07 February 2025 | Intake Channel: Online Self-Service Portal

SECTION 1 — POLICY INFORMATION

Policy Number	PAP-2023-TN-88210
Policyholder Name	Kavitha Subramanian
Policy Effective Date	01 April 2024
Policy Expiry Date	31 March 2025
Agent / Branch	Thiruvannmiyur Branch, Chennai — Agent ID: AG-0341
Coverage Type	Private Motor — Own Damage (OD) + Third-Party Liability (TPL)
No-Claim Bonus (NCB)	25 % applicable; no prior claims on this policy
Sum Insured	INR 7,20,000 (Insured Declared Value as at renewal)

SECTION 2 — INCIDENT INFORMATION

Date of Incident	05 February 2025
Time of Incident	07:20 AM
Location	ECR Road, near Injambakkam Signal, Chennai — TN 600115
GPS Co-ordinates	12.9121° N, 80.2573° E
Weather Conditions	Light drizzle; reduced visibility; road surface wet and slippery
Incident Description	The insured vehicle skidded on a wet section of ECR Road and made minor contact with a roadside concrete curb. The skid occurred after the vehicle passed over standing water near a partially blocked storm drain. No other vehicles, pedestrians, or structures were involved. The insured pulled over safely, activated hazard lights, photographed the damage, and called the 24x7 claims helpline at 07:35 AM. The vehicle remained fully drivable and was driven to the insured's residence.

SECTION 3 — INVOLVED PARTIES

Claimant Name	Kavitha Subramanian
Relationship to PH	Self — Policyholder is the driver
Date of Birth	14 August 1988
Driving Licence No.	TN-09-2010-0034521 (Valid to 13 August 2028)
Contact Number	+91 98410 77234
Email Address	kavitha.s88@gmail.com
Third Parties Involved	None — single-vehicle incident
Injuries Reported	None; insured confirms no physical harm to self or others
Police Report	Not filed — no third-party involvement; not required under policy terms

SECTION 4 — ASSET DETAILS

Asset Type	Private Motor Vehicle
Make / Model / Year	Maruti Suzuki Swift VXi Petrol, 2022
Registration Number	TN-09-CC-5523
Chassis Number	MA3FJEB1S00123456

Engine Number	K12MNA456789
Odometer Reading	22,400 km at time of incident
Damage Description	Left front alloy wheel rim scuffed and bent; left-side door sill cladding cracked; minor paint scrape on left front quarter panel. No structural, engine, or transmission damage observed.
Vehicle Drivable?	Yes — driven home after incident without further issues
Estimated Repair Cost	INR 18,500 (preliminary quote: Maruti True Value, ECR Road — includes alloy refurbishment, sill cladding replacement, paint touch-up)
Workshop	Maruti True Value Authorised Service Centre, ECR Road, Chennai
Photographs Taken	6 photographs captured via mobile app — Ref: IMG-2025-FT-001-A to F

SECTION 5 — CLAIM DETAILS & ATTACHMENTS

Claim Type	Motor Vehicle — Own Damage (Single Vehicle, Non-Collision Skid)
Claim Sub-Type	Accidental External Damage
Initial Estimate	INR 18,500
Surveyor Required	To be determined by claims desk; vehicle is drivable
Cashless / Reimb.	Cashless preferred — workshop is network garage
Documents Submitted	[1] Driving Licence — front and back (DL_KavithaSub_TN09.pdf) [2] Vehicle Registration Certificate (RC_TN09CC5523.pdf) [3] Insurance Policy Certificate (Cert_PAP2023TN88210.pdf) [4] Workshop Repair Estimate on letterhead (Est_MarutiTrueValue_Feb25.pdf) [5] Six accident photographs — IMG-2025-FT-001-A.jpg through IMG-2025-FT-001-F.jpg

SECTION 6 — DECLARATION

I, Kavitha Subramanian, hereby declare that all information provided in this First Notice of Loss is true, complete, and accurate to the best of my knowledge and belief. I understand that any false or misleading statement may result in rejection of this claim, cancellation of my policy, and legal action as applicable under the Insurance Act.

Claimant Signature	Kavitha Subramanian (e-signed via OTP authentication — Ref: ESIGN-20250207-4421)
Date of Declaration	07 February 2025
Claims Handler	Assigned — Online Portal Auto-Reference