Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Accessories

Addmix SF

Cold-Drawn Steel Fibres
for Concrete Reinforcement



Product Description

Addmix SF is a range of cold-drawn steel fibres (AISI 1010) for reinforcing concrete. Available as corrugated round, corrugated segmented and end-hooked fibres, they improve crack control, toughness and impact resistance.

Uses

- Industrial floors and warehouses.
- Roads and pavements.
- Shotcrete.
- Precast elements.

Advantages

- High tensile strength up to 1100 N/mm².
- Improves toughness and crack control.
- Three fibre types.
- Uniform distribution.
- Reduces mesh installation time.

Application

1. **Mix Design**
   Set fibre type and dosage in the approved mix design.
2. **Dosing**
   Add fibres gradually with the aggregates or to the truck mixer.
3. **Mixing**
   Mix to uniform distribution, avoiding balling.

Consumption

As per design
per m³ of concrete
Dosage set by the structural design.

Packaging

20 kg and 25 kg cartons; 800 × 1200 pallets; approx. 25 t per 40 ft container.

Storage & Shelf Life

Store dry and covered to prevent rusting.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Material	Cold-drawn wire, AISI 1010	—
Corrugated round	50 mm × 1.0 mm, L/D 50, 2800 pcs/kg, 1100 N/mm²	—
Corrugated segmented	50 mm, 2100 pcs/kg, 700 N/mm²	—
End-hooked	35 mm × 0.8 mm, L/D 43.75, 7200 pcs/kg, 1100 N/mm²	—

Consumption

Type	Length	Tensile strength
Corrugated round	50 mm	1100 N/mm²
Corrugated segmented	50 mm	700 N/mm²
End-hooked	35 mm	1100 N/mm²

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Use the approved fibre type and dosage.
- Add gradually to avoid balling.

Application Notes

- Add fibres gradually to avoid balling.
- Use a superplasticiser to keep workability.
- Finish floors with power floats to bury fibres.

Health & Safety

- Wear gloves, safety goggles and a dust mask when mixing.
- Contains cement; alkaline when wet. Avoid skin and eye contact.
- Avoid inhaling dust.

First Aid & Cleaning

- Eyes: rinse immediately with plenty of clean water for at least 15 minutes and seek medical advice.
- Skin: wash with soap and water; cement is alkaline when wet.
- Inhalation of dust: move to fresh air.
- Ingestion: rinse mouth and seek medical advice.
- Clean equipment with water.

The information in this datasheet is based on laboratory tests and practical experience and is given in good faith. Users should verify product suitability for their specific application. O MIX reserves the right to update this information without prior notice.