Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Accessories

Conducto Tape

Self-Adhesive Copper Tape
for ESD Floor Grounding



Product Description

Conducto Tape is a self-adhesive conductive copper tape for electrostatic-dissipative (ESD) and conductive floor systems. It is installed as a grid under the conductive primer and ESD coating and connected to earth points to dissipate static electricity safely.

Uses

- Grounding grid under conductive and ESD epoxy floors.
- Electronics production and assembly areas.
- Data centres and server rooms.
- Laboratories, clean rooms and pharmaceutical areas.
- Areas with explosive or sensitive materials.

Advantages

- Excellent electrical conductivity.
- Self-adhesive, easy installation.
- Forms a continuous grounding grid.
- Thin profile: 0.05 – 0.08 mm.
- Compatible with conductive primers and ESD coatings.

Application

1. **Layout**
   Mark the grid lines and earth-point positions on the primed, clean floor.
2. **Installation**
   Remove the liner and press the tape firmly along the lines; connect the grid to earth points.
3. **Coating**
   Apply the conductive primer and the ESD coating over the grid; test resistance.

Consumption

As per grid layout
grid spacing as per ESD floor design
Grid spacing and earth points as per the ESD floor design.

Packaging

Rolls of 20 m or 50 m; standard width 20 mm (10 – 25 mm available).

Storage & Shelf Life

Store in original packaging in a dry place at room temperature, away from moisture.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Material	Copper foil with conductive adhesive	—
Thickness	0.05 – 0.08 mm	—
Width	10 – 25 mm (standard 20 mm)	—
Roll length	20 m or 50 m	—
Function	Grounding grid for ESD / conductive floors	—

Consumption

Item	Requirement
Grid layout	As per ESD floor design
Connection to earth	At designed earth points
Joints	Overlap and press firmly

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Install on a clean, dry, primed surface.
- Press firmly for full adhesion along the whole length.
- Connect the grid to earth points as per the design.
- Check continuity before applying the conductive primer.

Application Notes

- Install straight runs and form junctions by overlapping tape ends.
- Avoid wrinkles and air pockets.
- Leave tails at earth points for connection by an electrician.
- Measure resistance of the finished floor as per the project specification.

Health & Safety

- Copper edges are sharp; wear cut-resistant gloves.
- Electrical connections to earth must be made by a qualified electrician.

First Aid & Cleaning

- Cuts: clean and dress the wound.
- Eyes: rinse with clean water if particles enter.
- Skin: wash with soap and water.
- Collect off-cuts and liners in waste bins.

The information in this datasheet is based on laboratory tests and practical experience and is given in good faith. Users should verify product suitability for their specific application. O MIX reserves the right to update this information without prior notice.