Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Accessories

Fiberlock

Woven Fiberglass Fabric
ECR-Grade Glass Fibres



Product Description

Fiberlock is a high-quality woven fiberglass fabric made from ECR-grade glass fibres. It resists high temperatures up to 550 °C, offers excellent thermal and electrical insulation, and is strong yet lightweight and flexible.

Uses

- Pipe and equipment insulation.
- Exhaust system wrapping.
- Welding blankets and curtains.
- Furnace, kiln and boiler linings.
- Fire protection and expansion joints in structures.
- Marine and offshore applications; reinforcement layer in composites.

Advantages

- High temperature resistance up to 550 °C.
- Excellent thermal and electrical insulation.
- High tensile strength, durable weave.
- Lightweight; easy to handle, cut and install.
- Resistant to most chemicals, oils and solvents.

Application

1. **Preparation**
   Clean the surface or item to be wrapped; measure and cut the fabric to size.
2. **Installation**
   Wrap or lay the fabric with the specified overlaps; secure with wire, pins or adhesive as required.
3. **Finishing**
   Cover or coat as specified for the system; inspect overlaps and fixings.

Consumption

1 m² per m²
per layer, plus overlaps
Allow extra for overlaps and wrapping.

Packaging

Rolls 1 m wide × 50 m long.

Storage & Shelf Life

Store in original packaging in a dry place, away from moisture and mechanical damage.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Material	Woven ECR-glass fibre fabric	—
Colour	White	—
Temperature resistance	up to 550 °C	—
Thicknesses	0.125 / 0.175 / 0.4 / 0.8 / 1.5 / 3.0 mm	—
Roll size	1 m × 50 m	—
Properties	Thermal and electrical insulation; chemical resistant	—

Consumption

Thickness	Typical use
0.125 – 0.175 mm	Composite reinforcement, light wrapping
0.4 – 0.8 mm	Pipe and exhaust wrapping, cable insulation
1.5 – 3.0 mm	Welding blankets, furnace and fire-protection uses

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Install on clean, dry surfaces.
- Overlap adjacent pieces as specified for the use.
- Secure against wind and movement.
- Cut with sharp scissors or knives to avoid fraying.

Application Notes

- Select thickness according to temperature and mechanical exposure.
- Overlap joints and wrap spirally on pipes.
- Fix with stainless-steel wire, pins or high-temperature adhesive as specified.
- Seal cut edges where fraying must be avoided.

Health & Safety

- Glass fibres may irritate skin and eyes; wear gloves, long sleeves and safety goggles.
- Use a dust mask when cutting.
- Wash skin after handling.

First Aid & Cleaning

- Eyes: rinse with clean water; do not rub.
- Skin: wash with cool water and soap.
- Inhalation: move to fresh air.
- Collect off-cuts and fibres with a vacuum.

The information in this datasheet is based on laboratory tests and practical experience and is given in good faith. Users should verify product suitability for their specific application. O MIX reserves the right to update this information without prior notice.