Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Accessories



Terra Flakes

Decorative Vinyl Flakes
for Epoxy & PU Floors

Product Description

Terra Flakes are coloured decorative vinyl flakes broadcast into epoxy and polyurethane floor coatings. They create a decorative, granite-like finish that hides minor defects and improves abrasion and slip resistance. Colours and blends are available on request.

Uses

- Residential garages and car showrooms.
- Shops, corridors and walkways.
- Industrial and commercial decorative floors.
- Pharmaceutical and clean areas with decorative requirements.
- Terra Flakes floor system with O-Mix SL and clear top coat.

Advantages

- Decorative, granite-like appearance.
- Hides minor surface defects.
- Improves abrasion resistance.
- Custom colours and blends.
- Long shelf life: 24 months.

Application

1. **Base Coat**
   Apply the O MIX epoxy or self-levelling base coat as specified.
2. **Broadcast**
   Broadcast Terra Flakes into the wet coat to the specified coverage (partial or full).
3. **Top Coat**
   After curing, remove loose flakes, scrape lightly and seal with a clear top coat.

Consumption

10 – 40 %
of base-coat weight, per required coverage
Full broadcast uses the higher rate.

Packaging

20 kg bags.

Storage & Shelf Life

24 months in original, closed packaging. Store dry, away from heat and direct sunlight.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Material	Pigmented vinyl flakes	—
Density	1.4 – 1.6 g/cm³	—
Addition rate	10 – 40 % by weight of base coat	—
Colours	Standard blends; custom on request	—
Compatible systems	Epoxy and polyurethane floor coatings	—
Shelf life	24 months	—

Consumption

Finish	Addition rate
Partial (random) broadcast	from 10 %
Full broadcast (to refusal)	up to 40 %

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Broadcast into the base coat while it is still wet.
- Use one colour batch per area.
- Remove all loose flakes before the top coat.
- Base and top coat conditions as per their datasheets.

Application Notes

- Broadcast by hand or blower in an even, upward throw so flakes fall naturally.
- For full broadcast, apply until refusal.
- After curing, scrape and vacuum loose flakes.
- Seal with a clear top coat for a smooth, cleanable surface.

Health & Safety

- Wear a dust mask when blowing flakes.
- Avoid inhalation of fine particles.
- Follow the safety instructions of the base and top coats.

First Aid & Cleaning

- Eyes: rinse with clean water.
- Inhalation: move to fresh air.
- Skin: wash with soap and water.
- Clean tools with a dry brush and vacuum.

The information in this datasheet is based on laboratory tests and practical experience and is given in good faith. Users should verify product suitability for their specific application. O MIX reserves the right to update this information without prior notice.