Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Protective Coating

Freezo Coat

Solvent-Free Two-Component PU Coating for Cold Rooms



Product Description

Freezo Coat is a highly flexible, solvent-free, two-component polyurethane coating for cold rooms and freezers. It has better adhesion than epoxy at low temperatures, acts as a flexible barrier against thermal cracking, and resists abrasion, chemicals and UV. Service range -35 °C to +150 °C.

Uses

- Cold rooms and freezers.
- Food and pharmaceutical plants.
- Industrial floors.
- Roofs and decks.

Advantages

- Service -35 °C to +150 °C.
- Highly flexible; resists thermal cracking.
- Solvent-free, VOC 0.
- Excellent adhesion.
- Abrasion, chemical and UV resistant.

Application

1. **Surface Preparation**
   Concrete ≥ 28 days, moisture < 4 %; prime with O-Prime SF and fill with O-Putty.
2. **Mixing**
   Stir Part A 30 s, add Part B (3 : 1 by weight) and mix 1 min; thin 5 – 10 % if required.
3. **Application**
   Apply by roller or squeegee at 0.2 – 0.3 kg/m² per 100 µm.

Consumption

0.2 – 0.3 kg/m²
per 100 µm
0.5 kg/m² as top coat in the Freezo system.

Packaging

20 kg sets (15 kg A + 5 kg B) and 5 kg sets (3.75 kg + 1.25 kg).

Storage & Shelf Life

12 months in original, unopened packaging. Store dry at +5 °C to +35 °C, away from direct sunlight.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Mixing ratio (A : B)	3 : 1 by weight	—
Solids content	99 %	—
VOC	0	—
Pot life	40 – 60 min	—
Tensile strength	40 – 50 N/mm²	—
Service temperature	-35 °C to +150 °C	—
Colours	Various	—

Consumption

Layer	Product	Consumption
Primer	O-Prime SF	0.10 – 0.15 kg/m²
Filling	O-Putty	0.25 – 0.30 kg/m²
Top coat	Freezo Coat	0.5 kg/m²

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Ambient and substrate temperature: +10 °C to +35 °C.
- Relative humidity: max. 90 %.
- Substrate moisture: < 4 %; concrete ≥ 28 days.

Application Notes

- Mix complete sets at 3 : 1 by weight.
- Thin 5 – 10 % only if required.
- Relative humidity max. 90 % during application.
- Allow full cure before lowering the room temperature.

Health & Safety

- Wear chemical-resistant gloves, safety goggles and overalls.
- Uncured resin may cause skin sensitisation; avoid skin and eye contact.
- Ensure good ventilation in enclosed areas.

First Aid & Cleaning

- Eyes: rinse immediately with plenty of clean water for at least 15 minutes and seek medical advice.
- Skin: remove contaminated clothing and wash with soap and water; do not use solvents on skin.
- Inhalation: move to fresh air; seek medical advice if symptoms persist.
- Ingestion: do not induce vomiting; seek medical advice immediately.
- Clean tools with the recommended thinner before the material cures.

The information in this datasheet is based on laboratory tests and practical experience and is given in good faith. Users should verify product suitability for their specific application. O MIX reserves the right to update this information without prior notice.