Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Waterproofing

Leakinject PU

Solvent-Free PU Injection Resin
for Stopping Active Leaks



Product Description

Leakinject PU is a solvent-free polyurethane injection resin that reacts with water to form a semi-rigid, closed-cell foam. It stops active water leaks under high pressure, expands up to 30 times when free, does not shrink, resists acids and fuels, is non-toxic and suitable for potable-water structures.

Uses

- Stopping active leaks in cracks and joints.
- Basements, tunnels and shafts.
- Water tanks and manholes.
- Sealing around pipe penetrations.
- Potable water tanks and structures.

Advantages

- Reacts with water; stops active leaks.
- Free expansion up to 30 times.
- Closed-cell, non-shrinking foam.
- Resistant to acids and fuels.
- Solvent-free and non-toxic.

Application

1. **Preparation**
   Drill injection holes along the crack and install packers.
2. **Mixing**
   Add catalyst (CAT) to the resin as recommended for site conditions.
3. **Injection**
   Inject with a single-component pump from the lowest point upward.

Consumption

0.2 – 2 kg
per linear metre of crack
Depends on crack width and voids.

Packaging

Resin 20 kg jerrycans (also IBC 1050 kg); catalyst 2 kg and 20 kg.

Storage & Shelf Life

12 months in original, unopened packaging. Store dry at +5 °C to +35 °C, away from direct sunlight.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Resin	Brown liquid, approx. 120 mPa·s	—
Density	1.18	—
Flash point	> 148 °C	—
Free expansion	up to 30 times	—
Compressive strength (foam)	11.5 MPa	—
E-modulus	295 MPa	—
Catalyst dosage	As recommended for site conditions	—

Consumption

Crack condition	Consumption
Fine cracks	0.2 – 0.5 kg/m
Wide cracks / voids	0.5 – 2 kg/m

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Material and substrate temperature: above +5 °C.
- Water can be present (reaction needs water).

Application Notes

- Start at the lowest point and move upward.
- Inject until resin appears at the next packer.
- Adjust catalyst dosage for reaction speed.
- Clean the pump with PU cleaner after use.

Health & Safety

- Wear chemical-resistant gloves, safety goggles and overalls.
- Uncured resin may cause skin sensitisation; avoid skin and eye contact.
- Ensure good ventilation in enclosed areas.

First Aid & Cleaning

- Eyes: rinse immediately with plenty of clean water for at least 15 minutes and seek medical advice.
- Skin: remove contaminated clothing and wash with soap and water; do not use solvents on skin.
- Inhalation: move to fresh air; seek medical advice if symptoms persist.
- Ingestion: do not induce vomiting; seek medical advice immediately.
- Clean pumps and tools with PU cleaner immediately after use.

The information in this datasheet is based on laboratory tests and practical experience and is given in good faith. Users should verify product suitability for their specific application. O MIX reserves the right to update this information without prior notice.