Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Protective Coating

O-Mastic

Surface-Tolerant
High-Build Epoxy Mastic



Product Description

O-Mastic is a two-component, surface-tolerant, high-build epoxy mastic for the corrosion protection of steel and concrete in industrial and marine environments. It can be used as primer, intermediate or finish coat in maintenance and new construction.

Uses

- Structural steel.
- Floors and decks.
- Tanks and pipes (external).
- Chemical plants.
- Marine and offshore structures.

Advantages

- Surface tolerant: suitable for maintenance painting.
- High build: 100 – 500 µm.
- Primer, intermediate or finish coat.
- Excellent adhesion to steel and concrete.
- Good chemical and corrosion resistance.

Application

1. **Surface Preparation**
   Remove rust, scale and loose coatings to St 2 minimum (Sa 2½ preferred); concrete sound and dry.
2. **Mixing**
   Add Part B to Part A (6 : 1 by volume) and mix 2 – 3 min.
3. **Application**
   Apply by brush, roller or airless spray at 0.15 – 0.30 kg/m² per coat.

Consumption

0.15 – 0.30 kg/m²
per coat
DFT 100 – 500 µm as specified.

Packaging

5 kg and 20 kg sets (Part A + Part B) in metal pails.

Storage & Shelf Life

12 months in original, unopened packaging. Store dry at +5 °C to +35 °C, away from heat and ignition sources.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Mixing ratio (A : B)	6 : 1 by volume — pre-weighed sets, mix as recommended	—
Finish	Semi-gloss	—
Solids content	85 %	—
Recommended DFT	100 – 500 µm	—
Pot life	2 hours	—
Surface dry	4 hours	—
Recoat interval	12 hours	—
Full cure	7 days	—
Shelf life	12 months	—

Consumption

Use	Consumption
Primer / intermediate coat	0.15 – 0.20 kg/m²
High-build coat	0.20 – 0.30 kg/m²

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Ambient and substrate temperature: +10 °C to +35 °C.
- Substrate at least 3 °C above dew point.
- Relative humidity: max. 85 %.
- Steel: St 2 minimum; Sa 2½ for immersion or severe exposure.

Application Notes

- Mix complete sets.
- Apply stripe coats on edges, welds and bolts.
- Check wet film thickness during application.
- Recoat after 12 hours.

Health & Safety

- Solvent-based: flammable. Keep away from heat, sparks and open flames; no smoking.
- Wear chemical-resistant gloves, safety goggles and overalls; use a respirator with organic vapour cartridges in enclosed spaces.
- Uncured epoxy may cause skin sensitisation; avoid skin and eye contact.
- Ensure good ventilation during application and curing.

First Aid & Cleaning

- Eyes: rinse immediately with plenty of clean water for at least 15 minutes and seek medical advice.
- Skin: remove contaminated clothing and wash with soap and water; do not use solvents on skin.
- Inhalation: move to fresh air; seek medical advice if symptoms persist.
- Ingestion: do not induce vomiting; seek medical advice immediately.
- Clean tools with epoxy thinner before the material cures.

The information in this datasheet is based on laboratory tests and practical experience and is given in good faith. Users should verify product suitability for their specific application. O MIX reserves the right to update this information without prior notice.