Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Flooring

Mixcoat GF

Glass-Flake Reinforced
High-Build Epoxy Coating



Product Description

Mixcoat GF is a two-component, glass-flake reinforced, high-build epoxy coating for severe corrosive environments. It can be used as primer or finish on steel and concrete, including splash zones, chemical-resistant floors, pipes and fuel tanks.

Uses

- Steel structures and bridges.
- Splash zones and marine structures.
- Chemical-resistant floors.
- Pipes, water and wastewater structures.
- Fuel tanks.

Advantages

- Glass flakes give a strong barrier.
- High build: 200 – 1000 µm.
- Surface tolerant: Sa 2½ or St 2 – St 3.
- Excellent chemical resistance.
- Long shelf life: 24 months.

Application

1. **Surface Preparation**
   Blast-clean to Sa 2½ or power-tool clean to St 2 – St 3.
2. **Mixing**
   Add Part B to Part A (4 : 1 by weight) and mix thoroughly.
3. **Application**
   Apply by brush, roller or airless spray at approx. 0.35 kg/m² per 200 µm.

Consumption

approx. 0.35 kg/m²
per 200 µm DFT
Theoretical coverage 4.25 m²/L at 200 µm.

Packaging

20 kg sets (16 kg A + 4 kg B) and 5 kg sets (4 kg + 1 kg), metal pails.

Storage & Shelf Life

12 months in original, unopened packaging. Store dry at +5 °C to +35 °C, away from direct sunlight.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Mixing ratio (A : B)	4 : 1 by weight	—
Finish / colour	Semi-gloss, grey	—
Solids content	85 %	—
DFT	200 – 1000 µm	—
Theoretical coverage	4.25 m²/L at 200 µm	—
Surface dry	2 hours	—
Recoat	4 hours to 7 days	—
Full cure	7 days	—
Pot life	1 hour	—
Flash point	27 °C	—
VOC	309 g/L	—
Shelf life	24 months	—

Consumption

Method	Thinning
Brush	0 – 5 %
Conventional spray	5 – 25 %
Airless spray	0 – 20 %

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Ambient and substrate temperature: +10 °C to +35 °C.
- Substrate at least 3 °C above dew point.
- Relative humidity: max. 85 %.
- Substrate moisture: < 4 %.

Application Notes

- Mix complete sets at 4 : 1 by weight.
- Thin according to application method.
- Apply stripe coats on edges and welds.
- Recoat within 4 hours to 7 days.

Health & Safety

- Solvent-based: flammable. Keep away from heat, sparks and open flames; no smoking.
- Wear chemical-resistant gloves, safety goggles and overalls; use a respirator with organic vapour cartridges in enclosed spaces.
- Uncured resin may cause skin sensitisation; avoid skin and eye contact.
- Ensure good ventilation during application and curing.

First Aid & Cleaning

- Eyes: rinse immediately with plenty of clean water for at least 15 minutes and seek medical advice.
- Skin: remove contaminated clothing and wash with soap and water; do not use solvents on skin.
- Inhalation: move to fresh air; seek medical advice if symptoms persist.
- Ingestion: do not induce vomiting; seek medical advice immediately.
- Clean tools with the recommended thinner before the material cures.