Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Flooring



O-Prime WS

Wet-Surface Epoxy Primer
for Green & Damp Concrete

Product Description

O-Prime WS is a two-component, solvent-free epoxy primer designed for green and damp concrete and surfaces with high moisture. It also bonds well to plastics, aluminium and fibreglass, and is the base coat for O MIX epoxy and PU systems on damp substrates.

Uses

- Primer on green concrete and damp substrates.
- Primer for floor and waterproofing systems in humid conditions.
- Bonding to plastics, aluminium and fibreglass.
- Base coat for O MIX epoxy and PU systems.

Advantages

- Bonds to damp and green concrete.
- Solvent-free, 100 % solids.
- Adheres to plastics, aluminium and fibreglass.
- High compressive strength: 70 N/mm².
- Flash point 140 °C.

Application

1. **Surface Preparation**
   Grind or shot blast; remove laitance and standing water (damp is acceptable).
2. **Mixing**
   Add Part B to Part A (3.9 : 1 by weight) and mix 2 – 3 min below 300 rpm.
3. **Application**
   Roll at 0.10 – 0.20 kg/m²; overcoat after 24 hours.

Consumption

0.10 – 0.20 kg/m²
per coat
Depends on substrate porosity.

Packaging

5 kg sets: Part A approx. 3.98 kg in pail + Part B approx. 1.02 kg in jerrycan.

Storage & Shelf Life

12 months in original, unopened packaging. Store dry at +5 °C to +35 °C, away from direct sunlight.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Mixing ratio (A : B)	3.9 : 1 by weight — pre-weighed sets, mix as recommended	—
Solids content	100 %	—
Specific gravity	1.06	—
Flash point	140 °C	—
Pot life (25 °C)	40 min	—
Touch dry / recoat	24 hours	—
Full cure	7 days	—
Compressive strength	70 N/mm²	—

Consumption

Substrate	Consumption
Dense, damp concrete	0.10 – 0.15 kg/m²
Porous / green concrete	0.15 – 0.20 kg/m²

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Ambient and substrate temperature: +10 °C to +35 °C.
- Substrate at least 3 °C above dew point.
- Relative humidity: max. 85 %.
- Substrate may be damp or green, but without standing water.

Application Notes

- Remove standing water before application.
- Mix below 300 rpm to avoid air entrapment.
- Apply a uniform film without puddles.
- Overcoat with the next layer after 24 hours.

Health & Safety

- Wear chemical-resistant gloves, safety goggles and overalls.
- Uncured epoxy may cause skin sensitisation; avoid skin and eye contact.
- Ensure good ventilation in enclosed areas.

First Aid & Cleaning

- Eyes: rinse immediately with plenty of clean water for at least 15 minutes and seek medical advice.
- Skin: remove contaminated clothing and wash with soap and water; do not use solvents on skin.
- Inhalation: move to fresh air; seek medical advice if symptoms persist.
- Ingestion: do not induce vomiting; seek medical advice immediately.
- Clean tools with epoxy thinner before the material cures.

The information in this datasheet is based on laboratory tests and practical experience and is given in good faith. Users should verify product suitability for their specific application. O MIX reserves the right to update this information without prior notice.