Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Flooring



Road Mark PU

Two-Component Polyurethane
Road Marking Top Coat

Product Description

Road Mark PU is a two-component polyurethane road marking top coat applied over epoxy systems. It gives a glossy, non-yellowing finish for roads, junctions, signs, car parks, petrol stations and speed bumps, and can be made reflective with glass beads applied wet-on-wet.

Uses

- Roads, junctions and signs.
- Car parks and garages.
- Petrol stations.
- Speed bumps.
- Top coat over epoxy marking systems.

Advantages

- Glossy, non-yellowing.
- Salt spray 240 h.
- Reflective with glass beads.
- Heat resistance 80 °C.
- RAL colours.

Application

1. **Surface Preparation**
   Apply over a cured epoxy base; clean and dry.
2. **Mixing**
   Mix Part A and Part B at 300 – 500 rpm for 2 minutes.
3. **Application**
   Apply at 0.10 – 0.15 kg/m² per coat; broadcast beads wet-on-wet.

Consumption

0.10 – 0.15 kg/m²
per coat
Two coats recommended.

Packaging

5 kg and 20 kg sets (Part A + Part B), metal pails.

Storage & Shelf Life

12 months in original, unopened packaging. Store dry at +5 °C to +35 °C, away from direct sunlight.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Mixing ratio	As recommended — pre-weighed sets	—
Density	1.3 kg/L	—
Colours	RAL	—
Solids content	58 % (white 70 %)	—
Flash point	31 °C	—
Pot life	1 hour	—
Recoat	16 hours	—
Full cure	5 days	—
Adhesion	0.7 N/mm²	—
Salt spray	240 hours	—
Heat resistance	80 °C	—

Consumption

Use	Consumption
Each coat	0.10 – 0.15 kg/m²

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Ambient and substrate temperature: +10 °C to +35 °C.
- Substrate at least 3 °C above dew point.
- Relative humidity: max. 85 %.
- Substrate moisture: < 4 %.

Application Notes

- Mix at 300 – 500 rpm for 2 minutes.
- Apply over a cured epoxy base.
- Broadcast Beadmix glass beads wet-on-wet for reflectivity.
- Recoat after 16 hours.

Health & Safety

- Solvent-based: flammable. Keep away from heat, sparks and open flames; no smoking.
- Wear chemical-resistant gloves, safety goggles and overalls; use a respirator with organic vapour cartridges in enclosed spaces.
- Uncured resin may cause skin sensitisation; avoid skin and eye contact.
- Ensure good ventilation during application and curing.

First Aid & Cleaning

- Eyes: rinse immediately with plenty of clean water for at least 15 minutes and seek medical advice.
- Skin: remove contaminated clothing and wash with soap and water; do not use solvents on skin.
- Inhalation: move to fresh air; seek medical advice if symptoms persist.
- Ingestion: do not induce vomiting; seek medical advice immediately.
- Clean tools with the recommended thinner before the material cures.

The information in this datasheet is based on laboratory tests and practical experience and is given in good faith. Users should verify product suitability for their specific application. O MIX reserves the right to update this information without prior notice.