Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Repair and Grouting Materials

Anchormix EP

Non-Sag Epoxy Paste
Structural Adhesive & Repair Mortar



Product Description

Anchormix EP is a two-component, non-sag, high-strength epoxy paste for structural bonding and repair. It can be applied on vertical and overhead surfaces without sagging and bonds concrete, steel, stone and masonry.

Uses

- Structural repairs and patching of concrete.
- Bonding new concrete to old concrete.
- Bonding steel plates to concrete.
- Sealing of static cracks before injection.
- Fixing of anchors, bolts and inserts.

Advantages

- Non-sag: vertical and overhead use.
- Compressive strength ≥ 70 N/mm².
- Bond strength > 3 N/mm².
- Tensile strength ≥ 20 N/mm².
- Solvent-free.

Application

1. **Surface Preparation**
   Concrete sound and clean; steel blast-cleaned to Sa 2½.
2. **Mixing**
   Mix Part A and Part B (2 : 1 by weight) to a uniform grey colour.
3. **Application**
   Apply with spatula or trowel; press firmly; finish within the pot life.

Consumption

1.7 – 2.0 kg/m²
per mm thickness
Bonding layers approx. 1 – 2 mm.

Packaging

5 kg sets (3.33 kg A + 1.67 kg B) and 20 kg sets (13.33 kg A + 6.67 kg B).

Storage & Shelf Life

12 months in original, unopened packaging. Store dry at +5 °C to +35 °C, away from direct sunlight.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Colour	Grey	—
Mixing ratio (A : B)	2 : 1 by weight	—
Pot life	30 – 45 min	—
Initial set	4 – 6 hours	—
Full cure	5 – 7 days	—
Compressive strength	≥ 70 N/mm²	—
Tensile strength	≥ 20 N/mm²	—
Bond strength to concrete	> 3 N/mm² (concrete failure)	—
Application temperature	+5 °C to +40 °C	—
Service temperature	-10 °C to +60 °C	—

Consumption

Use	Consumption
Per mm thickness	1.7 – 2.0 kg/m²
Crack sealing (surface)	approx. 0.1 – 0.2 kg per metre

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Ambient and substrate temperature: +5 °C to +40 °C.
- Substrate clean, sound and dry or matt-damp.
- Steel blast-cleaned to Sa 2½.

Application Notes

- Mix complete sets to a uniform colour without streaks.
- Press firmly into the substrate to ensure full contact.
- For steel plate bonding, apply on both surfaces and press until adhesive squeezes out.
- Remove excess before curing.

Health & Safety

- Wear chemical-resistant gloves, safety goggles and overalls.
- Uncured epoxy may cause skin sensitisation; avoid skin and eye contact.
- Ensure good ventilation in enclosed areas.

First Aid & Cleaning

- Eyes: rinse immediately with plenty of clean water for at least 15 minutes and seek medical advice.
- Skin: remove contaminated clothing and wash with soap and water; do not use solvents on skin.
- Inhalation: move to fresh air; seek medical advice if symptoms persist.
- Ingestion: do not induce vomiting; seek medical advice immediately.
- Clean tools with epoxy thinner before the material cures.

The information in this datasheet is based on laboratory tests and practical experience and is given in good faith. Users should verify product suitability for their specific application. O MIX reserves the right to update this information without prior notice.