automation Portal

IA_Project / PLC_1 [CPU 1511-1 PN] / PLC tags

03_green_assembly_line_IO [12]

Name		Data type	Address	Comment
1	green_assembly_base_clamp	Bool	%Q0.5	-
an a	green_assembly_lid_clamp	Bool	%Q0.6	-
1	green_assembly_move_X	Bool	%Q0.7	0 = gripper is above lid , 1= gripper is above base
all l	green_assembly_move_Z	Bool	%Q1.0	0 = gripper is up , 1= gripper is down
1	green_assembly_grab	Bool	%Q1.1	-
TII	green_assembly_clamp_up	Bool	%Q1.2	Raise the base clamp to allow the final product to exit the assembly line
1	green_assembly_base_in	Bool	%I1.2	The base is positioned at the edge of the base clamp
1	green_assembly_lid_in	Bool	%I1.3	The lid is positioned at the edge of the lid clamp
all l	green_assembly_done	Bool	%I1.4	Final product exited the assembly line
1	green_assembly_X_limit	Bool	%I1.5	Becomes 1 when the arm is fully extended along the X axis
1	green_assembly_Z_limit	Bool	%I1.6	Becomes 1 when the arm is fully extended along the Z axis
1	green_assembled_count	Int	%QW52	-