Totally Integrated	
automation Portal	

## IA\_Project / PLC\_1 [CPU 1511-1 PN] / PLC tags

## 08\_storage\_system\_IO [13]

PLC tags					
Name		Data type Address		Comment	
<b>1</b>	storage_fork_left_limit	Bool	%I4.0	Becomes 1 when fork reaches full left extension	
<b>(11)</b>	storage_fork_middle_limit	Bool	%I4.1	Becomes 1 when the fork is exactly at the center position	
<b>1</b>	storage_fork_right_limit	Bool	%14.2	Becomes 1 when fork reaches full right extension	
1	storage_X_moving	Bool	%I4.3	Becomes 1 while moving along the floor (X-axis); otherwise, 0	
<b>(11)</b>	storage_Z_moving	Bool	%14.4	Becomes 1 while moving up or down (Z-axis); otherwise, 0	
-	storage_fork_lift	Bool	%Q4.2	-	
<b>(11)</b>	storage_fork_move_left	Bool	%Q4.3	-	
1	storage_fork_move_right	Bool	%Q4.4	-	
<b>(III</b>	storage_loading_belt	Bool	%Q4.5	-	
<b>411</b>	storage_fork_position	Int	%QW40	1 to 54 = Valid storage positions; other values (except 0) = Home position	
-	storage_box_in	Bool	%I4.5	The box is ready to be lifted	
<b>=</b>	storage_stored_boxes_count	Int	%QW42	The total number of boxes in the storage as of right now	
<b>(11)</b>	storage_stored_products_count	Int	%QW44	The total number of products in the storage as of right now	