



**CONDITION BASED ASSESSMENT
QUICK SCANNING REPORT
SBUM DIAGNOSTIC PAHANG
TNB BAHAGIAN PEMBAHAGIAN PAHANG**

FUNCTIONAL LOCATION (ERMS)	:	CCHL/PCE/J00002
FUNCTIONAL LOCATION (SITE)	:	CCHL/PCE/J00002
SUBSTATION NAME (ERMS)	:	JALAN ROBINSON
SUBSTATION NAME (SITE)	:	JALAN ROBINSON
COORDINATE	:	4.453222, 101.391489
SUBSTATION TYPE	:	PAT+RMU
AREA	:	CAMERON HIGHLAND
STATE	:	PAHANG
PO	:	42289580
DATE	:	01 JUN 2026

SCANNED BY	
THERMOGRAPHY	: MUHAMMAD ADAM BIN SAFARUDDIN (2017MY34N004)
ULTRASOUND	: MUHAMMAD ADAM BIN SAFARUDDIN (UET2016316)

EQUIPMENT/TOOLS	
THERMOGRAPHY	: FLIR T640 (SN 55912229) (CALIBRATION DUE DATE: 26 DEC 2026)
ULTRASOUND	: UE 10000 MPH (SN 105249) (CALIBRATION DUE DATE: 26 DEC 2026)

PREPARED BY	
NAME OF CONTRACTOR	: EET ENGINEERING SERVICES SDN BHD
ADDRESS	: NO.38, JALAN SS19/1D,
	: 47500, SUBANG JAYA, SELANGOR.

SUBSTATION SIGNBOARD



EXECUTIVE SUMMARY


NO.	EQUIPMENT	AREA	IR (Abs T/ $\hat{a}^{\wedge}T$)	US (dB)	DEFECT
1.	RMU SF6 TAMCO	OVERVIEW	-	-	-
		OVERVIEW TOP	-	-	-
		OVERVIEW BOTTOM	-	-	-
	PANEL CCH00666 JALAN BOH	CABLE COMPARTMENT	-	-	
		CABLE ENTRY	-	-	
	PANEL CCH00667 TX 100kVA	CABLE COMPARTMENT	-	-	
		CABLE ENTRY	-	-	
	PANEL CCH00668 SSU HOSPITAL	CABLE COMPARTMENT	-	-	
		CABLE ENTRY	-	-	
2.	TX1 MTM 100kVA	OVERVIEW	-	-	-
		HV BUSHING	-	-	
		HV CABLE	-	-	
		LV BUSHING	-	-	
		LV CABLE	-	-	

VISUAL DEFECT SUMMARY

NO.	EQUIPMENT	DEFECT DESCRIPTION	ADDITIONAL REMARKS
1	SUBSTATION	CPR POSTER OLD VERSION	SWG BAY


	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	OVERVIEW			Panel No.
Panel Name	-				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	-
Spot Temp. 2 (Sp2)	-
Average Temp. (Ar1)	38.1 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	-
Load (A)	-
Defect	-

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	-

ULTRASOUND IMAGE



Decibel (dB)	-
Sound characteristic	-
Severity	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	OVERVIEW TOP		Panel No.	-
Panel Name	-				

IR IMAGE




VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	-
Spot Temp. 2 (Sp2)	-
Average Temp. (Ar1)	33.4 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	-
Load (A)	-
Defect	-

PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	-

ULTRASOUND IMAGE



Decibel (dB)	-
Sound characteristic	-
Severity	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	OVERVIEW BOTTOM		Panel No.	-
Panel Name	-				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	-
Spot Temp. 2 (Sp2)	-
Average Temp. (Ar1)	33.0 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	-
Load (A)	-
Defect	-

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	-

ULTRASOUND IMAGE



Decibel (dB)	-
Sound characteristic	-
Severity	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE COMPARTMENT	Panel No.	CCH00666	
Panel Name	JALAN BOH				

IR IMAGE




VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	31.8 °C
Spot Temp. 2 (Sp2)	31.8 °C
Average Temp. (Ar1)	31.7 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.0 °C
Load (A)	-
Defect	

PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE




Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE ENTRY		Panel No.	CCH00666
Panel Name	JALAN BOH				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	29.7 °C	Serial No.	B21729024
Spot Temp. 2 (Sp2)	29.3 °C	Heater (A)	-
Average Temp. (Ar1)	29.7 °C	CB Position	CLOSE
Ambient Temp.	23.2 °C	Busbar Position	-
Delta T (Δ T)	0.4 °C	Cable Type	XLPE
Load (A)	-		
Defect			


ULTRASOUND IMAGE	
	
Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -


	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE COMPARTMENT		Panel No.	CCH00667
Panel Name	TX 100kVA				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	31.5 °C	Serial No.	B21729024
Spot Temp. 2 (Sp2)	31.9 °C	Heater (A)	-
Average Temp. (Ar1)	31.7 °C	CB Position	CLOSE
Ambient Temp.	23.2 °C	Busbar Position	-
Delta T (Δ T)	0.4 °C	Cable Type	XLPE
Load (A)	-		
Defect			

ULTRASOUND IMAGE	
	
Decibel (dB)	OdB
Sound characteristic	Normal
Severity	
Sound clip	
Analysis & Recommendations:	
Analysis: No Anomaly.	
Recommendation: -	

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE ENTRY		Panel No.	CCH00667
Panel Name	TX 100kVA				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	30.1 °C
Spot Temp. 2 (Sp2)	29.5 °C
Average Temp. (Ar1)	30.3 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.5 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE



Decibel (dB)	OdB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE COMPARTMENT	Panel No.	CCH00668	
Panel Name	SSU HOSPITAL				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	38.3 °C
Spot Temp. 2 (Sp2)	37.9 °C
Average Temp. (Ar1)	38.7 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.4 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	B21729024
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE




Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	RMU SF6	Manufacturer	TAMCO	Time: 4:02 PM
	Model	GR1	Rating	12kV	Humidity: 77%
	Area	CABLE ENTRY		Panel No.	CCH00668
Panel Name	SSU HOSPITAL				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	30.0 °C	Serial No.	B21729024
Spot Temp. 2 (Sp2)	30.6 °C	Heater (A)	-
Average Temp. (Ar1)	33.0 °C	CB Position	CLOSE
Ambient Temp.	23.2 °C	Busbar Position	-
Delta T (Δ T)	0.6 °C	Cable Type	XLPE
Load (A)	-		
Defect			



ULTRASOUND IMAGE	
	
Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	

Analysis & Recommendations:

Analysis: No Anomaly.


Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 4:02 PM
	Model	HERMETICALLY SEAL	Rating	100kVA	Humidity: 77%
	Area	OVERVIEW		Tx No.	1
Location					

IR IMAGE		VISUAL IMAGE																													
																															
<table><tr><th>PARAMETER</th><th>VALUE</th></tr><tr><td>Spot Temp.1 (Sp1)</td><td>40.8 °C</td></tr><tr><td>Spot Temp. 2 (Sp2)</td><td>39.9 °C</td></tr><tr><td>Average Temp. (Ar1)</td><td>36.4 °C</td></tr><tr><td>Ambient Temp.</td><td>23.2 °C</td></tr><tr><td>Delta T (Δ T)</td><td>0.8 °C</td></tr><tr><td>Load (A)</td><td>-</td></tr><tr><td>Defect</td><td>-</td></tr></table>		PARAMETER	VALUE	Spot Temp.1 (Sp1)	40.8 °C	Spot Temp. 2 (Sp2)	39.9 °C	Average Temp. (Ar1)	36.4 °C	Ambient Temp.	23.2 °C	Delta T (Δ T)	0.8 °C	Load (A)	-	Defect	-	<table><tr><th>PARAMETER</th><th>VALUE</th></tr><tr><td>Serial No.</td><td>T/800/1452/1486</td></tr><tr><td>Heater (A)</td><td>-</td></tr><tr><td>CB Position</td><td>-</td></tr><tr><td>Busbar Position</td><td>-</td></tr><tr><td>Cable Type</td><td>-</td></tr></table>		PARAMETER	VALUE	Serial No.	T/800/1452/1486	Heater (A)	-	CB Position	-	Busbar Position	-	Cable Type	-
PARAMETER	VALUE																														
Spot Temp.1 (Sp1)	40.8 °C																														
Spot Temp. 2 (Sp2)	39.9 °C																														
Average Temp. (Ar1)	36.4 °C																														
Ambient Temp.	23.2 °C																														
Delta T (Δ T)	0.8 °C																														
Load (A)	-																														
Defect	-																														
PARAMETER	VALUE																														
Serial No.	T/800/1452/1486																														
Heater (A)	-																														
CB Position	-																														
Busbar Position	-																														
Cable Type	-																														
ULTRASOUND IMAGE  <table><tr><td>Decibel (dB)</td><td>-</td></tr><tr><td>Sound characteristic</td><td>-</td></tr><tr><td>Defect</td><td>-</td></tr><tr><td>Sound clip</td><td></td></tr></table>				Decibel (dB)	-	Sound characteristic	-	Defect	-	Sound clip																					
Decibel (dB)	-																														
Sound characteristic	-																														
Defect	-																														
Sound clip																															
Analysis & Recommendations:																															
Analysis: No Anomaly.																															
Recommendation: -																															

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 4:02 PM
	Model	HERMETICALLY SEAL	Rating	100kVA	Humidity: 77%
	Area	BUSHING		Tx No.	1
Location	HV SIDE				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	36.5 °C
Spot Temp. 2 (Sp2)	36.3 °C
Average Temp. (Ar1)	19.8 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.2 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	T/800/1452/1486
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE



Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 4:02 PM
	Model	HERMETICALLY SEAL	Rating	100kVA	Humidity: 77%
	Area	CABLE	Tx No.	1	
Location	HV SIDE				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	31.1 °C
Spot Temp. 2 (Sp2)	30.9 °C
Average Temp. (Ar1)	15.3 °C
Ambient Temp.	23.2 °C
Delta T (ΔT)	0.2 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	T/800/1452/1486
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE




Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 4:02 PM
	Model	HERMETICALLY SEAL	Rating	100kVA	Humidity: 77%
	Area	BUSHING		Tx No.	1
Location	LV SIDE				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	29.5 °C	Serial No.	T/800/1452/1486
Spot Temp. 2 (Sp2)	29.8 °C	Heater (A)	-
Average Temp. (Ar1)	27.8 °C	CB Position	-
Ambient Temp.	23.2 °C	Busbar Position	-
Delta T (ΔT)	0.3 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JALAN ROBINSON			Date: 01/06/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 4:02 PM
	Model	HERMETICALLY SEAL	Rating	100kVA	Humidity: 77%
	Area	CABLE		Tx No.	1
Location	LV SIDE				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	28.1 °C	Serial No.	T/800/1452/1486
Spot Temp. 2 (Sp2)	28.2 °C	Heater (A)	-
Average Temp. (Ar1)	20.7 °C	CB Position	-
Ambient Temp.	23.2 °C	Busbar Position	-
Delta T (Δ T)	0.0 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

SUBSTATION CONDITION


SUBSTATION OVERVIEW



SIGNBOARD



SWITCHGEAR




SWITCHGEAR NAMEPLATE



TRANSFORMER



TRANSFORMER NAMEPLATE



SUBSTATION CONDITION

EFI



SF6 INDICATOR



TRANSFORMER OIL LEVEL INDICATOR



VISUAL DEFECT



CPR POSTER OLD VERSION – SWG BAY

NORMAL/DEFECT STICKER

NORMAL STICKER	
CONDITION ASSESSMENT TENAGA NASIONAL Better Together DIAGNOSTIC UNIT SUBSTATION 	
Cycle/Year :	1/2026
Testing Date :	01-06-2026
Defect :	—
Company/Team :	EET ENGINEERING
	TEV U/S IR

151

PAT+
RMU

STATE / AREA:		PAHANG / CAMELON HIGHLAND		DISTRIBUTION SUBSTATION (PCS) CMA TEST SHEET										DATE		16/2026		FUNCTIONAL LOCATION:		CUM/PCS/J00002						
PE NAME:		JALAN ROBINSON												TIME IN / OUT		4:02 P.M. / 4:17 P.M.		BACKGROUND TEMP:		23.2 °C						
V.I. REF. NO.														TEV BACK GROUND / HUMIDITY		1 / 1										
DETAIL																										
NO.	FDR. NO.	FEEDER NAME	STATUS (TRIP / CLOSE)	LOAD (A)	CABLE TYPE/SIZE	HEATER (A)	SERIAL NO (ONLY BREAKER & OLIV)	COMP	Tmin (°C)	Tmax (°C)	AT	Avg (°C)	FILE	REMARKS	dB	FILE	TYPE CHAR.	dB	PULSE / CYCLE	TYPE CHAR.	REMARK					
1	CLH 00666	JALAN BOLA	TRIP / CLOSE		XLPE PILC N/A NACC			CABLE	31.9	32.1	0.2	32.0	6.7		0	2	-	5	0	-						
2	CLH 00667	TX 100 KVA	TRIP / CLOSE		XLPE PILC N/A NACC			CABLE	31.4	31.7	0.3	31.5	8.9		0	3	-	4	0	-						
3	CLH 00668	SSU HOSPITAL	TRIP / CLOSE		XLPE PILC N/A NACC			CABLE	38.4	38.9	0.5	38.6	10.11	SOLAR LOADING	0	4	-	4	0	-						
4			TRIP / CLOSE		XLPE PILC N/A NACC			CABLE																		
OVERVIEW								Bottom																		
								LOCAL TRANSFORMER																		
								THERMOGRAPHY																		
								ULTRASOUND																		
TX ID	SERIAL NO	CABLE TYPE/SIZE	REMARK	COMP.	Tmin (°C)	Tmax (°C)	AT	Avg (°C)	FILE	dB	TYPE CHAR.	TX ID	SERIAL NO	CABLE TYPE/SIZE	REMARK	COMP.	Tmin (°C)	Tmax (°C)	AT	FILE	Avg (°C)	FILE	dB	TYPE CHAR.	REMARKS	
TX1	11800 / 1452 / 1486	XLPE/PILC		HT CABLE	32.0	32.3	0.3	32.2	17.18	0	-	TX3		XLPE/PILC		HT CABLE	1									
		HT BUSHING			30.9	31.1	0.2	31.0	16	0	-			HT BUSHING												
		LV CABLE			27.2	27.5	0.3	27.3	15					LV CABLE												
		LV BUSHING			28.8	29.2	0.4	28.9	14					LV BUSHING												
		BODY			36.3	41.7	5.4	38.5	13					BODY												
TX2		XLPE/PILC		HT CABLE								TX4		XLPE/PILC		HT CABLE										
		HT BUSHING												HT BUSHING												
		LV CABLE												LV CABLE												
		LV BUSHING												LV BUSHING												
		BODY												BODY												
LV DISTRIBUTION BOARD / FEEDER PILLAR / OTHERS																										
1	LVDB / FP 1	INC. 1	INC. 2	INC. 3	F1	F2	F3	F4	F5	F6	F7	F8	F9	F10												
	CABLE TYPE / SIZE	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC												
2	LVDB / FP 2	INC. 1	INC. 2	INC. 3	F1	F2	F3	F4	F5	F6	F7	F8	F9	F10												
	CABLE TYPE / SIZE	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC	XLPE/PILC												
NO	LVDB / FP	DEFECTIVE FEEDER NAME	Tmin (°C)	Tmax (°C)	AT	FILE	Avg (°C)	REMARK																		
	INC 1																									
	INC 2																									
	F1																									
	F2																									
	F3																									
	F4																									
	F5																									
	F6																									
	F7																									
	F8																									
		Battery Bank																								
		Black Box 1																								
		Black Box 2																								
		Lightning Arrester																								
		Dropout Fuse																								
		Auto Recloser																								
		LBS																								

EET ENGINEERING SERVICES SDN BHD
 No. 38-21 2nd Floor, Jalan SS 19/1D
 47800 Subang Jaya, Selangor.
 Tel: 603-5636 6205 Fax: 603-5636 7205

MOHD AZZAD BIN OTHMAN (10085230)
 JURUTEKNIK TINGKATAN BIASA
 (DIAGNOSTIC SUBSTATION PAHANG)
 SBU MAINTENANCE EAST
 DISTRIBUTION NETWORK DIVISION, TNB

151

PAT+RMU

CPR (O.V, surg Bay)



VISUAL INSPECTION CHECKLIST FOR 11KV SUBSTATION

DATE:

P/E Name (ERMS):

P/E Name (SITE):

GPS Coordinate:

PCE Type:

PCE Area

Switchgear Type 1:

Manufacturer/Modal:

Switchgear Manufactured Date:

Switchgear Type 2:

Manufacturer/Modal:

Switchgear Manufactured Date:

No. of Transformer:

Tx 1:

Tx 2:

Tx 3:

Tx 4:

KEJANGGALAN

1. Signboard:

2. Earth connection:

3. EFI Functioning:

4. Heater Functioning:

5. Labelling @Switchgear:

6. Labelling @ LVDB:

7. Gas Pressure:

8. Tx Guard:

9. Tx Oil Level (conservator tank):

10. Tx Oil Leak:

11. Tx Bushing:

12. Top Demand Indicator (@LVDB):

13. Link/fuse Holder:

14. LV Termination:

15. Rubber Mat:

16. Trenching:

17. Battery Voltage:

18. Lighting:

19. Roof Condition:

20. Fire Fighting

21. Fence/door condition:

22. Cleanliness/Bushes:

23. Vandalism

24. Other Findings

1/6/2026

JALAN ROBINSON

JALAN ROBINSON

4.453222, 101.391489

INDOOR

NORMAL

RMU OIL

JAMCO / GRI

2017

RMU OIL

RMU SF6

1

Type HS

Type

Type

Type

Type

KVA 100

Construction Yr: 1996

Construction Yr:

Construction Yr:

Construction Yr:

Manufacturer: MT

Manufacturer:

Manufacturer:

Manufacturer:

S/N: 71800/1452/1486

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

S/N:

EET ENGINEERING SERVICES SDN BHD
(534556-W)
No. 38/2, 2nd Floor, Jalan SS 19/1D
47500 Subang Jaya, Selangor.
Tel: 603-5636 6205 Fax: 603-5636 7205

F/L NO (ERMS):

F/L NO (SITE):

CCAL / PCE / 100002

CCAL / PCE / 100002

ATTACH BUILDING

COMPACT

COASTAL

MRMU

VCB

MRMU

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

VCB

TNB SUPERVISOR/ ENGINEER (NAME & SIGNATURE):

MOHD AZZAD BIN OTHMAN (10085230)

JURUTEKNIK TINGKATAN BIASA

(DIAGNOSIS / INSPECTION / MAINTENANCE)

(DIAGNOSIS / INSPECTION / MAINTENANCE)

(DIAGNOSIS / INSPECTION / MAINTENANCE)

(DIAGNOSIS / INSPECTION / MAINTENANCE)

(DIAGNOSIS / INSPECTION / MAINTENANCE)

(DIAGNOSIS / INSPECTION / MAINTENANCE)

(DIAGNOSIS / INSPECTION / MAINTENANCE)