

EXECUTIVE SUMMARY

NO.	EQUIPMENT	DEFECT AREA	IR (Abs T/ Δ T)	DEFECT
1.	MRMU, INDKOM	OVERVIEW	-	-
		OVERVIEW TOP	-	-
	PANEL CCH00420 BERTAM MEWAH	CABLE COMPARTMENT	-	
	PANEL CCH00423 CS JENSIN	CABLE COMPARTMENT	-	
	PANEL CCH00422 OUF	CABLE COMPARTMENT	-	
	PANEL CCH00421 TX	CABLE COMPARTMENT	-	
2.	TX1 EWT 750kVA	OVERVIEW	-	-
		HV BUSHING	-	
		HV CABLE	-	
		LV BUSHING	-	
		LV CABLE	-	
3.	FP TX1	OVERVIEW	-	-