



**CONDITION BASED ASSESSMENT
FULL SCANNING REPORT
SBUM DIAGNOSTIC PAHANG
TNB BAHAGIAN PEMBAHAGIAN PAHANG**

FUNCTIONAL LOCATION (ERMS)	:	CRAU/PCE/J00096
FUNCTIONAL LOCATION (SITE)	:	CRAU/PCE/J00096
SUBSTATION NAME (ERMS)	:	JPS
SUBSTATION NAME (SITE)	:	JPS
COORDINATE	:	3.805802, 101.847206
SUBSTATION TYPE	:	PCE
AREA	:	RAUB
STATE	:	PAHANG
PO	:	42225439
DATE	:	06 MAR 2026

SCANNED BY	
THERMOGRAPHY	: MUHAMMAD ADAM BIN SAFARUDDIN (2017MY34N004)

EQUIPMENT/TOOLS	
THERMOGRAPHY	: FLIR T640 (SN 55912229) (CALIBRATION DUE DATE: 26 DEC 2026)

PREPARED BY	
NAME OF CONTRACTOR	: EET ENGINEERING SERVICES SDN BHD
ADDRESS	: NO.38, JALAN SS19/1D, 47500, SUBANG JAYA, SELANGOR.

SUBSTATION SIGNBOARD




EXECUTIVE SUMMARY

NO.	EQUIPMENT	DEFECT AREA	IR (Abs T/ Δ T)	DEFECT
1.	RMU SF6, SSE LUCY	OVERVIEW	-	-
		OVERVIEW BOTTOM	-	-
	PANEL CRB00329 SUNGAI LUI	CABLE COMPARTMENT	-	
		CABLE ENTRY	-	
	PANEL CRB00330 ALATUBAH	CABLE COMPARTMENT	-	
		CABLE SWG/CABLE XLPE	4.0 °C	
	PANEL CRB00330 TAMAN SHAHBANDAR	CABLE COMPARTMENT	-	
		CABLE ENTRY	-	
2.	TX1 - MTM 500kVA	OVERVIEW	-	-
		OVERVIEW TOP	-	-
		HV BUSHING	-	
		HV CABLES	-	
		LV BUSHING	-	
		LV CABLES	-	
3.	FP TX1	OVERVIEW	-	-
	OUTGOING F4	OUTGOING FUSE CONNECTION/ YELLOW PHASE	56.2 °C	

VISUAL DEFECT SUMMARY

NO.	EQUIPMENT	DEFECT DESCRIPTION	ADDITIONAL REMARKS
1	SUBSTATION	CPR POSTER OLD VERSION	SWG BAY
2	EFI	NO FEEDER LABEL	CRB00331 - TAMAN SHAHBANDAR
3	LIGHTING	NOT OPERATED	SWG BAY
4	FP/LVDB	NO FEEDER NO./FEEDER NAME	FP TX1 - NOT FOLLOW NEW STANDARD
5	CABLE PILC	CABLE PILC SWG	CRB00329 - SUNGAI LUI
6	CABLE PILC	CABLE PILC SWG	CRB00331 - TAMAN SHAHBANDAR
7	CABLE PILC	CABLE PILC LVDB/FP	FP TX1 / OUTGOING F2
8	CABLE PILC	CABLE PILC LVDB/FP	FP TX1 / OUTGOING F4

	Substation	JPS			Date: 06/03/2026
	Equipment	RMU SF6	Manufacturer	SSE LUCY	Time: 10:33 AM
	Model	VRN6A	Rating	12kV	Humidity: 71%
	Area	OVERVIEW			Panel No. -
Panel Name		-			


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	-	Serial No.	SF00089144
Spot Temp. 2 (Sp2)	-	Heater (A)	-
Average Temp. (Ar1)	32.0 °C	CB Position	-
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	-	Cable Type	-
Load (A)	-		
Severity	-		

Analysis & Recommendations:

Analysis: Please refer the following page for details defect.

Recommendation: N/A

	Substation	JPS			Date: 06/03/2026
	Equipment	RMU SF6	Manufacturer	SSE LUCY	Time: 10:33 AM
	Model	VRN6A	Rating	12kV	Humidity: 71%
	Area	OVERVIEW BOTTOM			Panel No.
Panel Name		-			


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	-	Serial No.	SF00089144
Spot Temp. 2 (Sp2)	-	Heater (A)	-
Average Temp. (Ar1)	32.0 °C	CB Position	-
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	-	Cable Type	-
Load (A)	-		
Severity	-		

Analysis & Recommendations:

Analysis: Please refer the following page for details defect.

Recommendation: N/A

	Substation	JPS		Date: 06/03/2026
	Equipment	RMU SF6	Manufacturer	SSE LUCY
	Model	VRN6A	Rating	12kV
	Area	CABLE COMPARTMENT		Humidity: 71%
Panel Name	SUNGAI LUI		Panel No.	CRB00329


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	32.5 °C	Serial No.	SF00089144
Spot Temp. 2 (Sp2)	32.8 °C	Heater (A)	-
Average Temp. (Ar1)	32.4 °C	CB Position	CLOSE
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	0.3 °C	Cable Type	PILC
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JPS			Date: 06/03/2026
	Equipment	RMU SF6	Manufacturer	SSE LUCY	Time: 10:33 AM
	Model	VRN6A	Rating	12kV	Humidity: 71%
	Area	CABLE ENTRY		Panel No.	CRB00329
Panel Name		SUNGAI LUI			


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	31.4 °C	Serial No.	SF00089144
Spot Temp. 2 (Sp2)	30.9 °C	Heater (A)	-
Average Temp. (Ar1)	31.1 °C	CB Position	CLOSE
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (Δ T)	0.5 °C	Cable Type	PILC
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JPS			Date: 06/03/2026
	Equipment	RMU SF6	Manufacturer	SSE LUCY	Time: 10:33 AM
	Model	VRN6A	Rating	12kV	Humidity: 71%
	Area	CABLE COMPARTMENT		Panel No.	CRB00330
Panel Name		ALATUBAH			


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	35.7 °C	Serial No.	SF00089144
Spot Temp. 2 (Sp2)	35.1 °C	Heater (A)	-
Average Temp. (Ar1)	36.5 °C	CB Position	CLOSE
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (Δ T)	0.5 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JPS			Date: 06/03/2026
	Equipment	RMU SF6	Manufacturer	SSE LUCY	Time: 10:33 AM
	Model	VRN6A	Rating	12kV	Humidity: 71%
	Area	CABLE ENTRY		Panel No.	CRB00330
Panel Name		ALATUBAH			


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	36.1 °C	Serial No.	SF00089144
Spot Temp. 2 (Sp2)	32.1 °C	Heater (A)	-
Average Temp. (Ar1)	32.5 °C	CB Position	CLOSE
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (Δ T)	4.0 °C	Cable Type	XLPE
Load (A)	-		
Severity			

Analysis & Recommendations:

Analysis: Thermal image above indicates hotspot detected at **CABLE XLPE – CABLE TERMINATION**.

Recommendation: To inspect and make a new termination or replace defective parts if necessary.

	Substation	JPS			Date: 06/03/2026
	Equipment	RMU SF6	Manufacturer	SSE LUCY	Time: 10:33 AM
	Model	VRN6A	Rating	12kV	Humidity: 71%
	Area	CABLE COMPARTMENT		Panel No.	CRB00330
Panel Name		TAMAN SHAHBANDAR			


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	37.6 °C	Serial No.	SF00089144
Spot Temp. 2 (Sp2)	37.5 °C	Heater (A)	-
Average Temp. (Ar1)	37.3 °C	CB Position	CLOSE
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	0.1 °C	Cable Type	PILC
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JPS			Date: 06/03/2026
	Equipment	RMU SF6	Manufacturer	SSE LUCY	Time: 10:33 AM
	Model	VRN6A	Rating	12kV	Humidity: 71%
	Area	CABLE ENTRY		Panel No.	CRB00330
Panel Name		TAMAN SHAHBANDAR			



IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	32.7 °C	Serial No.	SF00089144
Spot Temp. 2 (Sp2)	32.6 °C	Heater (A)	-
Average Temp. (Ar1)	32.7 °C	CB Position	CLOSE
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (Δ T)	0.2 °C	Cable Type	PILC
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JPS			Date: 06/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 10:33 AM
	Model	HERMETICALLY SEAL	Rating	500kVA	Humidity: 71%
	Area	OVERVIEW		Tx No.	TX1
Location		-			


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	40.9 °C	Serial No.	T1/272/5717
Spot Temp. 2 (Sp2)	37.6 °C	Heater (A)	-
Average Temp. (Ar1)	38.4 °C	CB Position	-
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	3.3 °C	Cable Type	-
Load (A)	-		
Defect	-		

Analysis & Recommendations:


Analysis: No Anomaly.

Recommendation: -


	Substation	JPS			Date: 06/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 10:33 AM
	Model	HERMETICALLY SEAL	Rating	500kVA	Humidity: 71%
	Area	OVERVIEW TOP		Tx No.	TX1
Location		-			

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	41.6 °C	Serial No.	T1/272/5717
Spot Temp. 2 (Sp2)	41.6 °C	Heater (A)	-
Average Temp. (Ar1)	40.3 °C	CB Position	-
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	0.1 °C	Cable Type	-
Load (A)	-		
Defect	-		
Analysis & Recommendations:			
Analysis: No Anomaly.			
Recommendation: -			

	Substation	JPS			Date: 06/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 10:33 AM
	Model	HERMETICALLY SEAL	Rating	500kVA	Humidity: 71%
	Area	BUSHING		Tx No.	TX1
Location	HV SIDE				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	38.7 °C	Serial No.	T1/272/5717
Spot Temp. 2 (Sp2)	38.6 °C	Heater (A)	-
Average Temp. (Ar1)	38.3 °C	CB Position	-
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	0.2 °C	Cable Type	XLPE
Load (A)	-		
Defect			
Analysis & Recommendations:			
Analysis: No Anomaly.			
Recommendation: -			

	Substation	JPS			Date: 06/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 10:33 AM
	Model	HERMETICALLY SEAL	Rating	500kVA	Humidity: 71%
	Area	CABLE		Tx No.	TX1
Location	HV SIDE				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	35.5 °C	Serial No.	T1/272/5717
Spot Temp. 2 (Sp2)	35.3 °C	Heater (A)	-
Average Temp. (Ar1)	35.7 °C	CB Position	-
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	0.2 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JPS			Date: 06/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 10:33 AM
	Model	HERMETICALLY SEAL	Rating	500kVA	Humidity: 71%
	Area	BUSHING		Tx No.	TX1
Location	LV SIDE				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	35.4 °C	Serial No.	T1/272/5717
Spot Temp. 2 (Sp2)	36.2 °C	Heater (A)	-
Average Temp. (Ar1)	36.9 °C	CB Position	-
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	0.9 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JPS			Date: 06/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 10:33 AM
	Model	HERMETICALLY SEAL	Rating	500kVA	Humidity: 71%
	Area	CABLE		Tx No.	TX1
Location	LV SIDE				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	35.7 °C	Serial No.	T1/272/5717
Spot Temp. 2 (Sp2)	35.7 °C	Heater (A)	-
Average Temp. (Ar1)	36.9 °C	CB Position	-
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	0.0 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	JPS			Date: 06/03/2026
	Equipment	FP TX1	Manufacturer	GEC	Time: 10:33 AM
	Model	J-SLOTTED	Rating	1600A	Humidity: 71%
	Area	OVERVIEW			Feeder No. -
Feeder Name		-			



IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	-	Serial No.	15519
Spot Temp. 2 (Sp2)	-	Heater (A)	-
Average Temp. (Ar1)	36.6 °C	CB Position	-
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	-	Cable Type	-
Load (A)	-		
Severity	-		

Analysis & Recommendations:

Analysis: Please refer the following page for details defect.

Recommendation: N/A

	Substation	JPS			Date: 06/03/2026
	Equipment	FP TX1	Manufacturer	GEC	Time: 10:33 AM
	Model	J-SLOTTED	Rating	1600A	Humidity: 71%
	Area	FUSE CONNECTION – YELLOW PHASE		Feeder No.	OUTGOING F4
Feeder Name		PEJABAT JPS			

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	56.2 °C	Serial No.	15519
Spot Temp. 2 (Sp2)	37.5 °C	Heater (A)	-
Average Temp. (Ar1)	38.5 °C	CB Position	-
Ambient Temp.	32.3 °C	Busbar Position	-
Delta T (ΔT)	18.7 °C	Cable Type	PILC
Load (A)	-		
Severity			

Analysis & Recommendations:

Analysis: Thermal image above indicates hot spot detected at **OUTGOING FUSE CONNECTION**. The anomaly is due to loosen or bad contact at the connection point.

Recommendation: To inspect, clean the contact surface and re-tighten the connection point. Replace defective parts if necessary.

SUBSTATION CONDITION

SUBSTATION OVERVIEW



SIGNBOARD



SWITCHGEAR



SWITCHGEAR NAMEPLATE



TRANSFORMER



TRANSFORMER NAMEPLATE



SUBSTATION CONDITION

FEEDER PILLAR



FEEDER PILLAR NAMEPLATE



EFI



SF6 INDICATOR



TRANSFORMER OIL LEVEL INDICATOR



VISUAL DEFECT

SUBSTATION



CPR POSTER OLD VERSION – SWG BAY

EFI



NO FEEDER LABEL – CRB00331 - TAMAN SHAHBANDAR

LIGHTING



NOT OPERATED – SWG BAY

FP/LVDB



NO FEEDER NO./FEEDER NAME – FP TX1 - NOT FOLLOW NEW STANDARD

CABLE PILC



CABLE PILC SWG – CRB00329 - SUNGAI LUI

CABLE PILC



CABLE PILC SWG – CRB00331 - TAMAN SHAHBANDAR

VISUAL DEFECT

CABLE PILC



FP TX1 / OUTGOING F2

CABLE PILC



FP TX1 / OUTGOING F4

NORMAL/DEFECT STICKER

NORMAL STICKER

Company/Team: _____

CONDITION ASSESSMENT

**DIAGNOSTIC UNIT SUBSTATION**

Cycle/Year : 1/2026

Testing Date : 06-03-2026

Defect : IR

Company/Team: EET ENGINEERING

TEV

UVS

IR

DEFECT STICKER PANEL CRB00330

DEFECT NOTIFICATION

**DIAGNOSTIC UNIT SUBSTATION**

Panel / TX No. : CRB00330 - Testing Date : 06-03-2026

Compartment : CABLE SWG Load (A) : -

Thermo: 1.0 °C

Abs. T 1.0 °C

Remarks: CABLE TERMINATION

Repair Date : _____ Repair By: _____

Rescan: OK ☐ NOT OK ☐ Company/Team: EET

Rescan Date : _____

TEV

UVS

IR

DEFECT STICKER FP TX1

DEFECT NOTIFICATION

**DIAGNOSTIC UNIT SUBSTATION**

Panel / TX No. : FP TX1

Testing Date : 06-03-2026

Defect 1 (S1/Abn.T): SWG

Location: 014 SW

Defect 2 (S1/Abn.T): _____

Location: _____

Defect 3 (S1/Abn.T): _____

Location: _____

Defect 4 (S1/Abn.T): _____

Location: _____

Defect 5 (S1/Abn.T): _____

Location: _____

Defect 6 (S1/Abn.T): _____

Location: _____

Defect 7 (S1/Abn.T): _____

Location: _____

Defect 8 (S1/Abn.T): _____

Location: _____

Company/Team: EET

(184)

AIR

STATE / AREA		PAVING / RAUB		DATE		FUNCTIONAL LOCATION					
PE NAME		JPS		TIME IN / OUT		10:33 AM / 10:54 AM					
V.I REF. NO				TEV BACK GROUND / HUMIDITY		71					
DETAIL				SWITCHGEAR							
NO.	FDR. NO	FEEDER NAME	STATUS (TRIP / CLOSE)	LOAD (A)	CABLE TYPE/SIZE	HEATER (A)	SERIAL NO (ONLY BREAKER & OLIV)				
1	CRB 00329	SUNGAI LUI	TRIP / CLOSE		XLPE / PILC N/A NACC						
2	CRB 00330	ALATUBAH	TRIP / CLOSE		XLPE / PILC N/A NACC						
3	CRB 00331	TAMAN SHAHBANDAR	TRIP / CLOSE		XLPE / PILC N/A NACC						
4			TRIP / CLOSE		XLPE / PILC N/A NACC						
OVERVIEW				TEMPERATURE							
COMP	Tmin (°C)	Tmax (°C)	ΔT	Avg (°C)	FILE	REMARKS	ULTRASOUND				
CABLE	32.4	32.8	0.4	32.7	156		-6				
BREAKER											
TOP PANEL											
PT											
CABLE	32.6	30.1	3.5	32.5	160	CABLE TERMINATION	-6				
BREAKER											
TOP PANEL											
PT											
CABLE	34.5	35.0	0.5	34.9	161	SOLAR LOADING	-6				
BREAKER											
TOP PANEL											
PT											
CABLE				31.7	153						
BREAKER											
TOP PANEL											
PT											
LOCAL TRANSFORMER				DETAILS							
TX ID	SERIAL NO	CABLE TYPE/ SIZE	REMARK	COMP.	Tmin (°C)	Tmax (°C)	ΔT	Avg (°C)	FILE	dB	TYPE CHAR.
TX1	111272 / 5917	XLPE/PILC		HT CABLE	35.0	35.9	0.9	35.8	168	-6	
		XLPE/PILC		HT BUSHING	40.0	40.8	0.8	40.4	167	-6	
		XLPE/PILC		LV CABLE	35.0	35.2	0.2	35.1	166		
		XLPE/PILC	SOLAR LOADING	LV BUSHING	38.1	38.5	0.4	38.4	165		
		XLPE/PILC		BODY	37.6	45.0	7.4	41.3	163		
TX2		XLPE/PILC		HT CABLE							
		XLPE/PILC		HT BUSHING							
		XLPE/PILC		LV CABLE							
		XLPE/PILC		LV BUSHING							
		XLPE/PILC		BODY							
LV DISTRIBUTION BOARD / FEEDER PILLAR / OTHERS				DETAILS							
NO	LVDB / FP	DEFECTIVE FEEDER NAME	Tmin (°C)	Tmax (°C)	ΔT	FILE	Avg (°C)				
1	LVDB / FP 1	INC. 1									
		INC. 2									
		INC. 3									
2	LVDB / FP 2	INC. 1									
		INC. 2									
		INC. 3									
3	LVDB / FP 3	INC. 1									
		INC. 2									
		INC. 3									
4	LVDB / FP 4	INC. 1									
		INC. 2									
		INC. 3									
5	LVDB / FP 5	INC. 1									
		INC. 2									
		INC. 3									
6	LVDB / FP 6	INC. 1									
		INC. 2									
		INC. 3									
7	LVDB / FP 7	INC. 1									
		INC. 2									
		INC. 3									
8	LVDB / FP 8	INC. 1									
		INC. 2									
		INC. 3									
9	LVDB / FP 9	INC. 1									
		INC. 2									
		INC. 3									
10	LVDB / FP 10	INC. 1									
		INC. 2									
		INC. 3									
11	LVDB / FP 11	INC. 1									
		INC. 2									
		INC. 3									
12	LVDB / FP 12	INC. 1									
		INC. 2									
		INC. 3									
13	LVDB / FP 13	INC. 1									
		INC. 2									
		INC. 3									
14	LVDB / FP 14	INC. 1									
		INC. 2									
		INC. 3									
15	LVDB / FP 15	INC. 1									
		INC. 2									
		INC. 3									
16	LVDB / FP 16	INC. 1									
		INC. 2									
		INC. 3									
17	LVDB / FP 17	INC. 1									
		INC. 2									
		INC. 3									
18	LVDB / FP 18	INC. 1									
		INC. 2									
		INC. 3									
19	LVDB / FP 19	INC. 1									
		INC. 2									
		INC. 3									
20	LVDB / FP 20	INC. 1									
		INC. 2									
		INC. 3									
21	LVDB / FP 21	INC. 1									
		INC. 2									
		INC. 3									
22	LVDB / FP 22	INC. 1									
		INC. 2									
		INC. 3									
23	LVDB / FP 23	INC. 1									
		INC. 2									
		INC. 3									
24	LVDB / FP 24	INC. 1									
		INC. 2									
		INC. 3									
25	LVDB / FP 25	INC. 1									
		INC. 2									
		INC. 3									
26	LVDB / FP 26	INC. 1									
		INC. 2									
		INC. 3									
27	LVDB / FP 27	INC. 1									
		INC. 2									
		INC. 3									
28	LVDB / FP 28	INC. 1									
		INC. 2									
		INC. 3									
29	LVDB / FP 29	INC. 1									
		INC. 2									
		INC. 3									
30	LVDB / FP 30	INC. 1									
		INC. 2									
		INC. 3									
31	LVDB / FP 31	INC. 1									
		INC. 2									
		INC. 3									
32	LVDB / FP 32	INC. 1									
		INC. 2									
		INC. 3									
33	LVDB / FP 33	INC. 1									
		INC. 2									
		INC. 3									
34	LVDB / FP 34	INC. 1									
		INC. 2									
		INC. 3									
35	LVDB / FP 35	INC. 1									
		INC. 2									
		INC. 3									
36	LVDB / FP 36	INC. 1									
		INC. 2									
		INC. 3									
37	LVDB / FP 37	INC. 1									
		INC. 2									
		INC. 3									
38	LVDB / FP 38	INC. 1									
		INC. 2									
		INC. 3									
39	LVDB / FP 39	INC. 1									
		INC. 2									
		INC. 3									
40	LVDB / FP 40	INC. 1									
		INC. 2									
		INC. 3									
41	LVDB / FP 41	INC. 1									
		INC. 2									
		INC. 3									
42	LVDB / FP 42	INC. 1									
		INC. 2									
		INC. 3									
43	LVDB / FP 43	INC. 1									
		INC. 2									
		INC. 3									
44	LVDB / FP 44	INC. 1									
		INC. 2									
		INC. 3									
45	LVDB / FP 45	INC. 1									
		INC. 2									
		INC. 3									
46	LVDB / FP 46	INC. 1									
		INC. 2									
		INC. 3									
47	LVDB / FP 47	INC. 1									
		INC. 2									
		INC. 3									
48	LVDB / FP 48	INC. 1									
		INC. 2									
		INC. 3									
49	LVDB / FP 49	INC. 1									
		INC. 2									
		INC. 3									
50	LVDB / FP 50	INC. 1									
		INC. 2									
		INC. 3									
51	LVDB / FP 51	INC. 1									
		INC. 2									
		INC. 3									
52	LVDB / FP 52	INC. 1									
		INC. 2									
		INC. 3									
53	LVDB / FP 53	INC. 1									
		INC. 2									
		INC. 3									
54	LVDB / FP 54	INC. 1									
		INC. 2									
		INC. 3									
55	LVDB / FP 55	INC. 1									
		INC. 2									
		INC. 3									
56	LVDB / FP 56	INC. 1									
		INC. 2									
		INC. 3									
57	LVDB / FP 57	INC. 1									
		INC. 2									
		INC. 3									
58	LVDB / FP										

