



**CONDITION BASED ASSESSMENT
FULL SCANNING REPORT
SBUM DIAGNOSTIC PAHANG
TNB BAHAGIAN PEMBAHAGIAN PAHANG**

FUNCTIONAL LOCATION (ERMS)	:	CCHL/PCE/J00226
FUNCTIONAL LOCATION (SITE)	:	-
SUBSTATION NAME (ERMS)	:	GOLDEN HILL NO.1
SUBSTATION NAME (SITE)	:	GOLDEN HILLS NO.1
COORDINATE	:	4.488321, 101.373858
SUBSTATION TYPE	:	PCE
AREA	:	CAMERON HIGHLAND
STATE	:	PAHANG
PO	:	42225439
DATE	:	13 MAR 2026

SCANNED BY	
THERMOGRAPHY	: MUHAMMAD ADAM BIN SAFARUDDIN (2017MY34N004)

EQUIPMENT/TOOLS	
THERMOGRAPHY	: FLIR T640 (SN 55912229) (CALIBRATION DUE DATE: 26 DEC 2026)

PREPARED BY	
NAME OF CONTRACTOR	: EET ENGINEERING SERVICES SDN BHD
ADDRESS	: NO.38, JALAN SS19/1D,
	: 47500, SUBANG JAYA, SELANGOR.

SUBSTATION SIGNBOARD




EXECUTIVE SUMMARY

NO.	EQUIPMENT	DEFECT AREA	IR (Abs T/ Δ T)	DEFECT
1.	RMU SF6, SCHNEIDER	OVERVIEW	-	-
		OVERVIEW TOP	-	-
	PANEL CCH00834 TX2 1000kVA	CABLE COMPARTMENT	-	
	PANEL CCH00835 FEDERAL BUNGLO	CABLE COMPARTMENT	-	
	PANEL CCH00833 TX1 1000kVA	CABLE COMPARTMENT	-	
	PANEL CCH00832 BARRINGTON SQUARE	CABLE COMPARTMENT	-	
2.	TX1 - MTM 1000kVA	OVERVIEW	-	-
		OVERVIEW TOP	-	-
		HV BUSHING	-	
		HV CABLES	-	
		LV BUSHING	-	
		LV CABLES	-	
3.	TX2 – MTM 1000kVA	OVERVIEW	-	-
		OVERVIEW TOP	-	-
		HV BUSHING	-	
		HV CABLES	-	
		LV BUSHING	-	
		LV CABLES	-	
4.	FP TX1	OVERVIEW	-	-
5.	FP TX2	OVERVIEW	-	-

VISUAL DEFECT SUMMARY

NO.	EQUIPMENT	DEFECT DESCRIPTION	ADDITIONAL REMARKS
1	SIGNBOARD	NO FUNCTIONAL LOCATION	-

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	RMU SF6	Manufacturer	SCHNEIDER	Time: 12:38 PM
	Model	RM6	Rating	12kV	Humidity: 59%
	Area	OVERVIEW		Panel No.	-
Panel Name	-				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	-	Serial No.	SF-2012-W11-5-0030
Spot Temp. 2 (Sp2)	-	Heater (A)	-
Average Temp. (Ar1)	23.6 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	-	Cable Type	-
Load (A)	-		
Defect	-		

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	RMU SF6	Manufacturer	SCHNEIDER	Time: 12:38 PM
	Model	RM6	Rating	12kV	Humidity: 59%
	Area	OVERVIEW TOP			Panel No.
Panel Name		-			


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	-	Serial No.	SF-2012-W11-5-0030
Spot Temp. 2 (Sp2)	-	Heater (A)	-
Average Temp. (Ar1)	23.7 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	-	Cable Type	-
Load (A)	-		
Defect	-		

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	RMU SF6	Manufacturer	SCHNEIDER	Time: 12:38 PM
	Model	RM6	Rating	12kV	Humidity: 59%
	Area	CABLE COMPARTMENT		Panel No.	CCH00834
Panel Name		TX2 1000kVA			


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	23.5 °C	Serial No.	SF-2012-W11-5-0030
Spot Temp. 2 (Sp2)	23.5 °C	Heater (A)	-
Average Temp. (Ar1)	23.5 °C	CB Position	CLOSE
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	0.0 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	RMU SF6	Manufacturer	SCHNEIDER	Time: 12:38 PM
	Model	RM6	Rating	12kV	Humidity: 59%
	Area	CABLE COMPARTMENT		Panel No.	CCH00835
Panel Name		FEDERAL BUNGLO			



IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	23.6 °C	Serial No.	SF-2012-W11-5-0030
Spot Temp. 2 (Sp2)	23.5 °C	Heater (A)	-
Average Temp. (Ar1)	23.5 °C	CB Position	CLOSE
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	0.0 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	RMU SF6	Manufacturer	SCHNEIDER	Time: 12:38 PM
	Model	RM6	Rating	12kV	Humidity: 59%
	Area	CABLE COMPARTMENT		Panel No.	CCH00833
Panel Name	TX1 1000kVA				



IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	23.4 °C	Serial No.	SF-2012-W11-5-0030
Spot Temp. 2 (Sp2)	23.5 °C	Heater (A)	-
Average Temp. (Ar1)	23.4 °C	CB Position	CLOSE
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	0.0 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	RMU SF6	Manufacturer	SCHNEIDER	Time: 12:38 PM
	Model	RM6	Rating	12kV	Humidity: 59%
	Area	CABLE COMPARTMENT		Panel No.	CCH00832
Panel Name	BARRINGTON SQUARE				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	23.4 °C	Serial No.	SF-2012-W11-5-0030
Spot Temp. 2 (Sp2)	23.5 °C	Heater (A)	-
Average Temp. (Ar1)	23.4 °C	CB Position	CLOSE
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	0.0 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 12:38 PM
	Model	HERMETICALLY SEAL	Rating	1000kVA	Humidity: 59%
	Area	OVERVIEW		Tx No.	TX1
Location	-				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	36.2 °C	Serial No.	T1/140/2012/10416
Spot Temp. 2 (Sp2)	31.3 °C	Heater (A)	-
Average Temp. (Ar1)	32.4 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (ΔT)	4.9 °C	Cable Type	-
Load (A)	-		
Defect	-		

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 12:38 PM
	Model	HERMETICALLY SEAL	Rating	1000kVA	Humidity: 59%
	Area	OVERVIEW TOP		Tx No.	TX1
Location	-				



IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	34.6 °C	Serial No.	T1/140/2012/10416
Spot Temp. 2 (Sp2)	35.3 °C	Heater (A)	-
Average Temp. (Ar1)	33.1 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	0.7 °C	Cable Type	-
Load (A)	-		
Defect	-		

Analysis & Recommendations:


Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 12:38 PM
	Model	HERMETICALLY SEAL	Rating	1000kVA	Humidity: 59%
	Area	BUSHING		Tx No.	TX1
Location	HV SIDE				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	31.3 °C	Serial No.	T1/140/2012/10416
Spot Temp. 2 (Sp2)	31.4 °C	Heater (A)	-
Average Temp. (Ar1)	27.6 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (ΔT)	0.1 °C	Cable Type	XLPE
Load (A)	-		
Defect			
Analysis & Recommendations:			
Analysis: No Anomaly.			
Recommendation: -			

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 12:38 PM
	Model	HERMETICALLY SEAL	Rating	1000kVA	Humidity: 59%
	Area	CABLE		Tx No.	TX1
Location	HV SIDE				



IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	27.3 °C	Serial No.	T1/140/2012/10416
Spot Temp. 2 (Sp2)	27.5 °C	Heater (A)	-
Average Temp. (Ar1)	25.6 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	0.2 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 12:38 PM
	Model	HERMETICALLY SEAL	Rating	1000kVA	Humidity: 59%
	Area	BUSHING		Tx No.	TX1
Location	LV SIDE				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	29.7 °C	Serial No.	T1/140/2012/10416
Spot Temp. 2 (Sp2)	29.6 °C	Heater (A)	-
Average Temp. (Ar1)	28.9 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (ΔT)	0.0 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 12:38 PM
	Model	HERMETICALLY SEAL	Rating	1000kVA	Humidity: 59%
	Area	OVERVIEW		Tx No.	TX2
Location	-				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	36.7 °C	Serial No.	T2/16/15515
Spot Temp. 2 (Sp2)	31.5 °C	Heater (A)	-
Average Temp. (Ar1)	31.9 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	5.2 °C	Cable Type	-
Load (A)	-		
Defect	-		

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 12:38 PM
	Model	HERMETICALLY SEAL	Rating	1000kVA	Humidity: 59%
	Area	OVERVIEW TOP		Tx No.	TX2
Location	-				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	35.8 °C	Serial No.	T2/16/15515
Spot Temp. 2 (Sp2)	36.3 °C	Heater (A)	-
Average Temp. (Ar1)	33.9 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	0.5 °C	Cable Type	-
Load (A)	-		
Defect			

Analysis & Recommendations:



Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 12:38 PM
	Model	HERMETICALLY SEAL	Rating	1000kVA	Humidity: 59%
	Area	BUSHING		Tx No.	TX2
Location	HV SIDE				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	32.4 °C	Serial No.	T2/16/15515
Spot Temp. 2 (Sp2)	31.9 °C	Heater (A)	-
Average Temp. (Ar1)	28.2 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (ΔT)	0.5 °C	Cable Type	XLPE
Load (A)	-		
Defect			
Analysis & Recommendations:			
Analysis: No Anomaly.			
Recommendation: -			

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 12:38 PM
	Model	HERMETICALLY SEAL	Rating	1000kVA	Humidity: 59%
	Area	CABLE		Tx No.	TX2
Location	HV SIDE				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	26.8 °C	Serial No.	T2/16/15515
Spot Temp. 2 (Sp2)	27.0 °C	Heater (A)	-
Average Temp. (Ar1)	26.4 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	0.2 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.


Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 12:38 PM
	Model	HERMETICALLY SEAL	Rating	1000kVA	Humidity: 59%
	Area	BUSHING		Tx No.	TX2
Location	LV SIDE				

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	30.0 °C	Serial No.	T2/16/15515
Spot Temp. 2 (Sp2)	30.0 °C	Heater (A)	-
Average Temp. (Ar1)	29.8 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	0.0 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:	
Analysis: No Anomaly.	
Recommendation: -	

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	TRANSFORMER	Manufacturer	MTM	Time: 12:38 PM
	Model	HERMETICALLY SEAL	Rating	1000kVA	Humidity: 59%
	Area	CABLE		Tx No.	TX2
Location	LV SIDE				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	27.5 °C	Serial No.	T2/16/15515
Spot Temp. 2 (Sp2)	27.5 °C	Heater (A)	-
Average Temp. (Ar1)	26.9 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	0.1 °C	Cable Type	XLPE
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	FP TX1	Manufacturer	SSE	Time: 12:38 PM
	Model	DIN TYPE	Rating	1600A	Humidity: 59%
	Area	OVERVIEW			Feeder No.
Feeder Name	-				


IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	-	Serial No.	FP9709-2047
Spot Temp. 2 (Sp2)	-	Heater (A)	-
Average Temp. (Ar1)	26.0 °C	CB Position	-
Ambient Temp.	27.6 °C	Busbar Position	-
Delta T (Δ T)	-	Cable Type	-
Load (A)	-		
Defect			

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	GOLDEN HILL NO.1			Date: 13/03/2026
	Equipment	FP TX2	Manufacturer	SSE	Time: 12:38 PM
	Model	DIN TYPE	Rating	1600A	Humidity: 59%
	Area	OVERVIEW			Feeder No.
Feeder Name	-				

IR IMAGE	VISUAL IMAGE																												
																													
<table> <tr> <th>PARAMETER</th><th>VALUE</th></tr> <tr> <td>Spot Temp.1 (Sp1)</td><td>-</td></tr> <tr> <td>Spot Temp. 2 (Sp2)</td><td>-</td></tr> <tr> <td>Average Temp. (Ar1)</td><td>27.2 °C</td></tr> <tr> <td>Ambient Temp.</td><td>27.6 °C</td></tr> <tr> <td>Delta T (Δ T)</td><td>-</td></tr> <tr> <td>Load (A)</td><td>-</td></tr> <tr> <td>Defect</td><td></td></tr> </table>	PARAMETER	VALUE	Spot Temp.1 (Sp1)	-	Spot Temp. 2 (Sp2)	-	Average Temp. (Ar1)	27.2 °C	Ambient Temp.	27.6 °C	Delta T (Δ T)	-	Load (A)	-	Defect		<table> <tr> <th>PARAMETER</th><th>VALUE</th></tr> <tr> <td>Serial No.</td><td>FP9801-2665</td></tr> <tr> <td>Heater (A)</td><td>-</td></tr> <tr> <td>CB Position</td><td>-</td></tr> <tr> <td>Busbar Position</td><td>-</td></tr> <tr> <td>Cable Type</td><td>-</td></tr> </table>	PARAMETER	VALUE	Serial No.	FP9801-2665	Heater (A)	-	CB Position	-	Busbar Position	-	Cable Type	-
PARAMETER	VALUE																												
Spot Temp.1 (Sp1)	-																												
Spot Temp. 2 (Sp2)	-																												
Average Temp. (Ar1)	27.2 °C																												
Ambient Temp.	27.6 °C																												
Delta T (Δ T)	-																												
Load (A)	-																												
Defect																													
PARAMETER	VALUE																												
Serial No.	FP9801-2665																												
Heater (A)	-																												
CB Position	-																												
Busbar Position	-																												
Cable Type	-																												

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

SUBSTATION CONDITION

SUBSTATION OVERVIEW




SIGNBOARD



SWITCHGEAR




SWITCHGEAR NAMEPLATE



TRANSFORMER 1



TRANSFORMER 1 NAMEPLATE




SUBSTATION CONDITION

TRANSFORMER 2




TRANSFORMER 2 NAMEPLATE



FEEDER PILLAR TX1




FEEDER PILLAR TX1 NAMEPLATE



FEEDER PILLAR TX2



FEEDER PILLAR TX2 NAMEPLATE




SUBSTATION CONDITION

EFI



SF6 INDICATOR



**FIRE EXTINGUISHER
(SWITCHGEAR ROOM)**



FIRE EXTINGUISHER EXPIRY DATE



**FIRE EXTINGUISHER
(TX1 ROOM)**



FIRE EXTINGUISHER EXPIRY DATE




SUBSTATION CONDITION


**FIRE EXTINGUISHER
(TX2 ROOM)**



FIRE EXTINGUISHER EXPIRY DATE



TRANSFORMER 1 OIL LEVEL INDICATOR



TRANSFORMER 2 OIL LEVEL INDICATOR



VISUAL DEFECT



NO FUNCTIONAL LOCATION

NORMAL/DEFECT STICKER

NORMAL STICKER	
CONDITION ASSESSMENT PTNAGA NASIONAL <i>Better Together</i> DIAGNOSTIC UNIT SUBSTATION 	
Cycle/Year :	1 / 2026
Testing Date :	13-03-2026
Defect :	-
Company/Team :	EET ENGINEERING
	TEV U/S IR

255

STATE / AREA:		PAVING / CAMERON		DISTRIBUTION SUBSTATION (PCE) CMA TEST SHEET										DATE		13/3/2026		FUNCTIONAL LOCATION:		CCHL/PCE/500226						
PE NAME:		GOLDEN HILL NO-1												TIME IN / OUT		12:38 P.M. / 1:02 P.M.										
V.J REF. NO														TEV BACK GROUND / HUMIDITY		0 / 1		59		BACKGROUND TEMP: 27.6						
SWITCHGEAR																										
DETAIL										TEMPERATURE					ULTRASOUND			TEV		REMARK						
NO.	FDR. NO	FEEDER NAME	STATUS (TRIP / CLOSE)	LOAD (A)	CABLE TYPE/SIZE	HEATER (A)	SERIAL NO (ONLY BREAKER & OLU)	COMP	Tmin (°C)	Tmax (°C)	AT	Avg (°C)	FILE	REMARKS	dB	FILE	TYPE CHAR.	dB	PULSE / CYCLE	TYPE CHAR.						
1	CCH 00834	Tx2 1000kVA	TRIP / CLOSE		XLPE/PILC N/A NACC			CABLE BREAKER TOP PANEL PT	23.5	23.6	0.1	23.5	276		-6	-	-	4	0	-						
2	CCH 00835	FEDERAL BUNGLO	TRIP / CLOSE		XLPE/PILC N/A NACC			CABLE BREAKER TOP PANEL PT	23.4	23.5	0.1	23.4	277		-6	-	-	3	0	-						
3	CCH 00833	Tx1 1000kVA	TRIP / CLOSE		XLPE/PILC N/A NACC			CABLE BREAKER TOP PANEL PT	23.3	23.4	0.1	23.3	278		-6	-	-	4	0	-						
4	CCH 00832	BARRINGTON SQUARE	TRIP / CLOSE		XLPE/PILC N/A NACC			CABLE BREAKER TOP PANEL PT	23.3	23.4	0.1	23.3	280		-6	-	-	3	0	-						
OVERVIEW										LOCAL TRANSFORMER																
DETAILS										THERMOGRAPHY					ULTRASOUND											
TX ID	SERIAL NO	CABLE TYPE/SIZE	REMARK	COMP.	Tmin (°C)	Tmax (°C)	AT	Avg (°C)	FILE	dB	TYPE CHAR.	TX ID	SERIAL NO	CABLE TYPE/SIZE	COMP.	Tmin (°C)	Tmax (°C)	AT	FILE	Avg (°C)	FILE	dB	TYPE CHAR.	REMARKS		
TX1	T1/140/2012/10416	XLPE/PILC		HT CABLE	27.7	28.0	0.3	27.9	292	-6	-	TX3		XLPE/PILC	HT CABLE											
				HT BUSHING	32.1	32.3	0.2	32.2	291	-6	-				HT BUSHING											
				LV CABLE	27.7	28.1	0.4	27.9	290	-6	-				LV CABLE											
				LV BUSHING	30.1	30.7	0.6	30.5	289	-6	-				LV BUSHING											
TX2	T1/16/15515	XLPE/PILC		HT CABLE	29.0	29.3	0.3	29.2	290	-6	-	TX4		XLPE/PILC	HT CABLE											
				HT BUSHING	32.7	33.1	0.4	32.9	298	-6	-				HT BUSHING											
				LV CABLE	26.9	27.1	0.2	27.0	297	-6	-				LV CABLE											
				LV BUSHING	24.1	24.4	0.3	24.3	296	-6	-				LV BUSHING											
				BODY	30.4	36.4	6.0	33.4	288	-6	-				BODY											
				HT CABLE	29.0	29.3	0.3	29.2	290	-6	-				HT CABLE											
				HT BUSHING	32.7	33.1	0.4	32.9	298	-6	-				HT BUSHING											
				LV CABLE	26.9	27.1	0.2	27.0	297	-6	-				LV CABLE											
				LV BUSHING	24.1	24.4	0.3	24.3	296	-6	-				LV BUSHING											
				BODY	30.6	36.8	6.2	33.7	295	-6	-				BODY											
LV DISTRIBUTION BOARD/FEEDER PILLAR/OTHERS																										
INC. 1										INC. 2										INC. 3						
CABLE TYPE / SIZE										CABLE TYPE / SIZE										CABLE TYPE / SIZE						
LVDB / F1										LVDB / F2										LVDB / F3						
CABLE TYPE / SIZE										CABLE TYPE / SIZE										CABLE TYPE / SIZE						
NO	LVDB / F1	DEFECTIVE FEEDER NAME	Tmin (°C)	Tmax (°C)	AT	FILE	Avg (°C)	REMARK	NO	LVDB / F2	DEFECTIVE FEEDER NAME	Tmin (°C)	Tmax (°C)	AT	FILE	Avg (°C)	REMARK	NO	LVDB / F3	DEFECTIVE FEEDER NAME	Tmin (°C)	Tmax (°C)	AT	FILE	Avg (°C)	REMARK
	INC 1									INC 2									INC 3							
	F1									F2									F3							
	F2									F3									F4							
	F3									F4									F5							
	F4									F5									F6							
	F5									F6									F7							
	F6									F7									F8							
	F7									F8									F9							
	F8									F9									F10							
Battery Bank Black Box 1 Black Box 2 Lightning Arrestor Dropped Fuse Auto Recloser LBS																										

MOHD AZZAD BIN OTHMAN (10085234)
 JURUTEKNIK TINGKATAN BIA
 (DIAGNOSTIC SUBSTATION PA...
 SBU MAINTENANCE EAST
 DISTRIBUTION NETWORK DIVISION, TND

Tested by (Name & Signature): Tel: 603-5636 6205 Fax: 603-5636 7205

TND Supervisor/Engineer (Name & Signature):

255

Sb(N-FIL)

VISUAL INSPECTION CHECKLIST FOR 11kV SUBSTATION



DATE: 13/3/2026
P/E Name (ERMS): GOLDEN HILL NO.1
P/E Name (SITE): GOLDEN HILLS NO.1
GPS Coordinate: 4-488321, 101-373858
PCE Type: INDOOR ☒ OUTDOOR ☐ COMPACT ☐ ATTACH BUILDING ☐ PAT ☐
PCE Area: NORMAL ☒ INDUSTRIAL ☐ COASTAL ☐
Switchgear Type 1: RMU OIL ☐ RMU SF6 ☒ MRMU ☐ VCB ☐ OCB ☐
Manufacturer/Model: SCHNEIDER / RM6
Switchgear Manufactured Date: 2012 Switchgear Rating: 12 kV RMU SF6 / OIL S/N: SF-2012-W11-5-0030
Switchgear Type 2: RMU OIL ☐ RMU SF6 ☐ MRMU ☐ VCB ☐ OCB ☐
Manufacturer/Model: Switchgear Rating: RMU SF6 / OIL S/N:
Switchgear Manufactured Date: No. of Transformer: 2
Tx 1: Type HS KVA 1000 Construction Yr: 2012 Manufacturer: MTM S/N: T1/140/2012/10416
Tx 2: Type HS KVA 1000 Construction Yr: 2016 Manufacturer: MTM S/N: T2/16/15515
Tx 3: Type KVA Construction Yr: Manufacturer: S/N:
Tx 4: Type KVA Construction Yr: Manufacturer: S/N:

KEJANGGALAN

- 1. Signboard:
- 2. Earth connection:
- 3. EFI Functioning:
- 4. Heater Functioning:
- 5. Labelling @ Switchgear:
- 6. Labelling @ LVDB:
- 7. Gas Pressure:
- 8. Tx Guard:
- 9. Tx Oil Level (conservator tank):
- 10. Tx Oil Leak:
- 11. Tx Bushing:
- 12. Top Demand Indicator (@LVDB):
- 13. Link/fuse Holder:
- 14. LV Termination:
- 15. Rubber Mat:
- 16. Trenching:
- 17. Battery Voltage:
- 18. Lighting:
- 19. Roof Condition:
- 20. Fire Fighting
- 21. Fence/door condition:
- 22. Cleanliness/Bushes:
- 23. Vandalisme
- 24. Other Findings

YES	-	NO	-
Good	☒	Not Good	☐
Good	☒	Not Good	☐
Good	☐	Not Good	☐
Good	☒	Not Good	☐
Good	☒	Not Good	☐
Good	☒	Not Good	☐
YES	☒	NO	☐
Good	☐	Not Good	☐
YES	☐	NO	☒
Good	☒	Not Good	☐
Good	☒	Not Good	☐
Good	☒	Not Good	☐
Good	☒	Not Good	☐
YES	☒	NO	☐
Good	☐	Not Good	☐
Good	☐	Not Good	☐
Good	☒	Not Good	☐
Good	☒	Not Good	☐
Valid	☒	Expired	☐
Good	☒	Not Good	☐
Good	☒	Not Good	☐
YES	☐	NO	☒

Remarks	NO FIL
Remarks	
Remarks	
Remarks	N/A
Remarks	
Remarks	
Remarks	
Remarks	
Remarks	N/A
Remarks	N/A
Remarks	
Remarks	
Remarks	
Remarks	
Remarks	Expiry Date: 18/9/2026 No. of missing portable: -
Remarks	
Remarks	
Remarks	

TESTED BY (NAME & SIGNATURE):

EET ENGINEERING SERVICES SDN BHL
(584556-W)
No. 38-2, 2nd Floor, Jalan SS 13/1D
47500 Subang Jaya, Selangor.
Tel: 603-5636 6205 Fax: 603-5636 7205

TNB SUPERVISOR/ ENGINEER (NAME & SIGNATURE):

MOHD AZZAD BIN OTHMAN (100K1230)
JURUTEKNIK TINGKATAN 4
(DIAGNOSTIC SUBSTATION) - (M) - (R)
SBU MAINTENANCE EAST
DISTRIBUTION NETWORK DIVISION, TNB