ECE 360 Prelab 1

Jacob KLOEPPER / V00940755

26 September 2024

Question 4.2.1

Noting motor parameters from Appendix 1, and with constant current equaling zero, we can simplify equation (2) from the manual and solve for ω_{max} :

$$u_m(t) = R_m i_m(t) + L_m \dot{i}_m(t) + u_e(t)$$

$$u_{max} = k_m \omega_{max}$$

$$\omega_{max} = \frac{u_{max}}{k_m}$$

$$= \frac{15 \text{ V}}{0.0502 \text{ Nm/A}}$$

$$= 298.8 \text{ s}^{-1}$$

Question 4.2.2

With zero rotation, we simplify (2):

$$u_{max} = R_m i_{max}$$
$$i_{max} = \frac{u_{max}}{R_m}$$
$$= \frac{15 \text{ V}}{10.6 \Omega}$$
$$= 1.42 \text{ A}$$

Question 4.2.3

With input constant voltage and measured constant current, we simplify (2):

$$R_m = \frac{u_m}{i_m}$$

Question 4.2.4

With constant current, we simplify (2):

$$k_m = \frac{u_m - R_m i_m}{\omega_m}$$

Question 4.3.1

From the LT of (5), we find

$$sJ_{eq}\Omega_m(s) = k_m I_m(s)$$

$$I_m(s) = \frac{sJ_{eq}\Omega_m(s)}{k_m}$$

Then, we solve for the transfer function:

$$G(s) = \frac{\Omega_m(s)}{R_m I_m(s) + s L_m I_m(s) + k_m \Omega_m(s)}$$

$$= \frac{\Omega_m(s)}{R_m \left(\frac{s J_{eq} \Omega_m(s)}{k_m}\right) + s L_m \left(\frac{s J_{eq} \Omega_m(s)}{k_m}\right) + k_m \Omega_m(s)}$$

$$= \frac{\Omega(s)}{\Omega(s) \left(\left(\frac{L_m J_{eq}}{k_m}\right) s^2 + \left(\frac{R_m J_{eq}}{k_m}\right) s + k_m\right)}$$

$$= \frac{1}{\left(\frac{L_m J_{eq}}{k_m}\right) s^2 + \left(\frac{R_m J_{eq}}{k_m}\right) s + k_m}$$

Question 4.3.2

Considering L_m to be much smaller than R_m , we approximate:

$$G(s) \approx \frac{1}{\left(\frac{R_m J_{eq}}{k_m}\right) s + k_m}$$

Question 4.3.3

Rearranging the equation from the previous question, we obtain

$$G(s) \approx \frac{\frac{k_m}{R_m J_{eq}}}{s + \frac{k_m^2}{R_m J_{eq}}}$$
$$\approx \frac{214.30}{s + 10.76}$$

Question 4.3.4

Rearranging the previous equation in a different way, we obtain

$$G(s) \approx \frac{\frac{1}{k_m}}{\left(\frac{R_m J_{eq}}{k_m^2}\right) s + 1}$$
$$\approx \frac{19.92}{0.093s + 1}$$

Question 4.3.5

From the LT of (2), assuming $u_m(t) = 0$ and $L_m = 0$, we obtain

$$0 = R_m I_m(s) + k_m \Omega_m(s)$$
$$I_m(s) = \frac{-k_m \Omega_m(s)}{R_m}$$

Then, from the LT of (5), we obtain $T_d(s)$:

$$sJ_{eq}\Omega_m(s) = k_m I_m(s) + T_d(s)$$
$$T_d(s) = sJ_{eq}\Omega_m(s) - k_m I_m(s)$$

Combining, we obtain the disturbance transfer function:

$$G_d(s) = \frac{\Omega_m(s)}{sJ_{eq}\Omega_m(s) + \frac{k_m^2\Omega_m(s)}{R_m}}$$
$$= \frac{1}{sJ_{eq} + \frac{k_m^2}{R_m}}$$

Question 4.3.6

Noting that $G(s) = \frac{k_m}{R_m} G_d(s)$, the block diagram is shown in figure 1.