NOTES:
1. ALL HEPACART SUPPLIED LINE VOLTAGE WIRE SHALL BE MINIMUM 16 GAUGE UNLESS OTHERWISE SPECIFIED.
2. LOW VOLTAGE WIRE SHALL BE MINIMUM 22 GAUGE.





R1 10K PINS

HEPACART
www.hepacart.com
INFECTION CONTROL TECHNOLOGIES

UNLESS OTHERWISE SPECIFIED DIMMENSIONS ARE IN INCHES DIMMENSIONS IN []'S ARE MM TOLERANCE ON DIMMENSIONS:

IN	MM
X.X: ± 0.060	X.X: ± 1.5
X.XX: ± 0.030	X.XX: ± 0.75
X.XXX: ± 0.010	X.XXX: ± 0.25

FRACTIONAL: ± 1/16 ANGLE: ± 1°

PROPRIETARY AND CONFIDENTIAL THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF HEPACART INC. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF HEPACART INC IS PROHIBITED.

INTERPRET GEOMETRIC TOLERANCING PER: ASME Y14.5

MATERIAL N/A

FINISH N/A

USED ON: HFAIR1100

DESCRIPTION: NEGATIVE AIR MACHINE WIRING DIAGRAM - 120V

	NAME	DATE
DRAWN	MMOSS	1/28/2019
CHECKED		
ENG APPR.		
MFG APPR.		
Q.A.		

DO NOT SCALE DRAWING

TITLE: WIRING DIAGRAM

SIZE B | DWG. NO. 80501-601 | REV

SCALE: 1:1 | WEIGHT: | SHEET 1 OF 1