

ESCON Setup

«Release Notes»

Edition September 2012

SYSTEM REQUIREMENTS

Minimum System Requirements	
Operating System	Windows 7, Windows XP SP3
Processor	Core2Duo 1.5 GHz
Drive	Hard disk drive, 1 GB available space
Port	USB 2.0
Memory	1 GB RAM
Monitor	Screen resolution 1024 x 600 pixels
Web Browser	Microsoft Internet Explorer 8

VERSION HISTORY

Edition 3.0 (2012-09)		
Features	ESCON Studio 1.2	- Supports new servo controller ESCON 36/3 EC - Supports additional languages: Japanese (ja), Chinese (zh) - Release of wizard «Diagnostic» - Release of tool «Data Recording»
Changes	ESCON 36/2 DC ESCON 50/5	- Upgrade of ESCON Firmware 0x0120 - Revision of documents: – Firmware Version Readme (September 2012) – Feature Comparison Chart (September 2012) – Hardware Reference (September 2012)
Features	ESCON 36/3 EC	- Upgrade of ESCON Firmware 0x0120 - Revision of documents: – Firmware Version Readme (September 2012) – Feature Comparison Chart (September 2012) – Hardware Reference (September 2012)

Edition 2.0 (2012-04)		
Features	ESCON Studio 1.1	• Supports new servo controller ESCON 50/5 • Supports additional languages: Italian (it), Spanish (es) • Release of Wiring Overview in «Startup Wizard» • Release of «Controller Monitor», Overview and Properties
Changes	ESCON 36/2 DC	• Upgrade of ESCON Firmware 0x0110 • Revision of documents: – Firmware Version Readme (March 2012) – Feature Comparison Chart (March 2012) – Hardware Reference (March 2012)
Features	ESCON 50/5	• Upgrade of ESCON Firmware 0x0110 • Revision of documents: – Firmware Version Readme (March 2012) – Feature Comparison Chart (March 2012) – Hardware Reference (March 2012)

Edition 1.1 (2011-11)		
Changes	ESCON Studio 1.0, Rev 2	«Controller Monitor» does no longer crash while clicking graphical control elements.

Edition 1 (2011-10)		
Features	New	Initial release
Changes	–	–

BRAND NAMES AND TRADEMARK OWNERS

- Core2Duo™; © Intel Corporation, USA-Santa Clara, CA
- Windows®, Internet Explorer®; © Microsoft Corporation, USA-Redmond, WA