

1. Penanganan terhadap temuan di audit GG safety atau plant accident prevention berjalan sesuai rencana.




ъ.

plant accident safety,

2. Tidak hanya melakukan penanganan terhadap temuan di audit GG safety atau plant accident prevention, tapi juga merencanakan sampai ke penerapan yang lain (yoko tenkai).




WIN-I Yokoten





3. Secara berkala (min 1x/thn) mengecek kondisi konsistensi penanganan hardware & software pada temuan GG safety, kecelakaan sebelumnya, termasuk hiyari serius, dan ada catatannya.



	The state of the s													A CANADA CONTRACTOR OF THE PROPERTY OF THE PRO							
	20)22	20)23	Jur	1-24	Jul	-24	Au	g-24	Sep	p-24	Oct	-24	Nov	v-24					
Finish date	OK/NG	Check date	OK/NG	Check date	OK/NG	Check date	OK/NG	Check date	OK/NG	Check date	OK/NG	Check date	OK/NG	Check date	OK/NG	Check date					
Jul-18	ОК	09 Juni 22	ок	19-Sep-23	ок	14 Juni 24															

Back

ъ.

(min 1x/thn) mengecek kondisi konsistensi penanganan hardware & software pada temuan GG safety, kecelakaan accident sebelumnya, termasuk y hiyari serius, dan ada catatannya.

3. Secara berkala

Safety check sheet for continuous action Category : New Machine V12

No					Problem			Δ	tion			Pric	odica	l che	ck af	ter a	ctio	n (si	x mo	onth)		Dec-26
		Date		1	Problem	risides			Jun-24		Dec-24		Jan-25		Jul-25		Des 25		6	Dec-26			
		Title State	Area/Machine	Position	Detail	Photo	Catagory	Detail	Photo	окума	Once date	ON/NG	Chock door	OKING	Check date	OK/NG	Check date	CK/MG	Disch dere	ow/wg o	beck date	оклис	Osek da
1	24-	Jun-22	V12	Take up machine	The emergicy stop switch must be located close to operator's position and easy to active		Getting wedget / caught	Make sure indication emergency stop		DK.	12-34+24												
2	24-	Jun-22	V12	ialine & drive capstan	Make sure safety devices are periodically checked		Getting wedget / caught	Install emergency stop	0	Oε	12-14-24												
3	24-	Jun-22	V12	lake up machine	Inertia rotation time must be indicated clearly on the machine having nertia rotation		Getting wedget / caught	Make indication still have inertia during push bottom Off	ÖO.	Oε	12-no-34												

2	Action			Priodical check after action (six month)														
(Jun-24		Dec-24		Jan-25		Jul-25		Des 25		Jul-26		Dec	c-21			
	Detail	Photo	OK/NG	Check date	OK/NG	Check date	OK/NG	Check date	OK/NG	Check date	OK/NG	Check date	OK/NG	Check date	OK/NG	Che		
-	Make sure indication emergency stop		ок	12-Jun-24														

2

accident plant

3. Secara berkala (min 1x/thn) mengecek kondisi konsistensi penanganan hardware & software pada temuan GG safety, kecelakaan sebelumnya, termasuk hiyari serius, dan ada catatannya.

Paste the Hiyari / Accident in actual Place













ъ.

3. Secara berkala (min 1x/thn) mengecek kondisi konsistensi penanganan hardware & software pada temuan GG safety, kecelakaan sebelumnya, termasuk hiyari serius, dan ada catatannya.









