ACTIVITY PLAN PROGRESS MONITORING

NO NO NO NO NO NO NO NO	oct	
Monitoring ECD KSI and Online alarm Monitor quality trend of Selected WR (WIN-M Method) D2-IDW-2-2 0.31 at H2B (collect blister mode) Collect data wire break (Reduce wire break due to WR Quality) Laid Coll 8.00mm Evaluation new supplier graphite carbon die (Toyo Tanso) Evaluation new UPCAST machine Reduce ECD count A00 Review drawing dies step 2.00 Reduce ECD count A00 Investigate detected position and check actual kizu Extend life time probe new ECD size 2.00 (compare with WIN-1) Laser Micro A03 Additional roller after dancer sheave Strengthen stand laser micro Compare blister HVCT and wire break at H52 Anneal (KSI) Reduce Wire break at 83 Reduce wire break at 83 Reduce wire break at 83 Additional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed DV Up A03 target 25%. On March 2022 has DV up 10% Collect data production Its Wefficiency drawing		nov
Monitor quality trend of Selected WR (WIN-M Method) D2-IDW-2-2 0.31 at H2B (collect blister mode) 4 Collect data wire break (Reduce wire break due to WR Quality) 5 Laid Coil 8.00mm 6 Evaluation new supplier graphite carbon die (Toyo Tanso) 7 Evaluation new UPCAST machine 8 Reduce ECD count A00 Install centering roller all capstan A00 Investigate detected position and check actual kizu Extend life time probe new ECD size 2.00 (compare with WIN-1) 9 Laser Micro A03 10 Additional roller after dancer sheave 11 Strengthen stand laser micro 12 Change 2.00 Anneal to 0.90 Anneal to 0.90 Anneal (KSI) Reduce wire break at B3 machine 13 Reduce wire break at B3 machine 14 DV Up A03 target 25%. On March 2022 has DV up 10% 15 Review drvs speed follow PE standard 16 IX efficiency drawing		
4 Collect data wire break (Reduce wire break due to WR Quality) 5 Laid Coil 8.00mm 6 Evaluation new supplier graphite carbon die (Toyo Tanso) 7 Evaluation new UPCAST machine 8 Reduce ECD count A00 Install centering roller all capstan A00 Investigate detected position and check actual kizu Extend life time probe new ECD size 2.00 (compare with WIN-1) 9 Laser Micro A03 Additional roller after dancer sheave 11 Strengthen stand laser micro 12 Change 2.00 Anneal to 0.90 Anneal (KSI) Reduce wire break at B3 machine Additional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed 15 Review drw speed follow PE standard Extending the first open of the production 16 Ix efficiency drawing		
Laid Coil 8.00mm Evaluation new supplier graphite carbon die (Toyo Tanso) Evaluation new UPCAST machine Size 2.60 (change dies 25% to 35%) dies size 4.700 and 4.100 Review drawing dies step 2.00 Install centering roller all capstan A00 Investigate detected position and check actual kizu Extend life time probe new ECD size 2.00 (compare with WIN-1) Laser Micro A03 Additional roller after dancer sheave Strengthen stand laser micro Change 2.00 Anneal to 0.90 Anneal K(SSI) Reduce wire break at B3 machine Reduce wire break at B3 machine Review draw speed follow PE standard Review draw speed follow PE standard Mass production		
Evaluation new supplier graphite carbon die (Toyo Tanso) Evaluation new UPCAST machine Size 2.60 (change dies 25% to 35%) dies size 4.700 and 4.100 Review drawing dies step 2.00 Install centering roller all capstan A00 Investigate detected position and check actual kizu Extend life time probe new ECD size 2.00 (compare with WIN-J) 9 Laser Micro A03 Additional roller after dancer sheave Strengthen stand laser micro Change 2.00 Anneal to 0.90 Anneal (KSI) Reduce wire break at B3 machine Reduce wire break at B3 machine To DV Up A03 target 25%. On March 2022 has DV up 10% Review drw speed follow PE standard Mass production Its efficiency drawing		
Feduce ECD count A00 Review drawing dies step 2.00 Reduce ECD count A00 Review drawing dies step 2.00 Install centering roller all capstan A00 Investigate detected position and check actual kizu Extend life time probe new ECD size 2.00 (compare with WIN-J) Laser Micro A03 Additional roller after dancer sheave Strengthen stand laser micro Change 2.00 Anneal to 0.90 Anneal (KSI) Reduce wire break at 83 machine Reduce wire break at 83 machine Review draw speed follow PE standard Mass production It efficiency drawing		
Size 2.60 (change dies 25% to 35%) dies size 4.700 and 4.100 Review drawing dies step 2.00 Province Pr		
Reduce ECD count A00 Reduce ECD count A00 Review drawing dies step 2.00 Install centering roller all capstan A00 Investigate detected position and check actual kizu Extend life time probe new ECD size 2.00 (compare with WIN-1) 9 Laser Micro A03 10 Additional roller after dancer sheave 11 Strengthen stand laser micro 12 Change 2.00 Anneal to 0.90 Anneal (KS1) Reduce wire break at B3 machine Reduce wire break at B3 machine 13 Review draw speed follow PE standard Collect data production 15 Review draw speed follow PE standard Collect data production Test to speed standard Mass production		
Reduce ECD count A00 Install centering roller all capstan A00 Investigate detected position and check actual kizu Extend life time probe new ECD size 2.00 (compare with WIN-J) 9 Laser Micro A03 10 Additional roller after dancer sheave 11 Strengthen stand laser micro 12 Change 2.00 Anneal to 0.90 Anneal (KSI) Additional bare wire supply B Line from KSI (0.90/1.00) Reduce wire break at B3 machine 14 DV Up A03 target 25%. On March 2022 has DV up 10% Review drw speed follow PE standard Collect data production Test to speed standard Mass production Install centering roller all capstan A00 Investigate detected position and check actual kizu Extend life time probe new ECD size 2.00 (compare with WIN-J) Compare blister HVCT and wire break at H52 Additional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed Collect data production Test to speed standard Mass production Test to speed standard Mass production		
Investigate detected position and check actual kizu Extend life time probe new ECD size 2.00 (compare with WIN-J) 9 Laser Micro A03 10 Additional roller after dancer sheave 11 Strengthen stand laser micro 12 Change 2.00 Anneal to 0.90 Compare blister HVCT and wire break at H52 Anneal (KSI) Reduce wire break at B3 machine Additional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed 14 DV Up A03 target 25%. On March 2022 has DV up 10% Review drw speed follow PE standard Collect data production Test to speed standard Mass production		
Extend life time probe new ECD size 2.00 (compare with WIN-1) 9 Laser Micro A03 10 Additional roller after dancer sheave 11 Strengthen stand laser micro 12 Change 2.00 Anneal to 0.90 Anneal to (SI) Reduce wire break at B3 Moltonal bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed 14 DV Up A03 target 25%. On March 2022 has DV up 10% Review drw speed follow PE standard Review drw speed follow PE standard Review drw speed follow PE Standard Additional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed Collect data production Test to speed standard Mass production		
9 Laser Micro A03 10 Additional roller after dancer sheave 11 Strengthen stand laser micro 12 Change 2.00 Anneal to 0.90 Anneal (KSI) Reduce wire break at B3 Moltional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed 14 DV Up A03 target 25%. On March 2022 has DV up 10% Review drw speed follow PE standard Test to speed standard Mass production 16 IK efficiency drawing		
10 Additional roller after dancer sheave 11 Strengthen stand laser micro 12 Change 2.00 Anneal to 0.90 Compare blister HVCT and wire break at H52 13 Reduce wire break at B3 machine 14 DV Up A03 target 25%. On March 2022 has DV up 10% Review drw speed follow PE standard 15 Review drw speed follow PE standard 16 IK efficiency drawing		
11 Strengthen stand laser micro 12 Change 2.00 Anneal to 0.90 Anneal (KSI) Reduce wire break at B3 machine Additional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed 14 DV Up A03 target 25%. On March 2022 has DV up 10% Review drw speed follow PE standard Review drw speed follow PE standard IK efficiency drawing Compare blister HVCT and wire break at H52 Additional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed Collect data production Test to speed standard Mass production		
12 Change 2.00 Anneal to 0.90 Anneal (KSI) Reduce wire break at B3 Machine Reduce wire break at B3 Adjust viscocity Rollcoater speed 14 DV Up A03 target 25%. On March 2022 has DV up 10% Review drw speed follow PE Standard Collect data production Test to speed standard Mass production 16 IK efficiency drawing Compare blister HVCT and wire break at H52 Additional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed Collect data production Test to speed standard Mass production		
Anneal (KSI) Reduce wire break at B3 machine Review drw speed follow PE standard Review drw speed follow PE standard IK efficiency drawing Additional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed Collect data production Test to speed standard Mass production		
Reduce wire break at B3 machine Additional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed 14 DV Up A03 target 25%. On March 2022 has DV up 10% Review drw speed follow PE standard Test to speed standard Mass production 16 IK efficiency drawing Additional bare wire supply B Line from KSI (0.90/1.00) Adjust viscocity Rollcoater speed Collect data production Test to speed standard Mass production Its to speed standard Mass production Test to speed standard Mass production		
13 machine Adjust viscocity Rollcoater speed 14 DV Up A03 target 25%. On March 2022 has DV up 10% 15 Review drw speed follow PE standard Collect data production Test to speed standard Mass production 16 IK efficiency drawing		
Rollcoater speed		1
Review drw speed follow PE standard Collect data production Test to speed standard Mass production 16 IK efficiency drawing		
15 Review drw speed follow PE standard Test to speed standard Mass production Test to speed standard Mass production		
standard Fest to speed standard Mass production Mass production		
Mass production Six efficiency drawing Six ef		
17 Make standard drawing machine (Standard spring, pressure dancer sheave, etc.)		
18 Combine A Line and B Line Test at B Line		
19 Dies Mapping Purchase new dies (priority dies)		
19 Dies Mapping Make set dies based on machine		
1 New M/C H4/H5		
2 Apply DV 80 alll type (remain AIW.PEW) H3		1
3 D2IDW4B DV UP 10%		
Make Drw Dies packet Size 0.25 & 0.26		
4 Problem dimension H1,H2 Monitoring dimension after install laser micro		
Install scale tension (T/U winding)		
Modification supply head varnish supply follow H2		
Modification inline lubricant shower H2 Follow H1		
5 Problem Blister & HVCT Alarm Add roller after Oven (improve wire touch outlet sheave Due to vibration at oven 2nd week jun DR		
Change Varnish Filter 50 ==>10 micron		
Add pass Middle coat IDW4B2 ,D2IDW-2-2 PRODUCT		

NOTE: DISCUSS/FOLLOW UP ACTIVITY EVERY MONDAY PE WEB

CEK DUE DATE



DECIDE ACTIVITY