Starting Manufacturing Quality Control Vision System...

Creating test images...

Created test images in folder 'qc_test_images'

Reference image loaded: qc_test_images\reference_good.jpg

Processing: test_with_scratch.jpg

Found 1 defects:

Defect #1: Surface Defect, Area: 516.0

Results saved to qc_results/test_with_scratch_20250512_232336.jpg

Defect Analysis: test_with_scratch.jpg





