

PEOS Self Test Report

- 1. Database Connection: Pass '
- 2. UI Load Test: Pass '
- 3. Belt Motor Check: Pass '
- 4. Kirana Barcode Scanner: Pass '
- 5. Projects Page Visible: Pass '
- 6. New Project Button: Pass '
- 7. Navigation Menu: Pass '

