<b>FR</b>	DEPARTMENT OF SCIENCE AND TECHNOLOGY  DOST Regional Office No. IX	DOCUMENT CODE	WI-QMR-06-02
	WOOK INCTOLICTIONS	REVISION NUMBER	1
	<b>WORK INSTRUCTIONS</b>	PAGE NUMBER	1 of 1
SECTION	PRODUCT REALIZATION	EFFECTIVITY DATE	01 July 2023
SUBJECT	How to Monitor the Availability of Equipment		

PERSON RESPONSIBLE: Maintenance Personnel

## STEPS:

- 1.0 Require equipment users to accomplish DOST IX-QMS F11, Equipment Monitoring Sheet.
- 2.0 Check for completeness of information. Compute the availability of equipment. Formula for the availability of equipment is:

 $Percentage \ Available = \frac{Total \ number \ of \ available \ days - Total \ number \ of \ unavailable \ days}{Total \ number \ of \ available \ days} \times 100$ 

3.0 Make Monthly Summary Report on the Availability of Equipment.

Prepared by:  Maintenance Officer	Approved by:
Mahre	Quality Management Personantative
Maintenance Officer	Quality Management Representative