

Maruti Suzuki Factory Safety Manual

Section 1: General Policy Statement and Safety Culture

Welcome to the Maruti Suzuki Factory Safety Management System (SMS) Manual. This document defines the organizational structures, responsibilities, policies, and procedures required to maintain a safe working environment across all assembly, stamping, painting, and tooling shops.

Rule 1.1: Leadership Commitment. Managers and assembly line supervisors must lead by example, adhering strictly to all safety codes and immediately addressing safety infractions. They are held directly accountable for safety audits, shift briefs, and PPE compliance in their zones.

Rule 1.2: Employee Empowerment. Every operator is fully authorized and expected to initiate a Line Stop procedure if they identify any unsafe condition or equipment failure. No operator will face disciplinary action for stopping a line in good faith due to safety concerns.

Rule 1.3: Continuous Improvement. All manufacturing plants conduct monthly safety reviews and update the SMS guidelines to align with global automotive standards. Employee feedback is highly encouraged to streamline safety protocols and minimize hazardous occurrences.

Rule 1.4: Visitor Access. Visitors must complete the Safety Orientation briefing and obtain temporary clearance badges before entering the shop floor. They must be accompanied by a host at all times.

Section 2: Speed Limit Regulations & Vehicle Safety

1. Speed Limit: The maximum speed limit inside the factory premises is 20 km/h. This limit applies to all forklifts, parts carriers, emergency units, and visitor vehicles. Speed limit signs are posted every 50 meters along the main assembly pathways. Violators face immediate suspension of plant access and disciplinary review.

Rule 2.1: Forklift Operations. Forklift operators must carry valid industrial licenses, sound their horns at all blind corners, and never carry loads that obstruct their forward vision. Forklifts must never exceed a walking pace (5 km/h) in heavily populated assembly line corridors.

Rule 2.2: Pedestrian Corridor Rights. Pedestrians have absolute right-of-way. All staff must walk strictly within the green-painted safety walkways and cross only at yellow zebra lanes. Do not step into active vehicular paths without checking mirrors.

Rule 2.3: Tow-Truck and AGV Coordination. Automated Guided Vehicles (AGVs) operate on fixed routes. Do not place parts, containers, or stand in the path of active AGVs or material transport trains. Manual override switches on AGVs should only be used during blockages or safety emergencies.

Rule 2.4: Parking and Loading Bays. Material trucks must park only inside designated loading zones. Wheels must be chocked when loading or unloading heavy container materials to prevent movement.

Section 3: Personal Protective Equipment (PPE) Gear

2. PPE Gear: All employees must wear high-visibility jackets and steel-toe safety shoes. Jackets must be worn properly zipped at all times on the manufacturing floor. High-visibility neon coloring ensures operators are clearly visible to vehicle drivers and crane operators.

Rule 3.1: Steel-Toe Safety Shoes. Steel-toe safety shoes are mandatory to protect against heavy dropped components. They must comply with industrial impact resistance standards.

Rule 3.2: Eye and Face Protection. Technicians operating in welding, stamping, and heavy machining areas must wear certified auto-darkening safety goggles or full face shields to prevent sparks, chips, or ultraviolet radiation from damaging eyesight.

Rule 3.3: Head Protection. Safety helmets must be worn in high crane loading areas, stacking zones, and whenever working under elevated structures or assembly lifts.

Rule 3.4: Ear and Hearing Conservation. Hearing protection (earplugs or earmuffs) is mandatory in stamping shops, engine testing bays, and spaces exceeding 85 decibels of continuous noise.

Rule 3.5: Hand Protection. Cut-resistant gloves must be worn when handling raw sheet metal, sharp stampings, or during maintenance of blade-related equipment.

Section 4: Daily Safety Audits and Supervision Protocols

3. Audits: Daily safety audit is mandatory for all assembly line supervisors. Supervisors must inspect assembly lines, machine guards, and emergency stop switches.

Rule 4.1: Pre-Shift Inspection Checklist. Supervisors must verify that emergency power stop buttons are functional, emergency exits are clear, and ventilation systems are operating. This physical check must be completed before any operator is allowed to start their shift.

Rule 4.2: Audit Timing. Audits must be completed and logged digitally in the factory safety portal by 8:00 AM daily, before the morning shift shift starts.

Rule 4.3: Infraction Resolution. Any safety violation or equipment issue identified during the audit must be resolved immediately. Work is not permitted to resume on the line until a safety officer clears the infraction.

Rule 4.4: Incident Reporting. Near-miss events and safety anomalies must be logged within 2 hours of occurrence. Detailed reports are reviewed weekly by the plant safety committee to adjust protocols.

Rule 4.5: Monthly Safety Audits. The safety team conducts deep-dive monthly reviews, analyzing incident logs, PPE wear metrics, and equipment maintenance status.

Section 5: Emergency Evacuation and Fire Safety Protocols

Rule 5.1: Alarm Sirens. In case of an emergency, alarm sirens will sound continuously across all plant bays. All personnel must immediately stop operations and power down their machinery.

Rule 5.2: Evacuation Assembly. Proceed calmly to the nearest assembly points marked outside the main gates. Do not run, panic, or attempt to retrieve personal belongings during an evacuation. Clear pathways must be maintained inside the plant bays at all times.

Rule 5.3: Supervisor Accountability. Line supervisors must take a roll call of their teams at the assembly points and report missing personnel to emergency coordinators immediately.

Rule 5.4: Fire Extinguisher Locations. Fire extinguishers and fire hoses are placed every 30 meters. Only trained fire safety wardens should operate extinguishers for active fires. Standard staff should focus on evacuation.

Rule 5.5: First Aid Stations. Fully equipped medical first aid rooms are located adjacent to the main security gates. Ambulances are stationed 24/7 for immediate medical transport.

Section 6: Tool Handling and Machine Guard Policies

Rule 6.1: Machine Cages. Machine guard locks and physical safety cages must never be bypassed or disabled during operation. Interlock sensors must remain fully active to cut off power in breaches.

Rule 6.2: Pressure Checks. All pneumatic and hydraulic hand tools must be checked daily for pressure seals, hose cracks, and connector stability before use. Defective tools must be tagged.

Rule 6.3: Heavy Presses. Only certified technicians are permitted to operate heavy pressing machinery. Dual-hand trigger controls must be used to ensure operators' hands are clear of the stamping zone.

Rule 6.4: Lock-Out Tag-Out (LOTO). Maintenance tasks require a strict LOTO procedure. All energy sources must be physically locked and tagged before servicing machines to prevent accidental starts.

Rule 6.5: Hazardous Material Disposal. All solvent rags, paint waste, and chemical drums must be disposed of in labeled fire-resistant containers inside ventilated storage zones.