
74-11-00

Engine Model(s): MODEL(S) PW150A

## Figure 1 Ignition Exciter Installation

Figure 1 Ignition Exciter Installation



c61660

	Fig. Item	Part No.	Airline Part No.	Nomenclature	Effect Code	Units Per Assy.
_	1			IGNITION EXCITER INSTALLATION SEE 72-00-00 FIG.1 FOR NHA		REF
	10	CH92043		• EXCITER, IGNITION FOR COMPLETE BREAKDOWN AND ADDITIONAL INFORMATION REFER TO CHAMPION AVIATION PRODUCTS COMPONENT MAINTENANCE MANUAL P/N 74-11-04 SUPPLIER CODE: 0AFL4 P&WC P/N: 3122413-05 (PRC 02): TWO-WAY INTRCHG WITH P/N CH92043-1 PRE-SB35052		1
_	10A	<u>CH92043-</u> <u>1</u>		• EXCITER, IGNITION FOR COMPLETE BREAKDOWN AND ADDITIONAL INFORMATION REFER TO CHAMPION AVIATION PRODUCTS COMPONENT MAINTENANCE MANUAL P/N 74-11-04 SUPPLIER CODE: 0AFL4 P&WC P/N: 3122413-06 (PRC 02): TWO-WAY INTRCHG WITH P/N CH92043-2 POST-SB35052 PRE-SB35104		1
_	10B	<u>CH92043-</u> <u>2</u>		• EXCITER, IGNITION FOR COMPLETE BREAKDOWN AND ADDITIONAL INFORMATION REFER TO CHAMPION AVIATION PRODUCTS COMPONENT MAINTENANCE MANUAL P/N 74-11-04 SUPPLIER CODE: 0AFL4 P&WC P/N: 3122413-07 (PRC 02): TWO-WAY INTRCHG WITH P/N CH92043-3 MAY BE OBTAINED BY REWORK OF P/N 3122413-06 POST-SB35104 PRE-SB35241		1
_	10C	<u>CH92043-</u> <u>3</u>		• EXCITER, IGNITION FOR COMPLETE BREAKDOWN AND ADDITIONAL INFORMATION REFER TO CHAMPION AVIATION PRODUCTS COMPONENT MAINTENANCE MANUAL P/N 74-11-04 SUPPLIER CODE: 0AFL4 P&WC P/N: 3122413-08 POST-SB35241		1
	20	MS9696-		ATTACHING PARTS		4

Export Classification: Outside US (EAR): Contains 1025% 9E991, US (EAR): NSR, Outside US (ITAR): NSR, US (ITAR): NSR, EIPA (ECL): NSR, DPA (CGD): NSR

Fig. Item	<b>Part No.</b> 08	Airline Part No.	Nomenclature  BOLT, MACHINE, DBL HEX *	Effect Code	Units Per Assy.
30	ST3413- 01		CABLE ASSY, GROUND, BRAIDED		1
40	ST3030- 09		ATTACHING PARTS  - NUT OPTION (IC) SEE NUT OPTION TABLE*		1

<sup>-</sup> ITEM NOT ILLUSTRATED