
73-11-00

Engine Model(s): MODEL(S) PW150A

Figure 5 Fuel Strainer Bypass Indicator Valve Installation

Figure 5 Fuel Strainer Bypass Indicator Valve Installation



c69592

	Fig. Item	Part No.	Airline Part No.	Nomenclature	Effect Code	Units Per Assy.
-	1			FUEL STRAINER BYPASS INDICATOR VALVE INSTALLATION SEE 72-00-00 FIG.1 FOR NHA		REF
	10	3049411- 01		VALVE ASSY, BYPASS, INDICATOR		1
	20	AS3209- 019		PACKING, PREFORMED (PRC 02): TWO-WAY INTRCHG WITH P/N ST6202-019 PRE-SB35178		1
_	20A	ST6202- 019		- PACKING, PREFORMED POST-SB35178		1
	30	M83461- 2-912		- PACKING, PREFORMED		1

[—] ITEM NOT ILLUSTRATED