Engine Model(s): PW150


72-11-00

Figure 4 Reduction Gearbox, Chip Detector Adapter & Strainer Installations


Figure 4 Reduction Gearbox, Chip Detector Adapter & Strainer Installations

(SHEET 1 OF 2)

Export Classification: ECCN=Contains 10-25% 9E991;ECL=NSR



## (SHEET 2 OF 2)



c61986

	Fig. Item	Part No.	Airline Part No.	Nomenclature	Effect Code	Units Per Assy.
_	1			REDUCTION GEARBOX, CHIP DETECTOR ADAPTER & STRAINER INSTALLATIONS SEE 72-02-00 FIG.2 FOR NHA		REF
	10	3122096- 01 (72-11- 83)		- ADAPTER, CHIP DETECTOR, MAGNETIC		1
	20	ST3030- 09		ATTACHING PARTS  • NUT OPTION (IC) SEE NUT OPTION TABLE		3
	30	MS9549- 09		• WASHER, FLAT		3
	40	AS3209- 138		• PACKING, PREFORMED		1
	50	3122228- 01 (72-11- 82)		• STRAINER ASSY, OIL		1
	60	3122095- 02 (72-11- 83)		ADAPTER, CHIP DETECTOR, MAGNETIC		1
	70	MS9490- 11		ATTACHING PARTS  • BOLT, MACHINE, HEX		2
	80	MS9549- 10		• WASHER, FLAT		2
	90	AS3209- 125		■ PACKING, PREFORMED		1
	100	3122231-		■ STRAINER ASSY, OIL		1

Fig. Item	Part No.	Airline Part No.	Nomenclature	Effect Code	Units Per Assy.
	01 (72-11- 82)				

<sup>—</sup> ITEM NOT ILLUSTRATED